## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Sente	70
Lessa No.	MO515	5

Unit T-26K, R-LIK

SUNDRY NOTICES AND REPORTS ON WELLS

	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY & SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	operate a castino com

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

				my cu	, 19
Well No. Randell. Collis locate	ed <b>990</b>	ft. from $\{$	and •••• ft. fro	om $\left\{\begin{matrix} E_{\bullet} \\ \bullet \end{matrix}\right\}$ line of s	sec. <u>10</u>
RE/4 Sec. 10	205	1116	Den		
(14 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	New Mercles	
(Field)	(	County or Subdivision)		(State or Territory)	

The elevation of the derrick floor above sea level is ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The test was spudded \$100 F.M., May 24, 1952, and 111' of 9-5/8" surface easing was set and coment circulated with 78 sacks. Sefere drilling the plug the easing was tested with \$00\$ and the plug was drilled and the coment jeb tested with \$00\$. There was no pressure drep in either teste.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.				
Company	Lucerne Corporation - Xilese Co			
Address	Mercantile Securities Building			
	Dallas	By Stanly		
	Total	Title		