

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Hartman
9. Well No. 1
10. Field and Pool, or Wildcat
12. County San Juan Co.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
Haynes & V.T. Drilling Company
Bedford Inc., Agent for & State of New Mexico

3. Address of Operator
P.O. Box E, Farmington, New Mexico 87401

4. Location of Well
UNIT LETTER C 990 FEET FROM THE N LINE AND 1650 FEET FROM
THE W LINE, SECTION 31 TOWNSHIP 29N RANGE 11W NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The Oil Conservation Division has employed Bedford, Inc., to plug and abandon this well as follows:

1. Tag cement top @ 1358', set plug from TD to 1350 if no plug is found.
2. Set cement plug 1250' to 1150'
3. Set cement plug from 450' to 350' inside & outside of 7" casing or in open hole if casing is pulled.
4. Set surface plug w/ P & A marker. Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry G. Bedford TITLE Agent for State DATE 8-31-78

APPROVED BY AR Kendrick TITLE SECRETARY DATE SEP 20 1978

CONDITIONS OF APPROVAL, IF ANY: