

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator <b>National Petroleum Co. # 1</b> 3. Address of Operator <b>Bloomfield Oilfield Service</b> <b>P. O. Box 1641 Bloomfield, N.M.</b> 4. Location of Well UNIT LETTER <b>D</b> FEET FROM THE LINE AND FEET FROM THE LINE, SECTION <b>22</b> TOWNSHIP <b>29 N</b> RANGE <b>11 W</b> NMPM. 15. Elevation (Show whether DF, RT, CR, etc.)	7. Unit Agreement Name 8. Farm or Lease Name <b>Unknown</b> 9. Well No. 10. Field and Pool, or Wildcat <b>Bloomfield-Farmington</b> 12. County <b>San Juan</b>
---	---

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-7-80 Move P & A, rig on location and rig up. Trip in hole with 3 7/8 bit, drill and clean out to 700', mix and spot 30 sks Class "A" cement 700' to 550' w.o.c. overnight, trip in hole with bit, tag cement @ 522' mix and spot 30 sks Class "A" cement + 2% cal. col. @ 180' w. o. c. 5 hrs could not tag cement @ 180', mix and spot 30 sks Class "A" cement + 2% cal. clo. @ 90' spot in overnight. Trip in with bit could not find cement @ 90', mix and spot 20 sks Class "A" cement + 4% cla clo. @ 90', cut 10" pipe off 3' below ground level, mix a pump 10 sks Class "A" cement in top of surface, weld on plate, level and clean up location, ready for inspection 8-11-80/



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. E. Bayler TITLE partner DATE 8-12-80

Original Signed by CHARLES GUNLSON

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE AUG 13 1980

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: