	San Juan	1 Pr. 15 V	The even labour distance that			
County		SEC.	_21т	29N_R.		
FIELD OR A	REA		LOCAT	10N_5681/1	[ <u>&amp; 301¹/E</u>	
LEASE	Reinhardt		WELL NO.	1		
COMPANY_	Noland & Wells	SPD.	6-23-39	_ COMPLETED	9-30-40	
ELEV.	5495	T. D.	7951	P. B		
	8 <sup>2</sup> 1 @ 921					
SHOT OR A	CID					
PERF						
-						
PRODUCIN	G FORM					
PRODUCTI	VE DEPTH OR INTERVAL					

REMARKS:

P&A 12-9-81

NORGY AND MINERALS DEPARTMENT	OIL CONSERVATION DIVISION P. O. BOX 2088	Form C-103 Revised 10-1-78
DISTRIBUTION	SANTA FE, NEW MEXICO 87501	
SANTA FE	SANTA PE, NEW MEXICO	Sa. Indicate Type of Lease
FILE		State Fee X
U.S.G.S.		5. State Oil 6 Gas Lease No.
LAND OFFICE	·	
DPERATOR		THITTINITY TO THE
	ATISES AND DEPOSTS ON WELLS	
SUNDRY N	OTICES AND REPORTS ON WELLS	
IDO NOT USE THIS FORM POLICATION FO	OF PLANT - (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL X WELL C	THEA-	8. Farm or Lease Ivame
Name of Operator		Noland and Wells
· ·		9. Well No.
James Hatcher		
Address of Operator	d Service, Box 1641, Bloomfield, N.M	Reinhardt # 1
Bloomfield Oilfield	d Service, Bon	10. Field and Pool, or white
Location of Well		i marmilio con bana
Α	FEET FROM THE LINE AND FEET F	
UNIT LETTER A	29N 11W	
•	21 TOWNSHIP 29N BANEE 11W	mom: [[[]]]]]]]
THE LINE, SECTION		- Million Hilling
THIM THE	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		San Juan
	Calmina Papart of	Orher Data
Check App	propriate Box To Indicate Nature of Notice, Report or	ENT REPORT OF:
NOTICE OF INTE	SUBSEQUE	ENT REPORT OF
NOTICE OF INTE		
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
ERFORM REMEDIAL WORK	COMMENCE DRILLING OPHS.	PLUG AND ABANDOHMENT
EMPORARILY ABANDON		_
	CHANGE PLANS CASING TEST AND CEMENT SEE	· \
IN COR ALTER CASING		
AFF OF WELLE CVAINE	OTHER	
		uding estimated date of starting any proposed
• Describe Proposed or Completed Opera	tions (Clearly state all pertinent details, and give pertinent dates, incl	uding estimated date of starting any proposed
Describe Proposed or Completed Opera	tions (Clearly state all pertinent details, and give pertinent dates, incl	d un
Describe Proposed or Completed Opera work) SEE RULE 1103.	ig and equipment on location and rigo	ged up.
Describe Proposed or Completed Opera work) SEE RULE 1103.	ig and equipment on location and rigo	ged up.
Describe Proposed or Completed Opera work) SEE RULE 1103.	ig and equipment on location and rigo	ged up.
Describe Proposed or Completed Opera work) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. P	ged up. to 690. Mixed and ulled tubing back to
Describe Proposed or Completed Opera work) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. P	ged up. to 690. Mixed and ulled tubing back to
Describe Proposed or Completed Opera work) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150.	ig and equipment on location and rigory 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plug from 150 to 50. Fluid 1	ged up. to 690. Mixed and ulled tubing back to evel fell down hole to ft. below ground
Describe Proposed or Completed Operation) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150.	ig and equipment on location and rigory 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plug from 150 to 50. Fluid 1	ged up. to 690. Mixed and ulled tubing back to evel fell down hole to ft. below ground
Describe Proposed or Completed Operation) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150.	ig and equipment on location and rigory 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plug from 150 to 50. Fluid 1	ged up. to 690. Mixed and ulled tubing back to evel fell down hole to ft. below ground
12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. P	ged up. to 690. Mixed and ulled tubing back to evel fell down hole to ft. below ground
12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigory 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plug from 150 to 50. Fluid 1	ged up. to 690. Mixed and ulled tubing back to evel fell down hole to ft. below ground
Describe Proposed or Completed Operation) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150.	ig and equipment on location and rigory 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plug from 150 to 50. Fluid 1	ged up. to 690. Mixed and ulled tubing back to evel fell down hole to ft. below ground
*Describe Proposed or Completed Operators) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigory 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plug from 150 to 50. Fluid 1	ged up. to 690. Mixed and ulled tubing back to evel fell down hole to ft. below ground
*Describe Proposed or Completed Operators) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plug from 150 to 50. Fluid 1	ged up. to 690. Mixed and ulled tubing back to evel fell down hole to ft. below ground
12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plug from 150 to 50. Fluid lasacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Rig	to 690. Mixed and ulled tubing back to evel fell down hole 4 ft. below ground ged down and moved
12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plug from 150 to 50. Fluid 1	ged up. to 690. Mixed and ulled tubing back to evel fell down hole to ft. below ground
12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plub from 150 to 50. Fluid lasacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Rigumans.	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved
12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pend set plug from 150 to 50. Fluid lasacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Rigumans.	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved
Describe Proposed or Completed Opera work) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pund set plub from 150 to 50. Fluid lasacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Rigumans.	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved
Describe Proposed or Completed Opera work) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pend set plug from 150 to 50. Fluid lasacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Rigumans.	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved
Describe Proposed or Completed Opera work) SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pend set plug from 150 to 50. Fluid lasacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Rigumans.	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved
Describe Proposed or Completed Operation), SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and off location.	ig and equipment on location and right up 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pluid la sacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Right MAR 5 OIL CONDIST	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved
Describe Proposed or Completed Operation), SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and off location.	ig and equipment on location and right up 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pluid la sacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Right MAR 5 OIL CONDIST	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved
Describe Proposed or Completed Opera work) SEE RULE 1703.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and off location.	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pend set plug from 150 to 50. Fluid lasacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Rigumans.	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved
Describe Proposed or Completed Opera work) SEE RULE 1703.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and off location.	ig and equipment on location and right up 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pluid la sacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Right MAR 5 OIL CONDIST	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved
Describe Proposed or Completed Opera work) SEE RULE 1703.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and off location.	ig and equipment on location and right up 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Pluid la sacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Right MAR 5 OIL CONDIST	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved  1982 COM.
Describe Proposed or Completed Operation), SEE RULE 1103.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and off location.	ig and equipment on location and rigure pertinent dates, included and equipment on location and rigure pertinent dates, included and tubing, cleaned out ement. Plug set from 690 to 550. Pland set plug from 150 to 50. Fluid less acks class B cement. Cut pipe off pumped 10 sacks, surface plug. Riguration of pumped 10 sacks, surface plug. Riguration of the best of my knowledge and belief.	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved  1982 COM.  1982
Describe Proposed or Completed Opera work) SEE RULE 1703.  12-7-81 - Moved r 12-8-81 - Picked pumped 40 sacks c 150. 12-9-81 - Mixed a Mix and pumped 30 level. Mixed and off location.	ig and equipment on location and rigup 3 7/8 bit and tubing, cleaned out ement. Plug set from 690 to 550. Plund set plub from 150 to 50. Fluid lasacks class B cement. Cut pipe off pumped 10 sacks, surface plug. Rigupated and set plug set from 690 to 50. District of my knowledge and belief.	to 690. Mixed and rulled tubing back to evel fell down hole 4 ft. below ground ged down and moved  1982 COM.  1982