

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

SP 100557

1. NAME OF OPERATOR

Producing Royalties, Inc.

2. ADDRESS OF OPERATOR

Box 1071 Lubbock Texas 79408

3. LOCATION OF WELL (State, County, Township, Range, Section, and Quarter Section, and any other location data required by the State to which the well is subject)

800' FN - 440' F&L Sec 13,
T29N, R12W, SAN JUAN Co. NM

4. DEPTH OF WELL

1. ELEVATION (in feet above sea level, or other datum)

5673 DF

CARRUT - CARVELL

5'

FOREVER - KUTE R

EX R 729N, R12W

N.M.M.

SAN JUAN N.M.

5. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

ABANDON, ETC., OF WELL

TEST WATER SHUT OFF

TEST OR ALTER Casing

WATER SHUT OFF

ABANDON WELL

FRAC. OR TREAT

MULTI-SHAFT Casing

FRAC. OR TREATMENT

ABANDON CASING

SHOOT OR GRIND

ABANDON*

SHOOTING OR GRINDING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

OTHER

OTHER

NOTE: Report results of multiple completion on Well Completion or Abandonment Report and Log form.

6. Describe briefly the nature of the work done, including a description of the work, the location of the well, the date of starting and completing the work, and the results of the work (If well is directionally drilled, also subsurface locations and measurements from surface for all markers and zones pertinent to this work.)

This well has been plugged & abandoned as follows:

6-10-76 Move in equip., Circulate hole w/ mud, Spot 50sx plug 1877' to 1735', Pulled 1" tag.

6-11-76 Perf 4 hole @ 650', Ran tag to 650' Spot 50sx @ 650', Pull tag. Squeezed 30sx thru Perfs. Set P&A marker w/ 10sx. Clean up loc.

7. I hereby certify that the foregoing is true and correct

SIGNED

Larry G. Bedford

TITLE

Agent for Operator

DATE

3-12-76


(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE



*See Instructions on Reverse Side