

1. NAME OF OPERATOR 3
 2. DISTRIBUTION
 3. SANTA FE 1
 4. FILE 1
 5. O.S.G.S.
 6. LAND OFFICE
 7. OPERATOR 1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

8. Indicate Type of Lease
 State ☐ Pool ☒
 9. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT, FORM C-101, FOR SUCH PROPOSALS.

10. Indicate Type of Well
 OIL ☐ GAS ☒ OTHER ☐
 11. Name of Operator
Artee Oil & Gas Company
 12. Address of Operator
Drawer 570, Farmington, New Mexico
 13. Location of Well
 UNIT 1 1620 FEET FROM THE South LINE AND 300 FEET FROM
West LINE, SECTION 11 TOWNSHIP 29N RANGE 12W NMPM.

14. Unit Agreement Name
 15. Name of Lease Name
Mont
 16. Well No.
 17. Field and Pool, or Wellbore
Trishon, Kitzee

18. Elevation (Show whether DF, RT, GR, etc.)

19. County
San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
 PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
 PULL OR ALTER CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOBS ☐
 OTHER ☐

20. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1109.

PROPOSE TO:

1. Spot cement plug across perfs 1696-1724'. Top of plug to be 1540'. Total depth is 1925'.
2. Perforate Ojo Alamo at 600' and squeeze with 50 sxs. Spot 100' plug inside pipe.
3. Squeeze bradenhead with 50 sxs.
4. Spot 10' plug at surface.
5. Install dry hole marker.
6. Clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE District Superintendent DATE 12-18-72

APPROVED BY [Signature] TITLE SUPERVISOR DIST. #3 DATE DEC 21 1972

CONDITIONS OF APPROVAL, IF ANY: