## New Mexico Oil Conservation Commission

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

October 2, 1959

auth le land

King Oil Company 745 Petroleum Club Building Denver, Colorado

Attn: Mr. Bernard King, President

Re: Non-standard Location, King Oil Company Navajo ###

Dear Str:

We received Notice of Intention to Drill and Acreage Dedication Plat on your #4 Navajo "C" well located 1970 feet from the North Line and 1460 feet from the East Line of Section 4-3CN-17W. I presume since you have dedicated 40 acres that this is primarily an oil prospect. This being the ease, the well does not comply with the New Mexico Oil Conservation Commission Rules and Regulations regarding spacing as it is not located the required distance from the 40-acre boundary.

New Mexico Rules require that an eil well be located no closer than 330 feet to the quarter-quarter section lines. Your well is located only 140 feet from the west line of the  $SR_2^2$   $Nk_2^2$ . Production on this well could not be approved without notice and hearing to show cause why the well could not be a standard location.

Will you please advise.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA : ka

## 

BONDER OF 1885

Zing (13 ko praj 1955 indopoda Pieka (1914) Israen (1918rodo

BANK BANK OF BUILDING CO. CO.

i ga ili kuma publikan biban tinta kilinta kating inti inakanting. Attiba**jta "V**" ki

මේම ගෙන දිනිස්ත් විධාය ගැන විධාය ගැන විධාය විධාය විධාය වන විධාය විධ විධාය විධාය විධාය විධාය විධාය විධ විධ විධාය විධාය විධාය විධාය ව

the taries haise require that the sit will be to the erest than 19 or and than 19 or and than 19 or and than 19 or and the sit of the erest of the e

18-11 and places assign

্স্থার চুল্পের সংবর্

olema o godi. Et t**o**letak proposition

20 A 178