

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR  
Murphy Oil USA *MESA RETAILERS*

3. ADDRESS OF OPERATOR  
238 Petroleum Plaza, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
5907.9

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.  
NM-02788

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Mesa Murphy Federal

9. WELL NO.  
1

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 27, T-30N, R-11W

12. COUNTY OR PARISH  
San Juan

13. STATE  
New Mexico

RECEIVED

SEP 27 1985

330' FSL & 660' FWL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

9-23-85

Rig up P & A rig, pull 7" csg. clean out with 4-3/4" bit to base of Ojo-Alamo or find hard cement plug at or in well bore below base of Ojo-Alamo sandstone, spot cement plug over Ojo-Alamo 960'-1030', spot solid cement plug 180' to surface, install dry hole marker, clean up all debris, fill in pits, re-store land to contour, reseed location and disturbed road area back to main lease road approximately 500 ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *D. E. Barker*

TITLE Acting Supt.

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

\*See Instructions on Reverse Side

OCT 07 1985  
OIL CON. DIV.  
DIST. 3

APPROVED

DATE September 23, 1985

OCT 02 1985

FARMINGTON RESOURCE AREA