

well file

SOUTHERN UNION PRODUCTION COMPANY

POST OFFICE BOX 808  
FARMINGTON, NEW MEXICO 87401

September 1, 1976

Mr. A. R. Kendrick  
Supervisor, District No. 3  
New Mexico Oil Conservation Commission  
1000 Rio Brazos Road  
Aztec, New Mexico 87410



Re: Southern Union Production Company  
Summit "B" No. 5  
Unit F, Sec. 33, Twp. 29-N, Rge. 11-W  
Fulcher Kutz Pictured Cliffs

Dear Sir:

In answer to your letter of July 30, 1976 on the above-referenced well, we have made several tests to try to find the source of the gas odor detected at our Summit "B" No. 5 well.

It has been determined that the odor was caused by a leak in the pipeline between the meter tube and the well. This pipe has been replaced by Gas Company of New Mexico and the ensuing surveys indicate that there is no further evidence of gas leakage or odors.

Your help in reporting this problem to us is appreciated.

Yours very truly,

SOUTHERN UNION PRODUCTION COMPANY

Rudy D. Motto  
Assistant Area Superintendent

RDM:bjs

cc: New Mexico Oil Conservation Commission  
P.O. Box 2088  
Santa Fe, New Mexico 87501  
United States Geological Survey  
P.O. Box 959  
Farmington, New Mexico 87401