

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Garry Michael; Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-513-4895
Facility Name:	lease road near the Cotton Draw Unit 237H	Facility Type	Lease Road
Surface Owner	Federal	Mineral Owner	Federal
		API No	30-025-41996

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	10	25S	32E	200	south	950	west	Lea

Latitude: 32.1382933 N

Longitude: 103.6683654 W

NATURE OF RELEASE

Type of Release	illegal dump; unknown fluid	Volume of Release	100BBLS	Volume Recovered	0BBLS
Source of Release	Illegal dump	Date and Hour of Occurrence	May 27, 2015 8:30 AM	Date and Hour of Discovery	May 27, 2015 8:30 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones; OCD & Jim Amos; BLM		
By Whom?	Matt Nettles; Assistant Production Foreman	Date and Hour	May 27, 2015 2:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		
If a Watercourse was Impacted, Describe Fully.	N/A				
Describe Cause of Problem and Remedial Action Taken.	Possible illegal dump discovered on lease road near the Cotton Draw Unit 237H. Fluid dumped is unknown at this time and the affected soil is being analyzed by Talon, LPE It appears that approximately 100BBLS of the unknown fluid was dumped.				

RECEIVED

By OCD District 1 at 11:49 am, May 29, 2015

Describe Area Affected and Cleanup Action Taken. The dump appears to have originated south of the Cotton Draw Unit 237H where Orla Road and Cotton Draw Road intersect. It appears that a truck driver opened his load/unload valve on the back of his truck and drove with it open releasing an unknown fluid from the intersection of Orla Road and Cotton Draw Road turning to another lease road to the north and then back to the west down another lease road ending at the Cotton Draw Unit 237H location. It appears that the width of the affected area fluctuates from 6" to 4' and is approximately a mile long. It appears that approximately 100BBLS of unknown fluid was released. None of the released fluid was recovered. Cleanup will be determined after samples are evaluated. Final report to follow.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandy Farley</i>	OIL CONSERVATION DIVISION		
Printed Name: Sandra Farley	Approved by Environmental Specialist: <i>Kellan</i>		
Title: Field Admin Support	Approval Date: 05/29/2015	Expiration Date: 08/29/2015	
E-mail Address: sandy.farley@dmv.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> 6137 1RP-3654
Date: May 29, 2015	Phone: 575.746.5587		

* Attach Additional Sheets If Necessary

pKJ1514943006
nKJ1514942919



10-32E
SESE

10-25S-32E
SWSW

10-25S-32E
SESW

Cotton Draw Unit 237H

15-32E
NENE

15-25S-32E
NWNW

15-25S-32E
NENW

15-32E
SENE

15-25S-32E
SWNW

15-25S-32E
SENE

total=approx 100BBLs unknown fluid

Cotton Draw Rd

Devon GIS Mapping



Disclaimer: This plat is for illustrative purposes only and is neither a legally recorded map nor a survey and is not intended to be used as one.

Scale: 1:4,514

Date Printed: 5/29/2015 10:13:05 AM

