

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☐ Final Report

Name of Company: <i>Chevron</i>	Contact: Caleb Weaver
Address: <i>2401 Ave O Eunice, NM 88231</i>	Telephone No.: 432-235-9382
Facility Name: <i>Moran #2</i>	Facility Type: Well Site/Battery

Surface Owner: SW Cattle Company	Mineral Owner:	API No.: 30-025-28704
----------------------------------	----------------	-----------------------

### LOCATION OF RELEASE

Unit Letter I	Section 6	Township 20	Range 38E	Feet from the 1639 ft	North/South Line South	Feet from the 686 ft	East/West Line East	County Lea
------------------	--------------	----------------	--------------	--------------------------	---------------------------	-------------------------	------------------------	---------------

Latitude: 32.599290 Longitude: -103.181621

### NATURE OF RELEASE

Type of Release: <i>Oil, Produced water</i>	Volume of Release: Historical	Volume Recovered: N/A
Source of Release: <i>Tank</i>	Date and Hour of Occurrence: Historic	Date and Hour of Discovery: 5/1/15
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

*By OCD District 1 at 2:43 pm, Jun 02, 2015*

Describe Cause of Problem and Remedial Action Taken.\*

*Removed old tank from jobsite. Soil underneath the tank appears to be contaminated. Soil will be removed and tested, and whole site will be remediated.*

Describe Area Affected and Cleanup Action Taken.\*

*Inside of a berm. Cleanup action is to haul contaminated soil to proper disposals and perform soil tests to ensure all affected soil is removed. Fresh dirt will be brought in to fill back in the area.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Caleb Weaver</i>	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Caleb Weaver	Approved by Environmental Specialist: <i>Kyle S</i>		
Title: Facilities Engineer	Approval Date: 06/02/2015	Expiration Date: 09/02/2015	
E-mail Address: caleb.weaver@chevron.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> 4323 1RP-3657
Date: 06/01/2015	Phone: 432-687-7258		

\* Attach Additional Sheets If Necessary

nKJ1515353221  
pKJ1515353382