<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Form C-141

Revised August 8, 2011

2,2,2,2,0													
Release Notification and Corrective Action													
						OPERA							
Name of Company Devon Energy Production Company						Contact Rudy Zuniga Production Foreman							
Address 6488 Seven Rivers Hwy Artesia, NM 88210						Telephone No. 575-390-5435							
Facility Name South Shoebar 15 State 2						Facility Type Oil							
						G							
Surface Owner State Mineral Owner						State API No 30-025-34702							
				LOCA		N OF RE	LEASE						
Unit Letter	Section	Township	Range	Feet from the	North	/South Line	Feet from the	East/	West Line	County			
Н	15	17S	35E	1650		North	800		East	Lea			
		,	Longitude: W 103'54'53.19"										
<u> </u>													
Type of Release Spill Volume of Release Volume Recovered													
Type of Rele Produced Wa						lecovered							
Produced wa	iter and On	27 bbls Produced Water and 17 bbls oil			6 bbls oil								
Source of Release							Date and Hour of Occurrence			Date and Hour of Discovery			
2" ball valve busted							1.3.16 @11:30 am 1.3.16 @1						
Was Immedi	iate Notice	If YES, To Whom?											
		d Kellie Jones OCD											
							Jim Amos BLM						
By Whom? Lynn Smith, Assistant Production Foreman							Date and Hour						
							1.4.16 @ 8:06 am 1.4.16 @ 8:10 am						
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse						
Yes No						N/A							
						RECEIVED							
If a Watercourse was Impacted, Describe Fully.* N/A													
Describe Cause of Problem and Remedial Action Taken.*							By Kellie Jones at 7:12 am, Jan 07, 2016						
2" ball valve busted causing a 44 bbl produced water and oil to release into unlined containment. Well was immediately shut in to prevent further release.													
Repairs on the ball valve will be made.													
Describe Area Affected and Cleanup Action Taken.*													
					South	West side of	the facility 6 bble	oil wa	s recovered	via vacuum	truck	Size of	
27 bbls produced water and 17 bbls oil was released on the South, South West side of the facility. 6 bbls oil was recovered via vacuum truck. Size of affected area was 5'x48'. All released fluid remained on location. Environmental Agency to be contacted for remediation.													
arrested and was 5 A to 17th followed fluid fernamed on foldation. Environmental regency to be contacted for fernediation.													
				e is true and comp									
				nd/or file certain r									
				ce of a C-141 report investigate and r									
				tance of a C-141									
				nance of a C-141	report u	oes not renev	e the operator or i	respons	ordinty for Co	mphance v	viui aii	y other	
federal, state, or local laws and/or regulations.							OIL CONSERVATION DIVISION						
Signature: C	orina h	OIL COLINDATIVITION DITINION											
	· ·	V ~~~											
Printed Name	e: Corina N		Approved by Environmental Specialist:										
Title: Field Admin Support						Approval Date: 01/07/2016 Expiration Date: 03/07/2016							
E-mail Addre	ess: corin a i	mova@dvn c	om			Conditions of	Approval:				_		
E-mail Address: corina.moya@dvn.com							Site samples required. Delineate and						

* Attach Additional Sheets If Necessary

Phone: 575.746.5559

Date: 1.5.2016

photographs of remediation recommended.

remediate as per MNOCD guides. Geotag

nKJ1600726055 pKJ1600726236

1RP-4079









