## **RECEIVED**

State of New Mexical By JKeyes at 8:15 am, Jan 15, 2016

Energy Minerals and Natural Resources

<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

**Release Notification and Corrective Action** 

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

						OPERATOR						
Name of Company Oxy Permian Ltd.						Contact Casey Summers						
Address 6 Desta Drive, Midland, TX 79705						Telephone No. (575) 513-8289						
Facility Name Antelope Ridge Compressor CTB						Facility Type Battery						
Surface Owner State Mineral Owner						API No. 30-025-21082						
				LOCA	TIO	N OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/V	Vest Line	County		
L	34	238	34E						Lea County, I			
	•		]	Latitude N 32.2	5817º	Longitu	de W 103.4639	9°				
NATURE OF RELEASE												
Type of Rele	ase Oil a	nd produced w			Volume of Release 1 bbl oil, 59 bbls produced water			Volume Recovered 45 bbls				
Source of Release Frozen 4" steel line to heater treater						Date and Hour of Occurrence			Date and Hour of Discovery			
Was Immediate Notice Given?						01/04/2016 If YES, To						
✓ Yes ☐ No ☐ Not Required												
By Whom? Jennifer Gilkey @ BBC International						Date and Hour 01/05/2016 @ 10:06 am						
Was a Watercourse Reached?  ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*												
a water-course in parious properties a diff.												
Describe Cause of Problem and Remedial Action Taken.*												
A frozen 4" steel line to the heater treater leaked 1 bbl of oil and 59 bbls of produced water onto the ground. A vacuum truck recovered 45 bbls of fluids												
and the line was repaired/replaced.												
Describe Area Affected and Cleanup Action Taken.*												
The affected area is approximately 30' x 30' centrally located around the heater treater on the pad. Remediation will be completed in accordance with a												
remediation plan approved by NMOCD.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state, or local laws and/or regulations.						OIL CONSERVATION DIVISION						
/ //						<u>old combek virilor bivibion</u>						
Signature:						Approved by Environmental Specialist:						
Printed Name: Casey Summers												
Title: NM Environmental Advisor						Approval Date: 01/15/2016 Expiration Date: 03/15/2016						
	19	-	į				-		W.			
E-mail Addre								Delinos	Attached			
Date:	14-10	Phone: (575) 513-8289 remediate per NMOCD guidelines.							1RP 4111	11		
							Geotagged photos of remediation nJXK1601529499					
						recommended	l.			pJXK1601	529603	3