

RECEIVED**By JKeyes at 7:19 am, Feb 10, 2016**

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation	Contact Bruce Baker
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982
Facility Name WBDU 127	Facility Type: Injection Well

Surface Owner Millard Deck Estates	Mineral Owner	API No. 30-025-39574
------------------------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter N	Section 4	Township 21S	Range 37E	Feet from the 660'	North/South Line FSL	Feet from the 1650'	East/West Line FWL	County Lea
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	------------------------	-----------------------	---------------

Latitude 32.5024796 Longitude -103.1712189**NATURE OF RELEASE**

Type of Release: produced water	Volume of Release 115 barrels of produced water	Volume Recovered 90 barrels of produced water
Source of Release: Fiberglass line	Date and Hour of Occurrence 1/28/2016	Date and Hour of Discovery 1/28/2016
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones (NMOCD)	
By Whom? Bruce Baker	Date and Hour 1/29/2016 at 10:05 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 2 inch buried fiberglass line ruptured. The line was isolated and trucks were dispatched to pick-up standing fluid.

Describe Area Affected and Cleanup Action Taken.

The majority of the release was contained to lease pads and lease road except for a small area south of lease road and east of the WBDU 100 lease pad affected pasture.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bruce Baker</i>	OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker	Approved by Environmental Specialist: <i>Jamie Keyes</i>	
Title: Environmental Technician	Approval Date: 02/10/2016	Expiration Date: 04/10/2016
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval: Discrete site samples only. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> IRP 4176
Date: 2/5/2016 Phone: (432) 631-6982		

* Attach Additional Sheets If Necessary

nJXK1604126187
pJXK1604126281