RECEIVED By JKeyes at 8:10 am, Apr 07, 2016



Discrete samples only, no composites.

ConocoPhillips

P.O. Box 2197 Houston, TX 77252-2197 Phone 281.293.1000

Red Hills West State 16 W1 11 H (RP-4215) Corrective Action Plan

API No. 30-025-41707

Release Date: March 12, 2016

Unit A, Section 16, Township 265, Range 32E

April 6, 2016

Jamie Keys Environmental Specialist – New Mexico Oil Conservation Division Energy, Minerals and Natural Resources Department 1625 N. French Dr. Hobbs, NM 88240

RE: Corrective Action Plan ConocoPhillips Red Hills West State 16 W1 11H (RP-4215) API No. 30-025-41707

Mr. Keys:

ConocoPhillips (CoP) has prepared this Corrective Action Plan (CAP) to address potential environmental concerns at the above-referenced site.

Background and Previous Work

On Saturday March 12, 2016 at 0800, a release of crude oil/produced water occurred due to two ruptured gasket seals, resulting in the release of 1.6 BBLs of crude oil and 5 BBLs of produced water with 1.5 BBLs of crude and 4.5 BBLs of produced water recovered. Immediate action was to depressurize line, replace seals, and return equipment back to service. NMOCD was notified of the release on March 14, 2016, and an initial C-141 was submitted (Appendix A).

COP personnel were on site to visually assess the release on March 14, 2016. The release was mapped and photographed (Appendix B). Based on the assessment, the release will be excavated down 6 inches bgs. Once the excavation is completed, a composite sample from the bottom of the excavation will be taken and field tested for chlorides and organic vapors. If the field data indicates that the composite will not achieve chloride, Gasoline Range Organics (GRO), Diesel Range Organics (DRO) and BTEX readings below regulatory standards, the excavation will be deepened until field testing indicates that all constituents from the bottom composite will return values below regulatory standards. The bottom composite will then be taken to a commercial laboratory to confirm that chloride, GRO, DRO and BTEX readings are below regulatory standards.

All excavated soils will be taken to a NMOCD approved facility for disposal. Clean soil will be imported to the site to serve as backfill and contoured to the surrounding location. A sample of the backfill soil will be taken to a commercial laboratory to confirm that the chloride reading is below regulatory standards.

Once these activities have been completed, a report will be sent to NMOCD requesting 'remediation termination' and site closure.

Please call me if you have any questions or wish to discuss the site. Sincerely,

Philip Lee, CIH, CSP HSE Senior Specialist (432) 688-6866 Attachments:

Figure 1 – Site Map Appendix A – Initial C-141 Appendix B – Photo Documentation

Figure 1 – Site Map



Appendix A – Initial C-141

District I 1625 N. Franch Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210		New Mexico and Natural Resources			Form C-141 Revised August 8, 2011	
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV					to appropriate District Office in cordance with 19.15.29 NMAC.	
1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505						
Release Notification and Corrective Action						
	OPERATOR 🛛 Initial Report 🗌 Final Report					
			Contact: Philip Lee			
			Telephone No. 432-238-1050 Facility Type: Wellhead			
rface Owner: NMOCD Mineral Owner: N		NMOCD API No. 30-025-41		. 30-025-41707		
LOCATION OF RELEASE						
			/South Line Feet from the East/West Line County West LEA		-	
A 16 265 32E	NO	n		West	LEA	
Latitude N32°2'10.86" Longitude W103		OF DELE	A CT			
Type of Release: Spill	NATURE	OF RELE	ASE Release: 6.6 BBI	S Vohme R	lecovered: 6 BBLS	
Source of Release: Ruptured gasket seals near	wellhead (Lat/Long of		our of Occurrenc		Hour of Discovery	
well).		03/12/2016		03/12/201	6 8:00 am	
Was Immediate Notice Given?	No. Not Pomiro	If YES, To				
Yes No Not Required Jamie Keyes, NMOCD By Whom? Philip Lee Date and Hour: 03/14/2016 09:45 am						
By Whom? Philip Lee Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.					
□ Yes						
If a Watercourse was Impacted, Describe Fully Describe Cause of Problem and Remedial Acti						
Describe Area Affected and Cleanup Action Taken."						
On Saturday March 12, 2016 at 0800 (MST), a release of crude oil/produced water occurred due to two ruptured gasket seals, resulting in the release of 1.6 BBLs of crude oil and 5 BBLs of produced water with 1.5 BBLs of crude and 4.5 BBLs of produced water recovered. Immediate action was to depressurize line, replace seals, and return equipment back to service. Location will be remediated in accordance with NMOCD and COPC policies with confirmation soil samples.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other						
federal, state, or local laws and/or regulations.						
OIL CONSERVATION DIVISION						
Signature:	-					
Printed Name: Philip Lee Approved by Environmental Specialist:						
Title: HSE		Approval Date	2:	Expiration 1	Date:	
E-mail Address: philip.p.lee@conocopl	hillips.com	Conditions of	Approval:		Attached	
Date: 03/16/2016 Attach Additional Sheets If Necessary	Phone:432-238-1050					

Appendix B – Photo Documentation



View looking towards the east (3/14/2016)



