District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources



Final Report

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

☐ Initial Report

Release Notification and Corrective Action

OPERATOR

			ion Company		Contact Randall Gladden, Production Foreman						
•						Telephone No. 575-513-9463					
Facility Name Thistle Unit #52H Fa							Facility Type Oil				
Surface Owner Private Mineral Owner						r Federal API No 30-025-41897					
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the		/South Line	Feet from the	East/Wes	st Line	County	
С	28	23S	33E	180		North	1795	We	est	Lea	
Latitude: 32.2824745 Longitude: -103.5799866											
NATURE OF RELEASE											
							Volume of Release 6 BBLS Volume Recovered 6 BBLS				
Source of Release Thief hatch									Hour of Discovery © 9:05pm		
Was Immediate Notice Given? If YES, To Whom?										, с э.юэрш	
☐ Yes ☐ No ☐ Not Required											
By Whom? David Simmons, Assistant Production Foreman						Date and Hour					
						BLM - 7/10/2016 @ 9:30pm OCD - 7/10/2016 @ 9:36pm					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse					
					N/A						
If a Watercourse was Impacted, Describe Fully.* N/A											
Describe Cause of Problem and Remedial Action Taken.*											
6 BBLS oil overflowed from the Thief hatch on the top of the oil tank due to a closed Equalizer line. The Equalizer line was opened so oil could flow through line to other oil tank to prevent further release. All tanks returned to operation.											
		l and Cleanu			k into lii	ned containme	ent All 6 RRIS o	il remaine	d in linea	Loontainment Liner was	
checked for h	6 BBLS of oil was released from the Thief hatch on top of oil tank into lined containment. All 6 BBLS oil remained in lined containment. Liner was checked for holes, no holes were found in the liner. Vacuum truck recovered all 6 BBLS of the released oil. No further action is necessary.										
										uant to NMOCD rules and	
										eases which may endanger	
	public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health										
or the enviro	nment. In a	addition, NMC	OCD accep							ompliance with any other	
federal, state	, or local la	ws and/or regu	ılations.				077 0017	~====			
Signature: Sarah Gallegos-Troublefield						OIL CONSERVATION DIVISION					
Signature. Sour wire growing of 110 works term									Jamx	lyer	
Printed Name: Sarah Gallegos-Troublefield						Approved by Environmental Specialist:					
Title: Field Admin Support						Approval Date: 07/11/2016 Expiration Date: ///					
E-mail Address: Sarah.Gallegos-Troublefield@dvn.com						Conditions of Approval: Attached					
Date:7/11/20	16 Ph	one: 575.748.			1RP 4346						

Thistle Unit #52H 6 BBLS Oil- 7/10/2016



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere Prepared by: Sarah Map is current สอประชาระวันควยโพส ield

Z

Map is current a de allegos Juo polo de de la Miles

0.00 0.0

0.02 1:889











