

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By **JKeyes** at **7:19 am, Jul 19, 2016**

Form C-141

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Jake Harrington, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	432-214-5175
Facility Name	Cotton Draw Unit #252H	Facility Type	Oil
Surface Owner	Federal	Mineral Owner	Federal
		API No	30-025-42619

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	7	25S	32E	100	North	1780	East	Lea

Latitude: 32.1517521209268 Longitude: -103.711592528012

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	785 BBLS	Volume Recovered	785 BBLS
Source of Release	Water tank	Date and Hour of Occurrence	7/15/2016 @ 7:20pm	Date and Hour of Discovery	7/15/2016 @ 7:20pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	OCD- Jamie Keyes BLM- Shelly Tucker		
By Whom?	Hubert Perry, Night Production Foreman	Date and Hour	OCD- 7/15/2016 @ 11:48pm BLM- 7/18/2016 @ 2:14pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

A water tank was struck by lightning resulting in a release of 785 BBLS produced water. All wells that produce to this facility were shut in immediately to prevent further release. Repairs will be made.

Describe Area Affected and Cleanup Action Taken.*

Produced water was released when lighting struck one of the water tanks rupturing the tank. This resulted in the connected equalizing lines to release additional produced water; totaling a release of 785BBLS of produced water. The produced water was released into the surrounding lined containment and secondary lined containment. Both liners were checked for holes, no holes were found in both the liners. Due to the fact that no holes were found in the liners, it is assumed all the released fluid remained in the lined containment and did not leave location. This assumption could be incorrect due to the wet ground from the rain. Vacuum truck recovered approximately 786 BBLS of fluid; 785 BBLS produced water, 1 BBL of rain water. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sarah Gallegos-Troublefield</i>	OIL CONSERVATION DIVISION		
Printed Name: Sarah Gallegos-Troublefield	Approved by Environmental Specialist: <i>Jamie Keyes</i>		
Title: Field Admin Support	Approval Date: 07/19/2016	Expiration Date: 09/19/2016	
E-mail Address: Sarah.Gallegos-Troublefield@dv.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7/18/2016 Phone: 575.748.1864	Discrete samples only. Delineate and remediate per NMOCD guidelines. Ensure BLM concurrence/ approval.		1RP 4352

* Attach Additional Sheets If Necessary

nJXK1620126153
pJXK1620126303

Cotton Draw Unit #252H

785 BBLs PW 7-15-2016



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: Sarah
Map is current as of 7-15-2016



Miles
0 0.00 0.01 0.02 1:889

Sec 7, T25S, R32E

785 BBLs PW











