

REVIEWED

By Kristen Lynch at 12:09 pm, Oct 20, 2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**☒ Initial Report ☐ Final Report

Name of Company - EOG Resources, Inc.	Contact Zane Kurtz	
Address 5509 Champions Drive, Midland, TX 79706	Telephone No. 432-425-2023	
Facility Name Endurance 36 State Com 701/704	Facility Type oil well	
Surface Owner NM State Lands	Mineral Owner EOG	API No. 30-025-42984

LOCATION OF RELEASE

Unit Letter	Section 36	Township 26S	Range 33E	Feet from the 360	North/South Line South	Feet from the 1020	East/West Line West	County Lea
-------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.0011 Longitude -103.5315

NATURE OF RELEASE



Type of Release Produced Water	Volume of Release 2980 bbls	Volume Recovered 2660 bbls
Source of Release 6500 bbl water holding tank	Date and Hour of Occurrence 10-16-2016	Date and Hour of Discovery 0700
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
6500 bbls produced water holding tank ruptured and spilled 2980 bbls into a small containment and onto the pad and off the pad on the west side. It stayed within 20 feet of the pad and did not migrate far into the pasture or dry creeks. We were able to recover about 2660 bbls with vac trucks. One call was made and consultant went out to delineate vertical and horizontal impacts. A work plan will be prepared to remediate impacted soil.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Zane Kurtz		Approved by Environmental Specialist: 	
Title: Sr. Environmental Rep.		Approval Date: 10/20/2016	Expiration Date: 12/20/2016
E-mail Address: zane_kurtz@eogresources.com		NMOCD Accepts Discrete Samples Only	
Date: 10-18-2016 Phone: 423-425-2023		Conditions of Approval: Notify NMOCD Prior to Sampling Please submit remediation plan no later than 11/20/2016	
		Attached <input type="checkbox"/> 1RP 4471	

* Attach Additional Sheets If Necessary

nKL1629443451
pKL1629443643