

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

REVIEWED

By Kristen Lynch at 7:31 am, Oct 31, 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	FORGE ENERGY, LLC	Contact	KATRINA BOYD
Address	10999 IH 10 WEST, SUITE 900, SAN ANTONIO, TX 78230	Telephone No.	432-524-1301
Facility Name	SCHUBERT 18-4H	Facility Type	OIL WELL
Surface Owner	Mineral Owner	API No.	30-025-43365

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	18	19S	39E	245	SOUTH	2405	EAST	LEA

Latitude 32.65371776 Longitude -103.0840306

NATURE OF RELEASE

Type of Release	WATER	Volume of Release	70BBLS	Volume Recovered	10BBLS
Source of Release	WELLHEAD	Date and Hour of Occurrence	Date and Hour of Discovery 10/23/2016 @ 2pm		
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Well started kicking while installing Artificial Lift Equipment; well started to pressure up, Vacuum truck couldn't keep up with fluid returns. BOP RAMS had trouble sealing around meter cable. Pump truck continued to pump kill fluid until it was killed. Hydril BOP was installed on top of manual BOP

Describe Area Affected and Cleanup Action Taken.*

Wellsite Location; all fluids except 2 bbls remained on location the remaining 2 bbls are on the outside edge of location. Clean-up action involves 3rd Party, Tetra Tech Environmental.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>K. Boyd</i>		OIL CONSERVATION DIVISION	
Printed Name: Katrina Boyd		Approved by Environmental Specialist: <i>Kristen Lynch</i>	
Title: Operations Assistant		Approval Date: 10/31/2016	Expiration Date: 12/31/2016
E-mail Address: kboyd@forenergy.com		NMOCD accepts discrete samples only	
Date: 10/24/2016 Phone: 432-524-1301		Conditions of Approval: Notify OCD prior to sampling Please submit remediation plan no later than 11/31/2016.	
		Attached <input type="checkbox"/> 1RP 4478	

* Attach Additional Sheets If Necessary

nKL1630526579
pKL1630526875