

From: Yu, Olivia, EMNRD
To: "superior21j@aol.com"
Cc: Tucker, Shelly
Subject: RE: C141 Lea Unit #34 H
Date: Friday, August 11, 2017 11:39:00 AM
Attachments: image001.png
1RP4780.pdf

Mr. Orozco:

Thank you for the below information. Based on the GPS coordinates, the PLSS has been modified to 13C- T20S- R34E. Also, please confirm that the type of release is oil rather than produced water.

The 1RP for this incident is

4780	8/8/2017	A	Legacy	Lea Unit 34H	30-025- 42344	20S-34E- 13C	7/31/2017
-------------	----------	---	--------	--------------	------------------	-----------------	-----------

Please note that a release characterization/delineation workplan as detailed in the attachment must be approved by NMOCD BEFORE any remediation work.

Thanks,

Olivia Yu
Environmental Specialist
NMOCD, District I
Olivia.yu@state.nm.us
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: superior21j@aol.com [mailto:superior21j@aol.com]
Sent: Tuesday, August 8, 2017 11:45 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Subject: Fwd: C141 Lea Unit #34 H

Olivia

The well pad is located on the east side of Marathon Rd there is a road crossing where the poly runs thru marathon road putting the spill on the west side of Marathon Rd.



Sent from my iPhone

Begin forwarded message:

From: "Yu, Olivia, EMNRD" <Olivia.Yu@state.nm.us>
Date: August 8, 2017 at 11:12:42 AM MDT
To: "superior21j@aol.com" <superior21j@aol.com>, ofrayre20 <ofrayre20@gmail.com>
Cc: "Tucker, Shelly" <stucker@blm.gov>
Subject: RE: C141 Lea Unit #34 H

Dear Mr. Orozco:

Please check the GPS coordinates for this release. The provided lat/long coordinates are > 1000 ft. west from API well # 30-025-42344, which is not next to Marathon Road. Please confirm that the correct API well is associated.

Thanks,
Olivia

From: superior21j@aol.com [<mailto:superior21j@aol.com>]
Sent: Friday, August 4, 2017 9:03 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; ofrayre20 <ofrayre20@gmail.com>
Subject: C141 Lea Unit #34 H

Olivia

This is Mel with Superior Oilfield Services. Please see attached C141 for the Lea Federal Unit #34 H for Legacy Reserves. A poly line ruptured approximately 1,000 ft west of well. These well is located on Marathon RD, I will gather more information for you by next week

Thanks

Melecio Orozco

575-631-1217

Superior Oilfield Services

Begin forwarded message:

From: Superior Oilfield Services <superior21j@aol.com>

Date: August 4, 2017 at 7:54:41 AM MDT

To: "<superior21j@aol.com>" <superior21j@aol.com>

Superior21j@aol.com