From: Yu, Olivia, EMNRD

To: "Everhart, Harley"

Cc: <u>Stahnke, Graham; agroves@slo.state.nm.us</u>

Subject: RE: 1RP-4671\_REMEDIATION SUMMARY\_Rhombus\_11.15.17\_Part 1

**Date:** Friday, December 1, 2017 12:19:00 PM

Attachments: approved\_1RP-4671\_REMEDIATION SUMMARY\_Rhombus\_11.15.17\_Part 1.pdf

## Mr. Everhart:

Thank you for your prompt response. NMOCD approves of the delineation and proposed remediation for 1RP-4671. See attachment for your records.

In the closure document, please include 1) an appropriately scaled map with lined and excavated area demarcated and depths of excavation annotated. If there are differing depths of excavation within the release area, please separately outline each area and indicate on the scaled map. 2) Dated photo documentation of the remedial activities.

Like approval from NMSLO is required before emplacement of liner and backfilling.

Thanks, Olivia

**From:** Everhart, Harley [mailto:heverhart@akaenergy.com]

**Sent:** Friday, December 1, 2017 11:53 AM **To:** Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us> **Cc:** Stahnke, Graham < gstahnke@sugf.com>

**Subject:** RE: 1RP-4671\_REMEDIATION SUMMARY\_Rhombus\_11.15.17\_Part 1

Several questions regarding the remediation plan for 1RP-4671:

- Where was the East of Leak sample located? See attachment
- Is a 20 mil liner still proposed as written on page 7? Yes
- Does the data tables indicate the depths of excavation or depth of soil samples taken? Depth samples were taken

From: Yu, Olivia, EMNRD [mailto:Olivia.Yu@state.nm.us]

**Sent:** Friday, December 01, 2017 11:35 AM

**To:** Everhart, Harley < heverhart@akaenergy.com >

**Subject:** RE: 1RP-4671\_REMEDIATION SUMMARY\_Rhombus\_11.15.17\_Part 1

Mr. Everhart:

Pardon, I see that Part 2 included the lab results.

Olivia

From: Yu, Olivia, EMNRD

**Sent:** Friday, December 1, 2017 11:31 AM

**To:** Everhart, Harley < heverhart@akaenergy.com >; agroves@slo.state.nm.us **Subject:** RE: 1RP-4671\_REMEDIATION SUMMARY\_Rhombus\_11.15.17\_Part 1

Mr. Everhart:

Several questions regarding the remediation plan for 1RP-4671:

- Please submit laboratory reports with the chain of command for the soil samples from October 10, 2017.
- Where was the East of Leak sample located?
- Is a 20 mil liner still proposed as written on page 7?
- Does the data tables indicate the depths of excavation or depth of soil samples taken?

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

**From:** Everhart, Harley [mailto:heverhart@akaenergy.com]

Sent: Thursday, November 16, 2017 1:03 PM

**To:** Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us >; agroves@slo.state.nm.us **Subject:** 1RP-4671\_REMEDIATION SUMMARY\_Rhombus\_11.15.17\_Part 1

Dear Ms. Yu and Ms. Groves

## Part 1

Frontier Field Services (FFS) is pleased to submit the attached Remediation Summary for the Rhombus Union State Com #1, which provides recent analytical reports and excavation volumes. The remediation was completed in accordance with the enclosed New Mexico Oil Conservation Division (NMOCD) Approved Remediation Plan.

On behalf of Frontier Field Services, LLC (Frontier), a wholly-owned subsidiary of the Southern Ute Indian Tribe, the following Approved Revegetation and Noxious Weed

Management Plan is provided to address revegetation at the Rhombus Union State Com 1 release location.

Respectfully,

Harley Everhart

**EH&S Compliance** 

(575) 676-3505 - Direct

(575) 513-4922 - Cell

(575) 676-2401 - Fax

heverhart@akaenergy.com





## **CONFIDENTIALITY NOTICE:**

This email, including attachments, may include confidential and/or proprietary information, and may be used only by the person or entity to which it is addressed. Please do not read, copy or disseminate this communication unless you are the intended addressee. If you have received this communication in error, please permanently delete and call (575) 513-4922 immediately and ask to speak to the sender of this communication. Also, please notify immediately via email that you have received this message in error.