APPROVED By Olivia Yu at 11:45 am, Mar 08, 2018

NMOCD approves of the proposed delineation plan for 1RP-1568, 1RP-1711, 1RP-4231. See email correspondence for additional delineation sample locations.

1RP-1568, 1RP-1711 & 1RP-4231 DELINEATION PLAN J.M. Denton Battery Produced Water And Crude Oil Spill Lea County, New Mexico

Latitude: N33.02996 Longitude: W-103.17116

> LAI Project No. 17-0175-02 17-0175-03 17-0175-23

January 8, 2018

Prepared for: Legacy Reserves Operating, LP 303 West Wall Street, Suite 1300 Midland, Texas 79701

Prepared by: Larson & Associates, Inc. 507 North Marienfeld Street, Suite 205 Midland, Texas 79701

Mark J. Larson, P.G. Certified Professional Geologist #10490

Sarah/R. Johnson Staff Geologist

This Page Intentionally Left Blank

Table of Contents

1.0 INTRODUCTION	1
1.1 Background	1
1.2 Physical Setting	
1.3 Remediation Action Levels	
2.0 PRELIMINARY DELINEATION	2
3.0 DELINEATION PLAN	2
4.0 REMEDIATION PLAN	

Figures

Figure 1	Topographic Map
Figure 2	Aerial Map Showing Proposed Sample Points

Appendices

Appendix A	Initial C-141
Appendix B	EPI Preliminary Delineation Data
Appendix C	Photographs

1.0 INTRODUCTION

Larson & Associates, Inc. (LAI) has prepared this delineation plan on behalf of Legacy Reserves Operating, LP (Legacy) for submittal to the New Mexico Oil Conservation Division (OCD) District I for two produced water spills (1RP-1568 and 1RP-4231) and crude oil spill (1RP-1711) at the J.M. Denton Battery (Site) located in Unit J (NE/4, SW/4), Section 11, Township 15 South, Range 37 East, in Lea County, New Mexico. The geodetic position is North 33.02996 and West -103.17116. Figure 1 presents a topographic map. Figure 2 presents an aerial map.

1.1 Background

A produced water spill occurred on September 10, 2007, due to power outage causing the water transfer pump to shut down and the alarm system to fail. The water tanks overflowed releasing more than 25 barrels (bbl) of produced water. An unknown amount of produced water was recovered. All released fluids were contained within the firewall. The initial C-141 was submitted on September 12, 2017 and assigned remediation permit number 1RP-1568. Appendix A presents the initial C-141.

On November 13, 2007, a crude oil spill occurred due to failure of the free water knock out transferring all the produced fluids to the oil tanks, causing the oil tank to overflow and release 70 barrels (bbl) of crude oil. Approximately 65 bbl were recovered. The released fluids were contained within the firewall surrounding the tank battery. The spill was reported to the OCD (verbal notification with Mark Whitaker) on November 13, 2007. The initial C-141 was submitted on November 14, 2007 and assigned remediation permit number 1RP-1711. Appendix A presents the initial C-141.

On April 3, 2016, a produced water spill occurred due do a leak in a transfer line from the tank battery, releasing 100 barrels (bbl) of produced water. Approximately 80 bbl were recovered. The fluids predominately contained around the well head. The initial C-141 was submitted on April 3, 2016 and assigned remediation permit number 1RP-4231.

1.2 Physical Setting

The physical setting is as follows:

- The surface elevation is approximately 3,800 feet above mean sea level (msl);
- The topography slopes gently towards the southeast;
- There are no surface water features within 1,000 feet of the Site;
- The soils are designated as "Stegall loam, 0 to 1 percent slopes", consisting as 0 to 8 inches of loam underlain by 8 to 28 inches of clay loam;
- The surface geology is the Ogallala Formation (lower Pliocene to middle Miocene)- Alluvial and eolian deposits, and petrocalcic soils of the southern High Plains;
- Groundwater occurs in the Ogallala formation at approximately 57 feet below ground surface (bgs) (1991);
- The nearest fresh water well is located in Unit M (SW/4, SW/4), Section 11, Township 15 South, Range 37 East, about 0.5 miles southwest of the Site.

1.3 Recommended Remediation Action Levels

The recommended remediation action levels (RRAL) were calculated for benzene, BTEX and TPH based on the following criteria established by the OCD in *"Guidelines for Remediation of Leaks, Spills and Releases, pp.6-7, August 13, 1993"*:

Criteria	Result	Score
Depth-to-Groundwater	50 - 99 Feet	10
Wellhead Protection Area	No	0
Distance to Surface Water Body	>1,000 Horizontal Feet	0

The following RRAL apply to the release ranking score: 10

- Benzene 10 mg/Kg
- BTEX 50 mg/Kg
- TPH 1,000 mg/Kg

Depth to groundwater between 50 and 99 feet bgs require vertical delineation for chloride to 600 milligrams per kilogram (mg/Kg) and maintained a minimum of 5 feet farther in depth.

2.0 PRELIMINARY DELINEATION

On August 23, 2016, Environmental Plus, Inc. (EPI) collected soil samples from eight (8) locations (SSP1 through SSP8) outside of the firewall. The samples were collected at the surface (0' bgs) and to a depth of 6 inches bgs. The samples were analyzed for chloride by titration method. The following samples reported chloride levels above 600 mg/Kg:

- SSP1, 0' (4,000 mg/Kg)
- SSP1A, 6" (1,600 mg/Kg)
- SSP2A, 6" (2,400 mg/Kg)
- SSP3A, 6" (720 mg/Kg)

- SSP5, 0' (1,360 mg/Kg)
- SSP6, 0' (2,000 mg/Kg)
- SSP7 0' (4,000 mg/Kg)
- SSP7A 6" (2,000 mg/Kg)

On December 21, 2016, EPI mobilized a drilling rig to collect soil samples at five (5) locations within the firewall (SP1 through SP5). The samples were collected at depths of 40 feet bgs (SP1 and SP4) and 70 feet bgs (SP2, SP3, and SP5). A groundwater sample was collected at SP5 at a depth of 70 feet bgs. The soil samples were delivered under chain of custody and preservation to Cardinal Laboratories (Cardinal), in Hobbs, New Mexico and analyzed for BTEX (the sum of benzene, toluene, ethylbenzene and xylene), total petroleum hydrocarbons (TPH), including gasoline range organics (GRO) and diesel range organics (DRO), and chloride. All samples reported below the RRAL for TPH. Chloride reported above 600 mg/Kg at SP3 (672 mg/Kg). Appendix B presents EPI preliminary delineation data.

3.0 DELINEATION PLAN

LAI proposes to delineate all three spills concurrently. LAI proposes to collect soil samples at fourteen (14) locations within the spill areas. The samples will be collected at 1 foot intervals to approximately 4 feet bgs and 2 foot intervals to approximately 12 feet bgs using direct push technology (DPT) depending

on subsurface conditions. Additional samples will be collected in each cardinal direction (north, south, east and west) of the spill area at the same depth intervals for horizontal delineation. The soil samples will be delivered under chain of custody and preservation to XENCO Laboratories (XENCO) in Midland, Texas, and analyzed for benzene, toluene, ethylbenzne and xylenes (BTEX), total potential hydrocarbons (TPH), including gasoline range organics (GRO), diesel range organics (DRO) and oil range organics (ORO) and chloride by EPA SW-846 Methods 8021B, 8015M and 300 respectively. Pending laboratory results, further delineation may be required to reach cleanup level standards. Figure 3 presents a site map showing proposed soil sample locations. Appendix C presents photographs.

4.0 REMEDIAITON PLAN

Legacy will include a remediation plan in the delineation report to be submitted to the OCD upon receipt of the laboratory report.

Figures



Figure 1 - Topographic Map



Appendix A

Initial C-141

Division ancis Dr. 87505 Corrective Action Corrective Action ATOR Initial Report Final Report DANNY BROCK me No. 432-689-5219, MOBILE – 432-559-4556 Type CENTRAL BATTERY OUS Lease No. RELEASE ne Feet from the East/West Line County 1574076 ELEASE titude EAST COUNTY 1574076 ELEASE to of Release GREATER 25 Volume Recovered GREATER 25 C nd Hour of Occurrence Date and Hour of Discovery A S, To Whom? 9-10-07 8:00 AM 9-10-07 10:00 AM CY JOHNSON – OCD – HOBBS, NM CE 62 82 1.0 9 Note of Release GREATER 25 C Note of Release CREATER 25 C A Hour 9-10-07 11:00 AM S, Volume Impacting the Watercourse.				
8/505 Initial Report Final Report Corrective Action Initial Report Final Report DANNY BROCK Initial Report Final Report OUS Lease No. Initial Report Final Report GUS Lease No. East/West Line County Initial Report Final Report ELEASE East/West Line County Initial Report Final Report Finitial Report Final Report<				
RATOR DANNY BROCK me No. 432-689-5219, MOBILE – 432-559-4556 Type CENTRAL BATTERY OUS Lease No. RELEASE ine Feet from the 2275 EAST inude State Initial Report OUS Lease No. RELEASE inude ELEASE Initial Report Final Report OUS Lease No. RELEASE inude ELEASE Initial Report Feet from the 2275 The initial Report in				
DANNY BROCK me No. 432-689-5219, MOBILE – 432-559-4556 Type CENTRAL BATTERY OUS Lease No. RELEASE ne Feet from the East/West Line EAST Stude ELEASE te of Release GREATER 25 Volume Recovered GREATER 25 (nd Hour of Occurrence Date and Hour of Discovery A S, To Whom? 9-10-07 8:00 AM 9-10-07 10:00AM CY JOHNSON – OCD – HOBBS, NM CE 62 87 1.0 S, Volume Impacting the Watercourse. OWER WENT DOWN ON WATER TRANSFER PUMP, ALARM INED WITHIN FIREWALL. THE FIREWALL ALSO HAD				
one No. 432-689-5219, MOBILE – 432-559-4556 Type CENTRAL BATTERY OUS Lease No. RELEASE ine Feet from the 2275 ELEASE County2 15 14 15 76 itude County2 15 14 15 76 ELEASE County2 15 14 15 76 e of Release GREATER 25 Volume Recovered GREATER 25 (County2 15 14 15 76) nd Hour of Occurrence Date and Hour of Discovery Date and Hour of Discovery A S, To Whom? 9-10-07 8:00 AM 9-10-07 10:00AM County JOHNSON – OCD – HOBBS, NM County 2 10 00 AM County JOHNSON – OCD – HOBBS, NM Coc 82 1 10 00 AM S, Volume Impacting the Watercourse. County 2 10 00 AM COWER WENT DOWN ON WATER TRANSFER PUMP, ALARM OWER WENT DOWN ON WATER TRANSFER PUMP, ALARM OWER WENT DOWN ON WATER TRANSFER PUMP, ALARM COWER WENT DOWN ON WATER TRANSFER PUMP, ALARM				
OUS Lease No. RELEASE County 1 is in its 76 ine Feet from the 2275 East/West Line EAST County 1 is in its 76 itude				
RELEASE East/West Line County 15 1415 76 ine Feet from the 2275 EAST SLEA itude SEP SEP SEP itude SEP SEP Secovered GREATER 25 Volume Recovered GREATER 25 (Secovered) ind Hour of Occurrence Date and Flour of Discovery A S, To Whom? 9-10-07 8:00 AM 9-10-07 10:00AM Secovered) Corr Secovered GREATER 25 (Secovered) Secovered) Ind Hour 9-10-07 11:00 AM Secovered) Secovered) Secovered) S, Volume Impacting the Watercourse. Secovered) Secovered) Secovered) COWER WENT DOWN ON WATER TRANSFER PUMP, ALARM Secovered) Secovered) Secovered) COWER WENT DOWN ON WATER TRANSFER PUMP, ALARM Secovered) Secovered) Secovered) COWER WENT DOWN ON WATER TRANSFER PUMP, ALARM Secovered) Secovered) Secovered)				
RELEASE County2 13 14 10 76 ine Feet from the 2275 East/West Line EAST County2 13 14 10 76 itude SEP SEP SEP itude SEP SEP Sep ELEASE SEP Secovered GREATER 25 Secovered GREATER 25 / nd Hour of Occurrence Date and Flour of Discovery A S, To Whom? 9-10-07 8:00 AM 9-10-07 10:00AM Secovered GREATER 25 / Nd Hour 9-10-07 11:00 AM Secovered GREATER 25 / Secovered GREATER 25 / OWER WENT DOWN ON WATER TRANSFER PUMP, ALARM Secovered GREATER 25 / Secovered GREATER 25 /				
Ine Feet from the 2275 East/West Line EAST County 1010 for SLEA itude				
ELEASE Image: Construct of Construction of Constructing of Construction of Construction of Const				
A contraction of the contraction				
nd Hour of Occurrence Date and Four of Discovery S, To Whom? 9-10-07 8:00 AM 9-10-07 10:00AM SY JOHNSON – OCD – HOBBS, NM 9-10-07 10:00AM Ind Hour 9-10-07 11:00 AM S, Volume Impacting the Watercourse.				
nd Hour 9-10-07 11:00 AM S, Volume Impacting the Watercourse. OWER WENT DOWN ON WATER TRANSFER PUMP, ALARM INED WITHIN FIREWALL. THE FIREWALL ALSO HAD				
OWER WENT DOWN ON WATER TRANSFER PUMP, ALARM INED WITHIN FIREWALL. THE FIREWALL ALSO HAD				
INED WITHIN FIREWALL. THE FIREWALL ALSO HAD				
ESTORED TO PUMPS. ALSO THE ALARM WAS REPAIRED.				
AINED WITHIN THE FIREWALL. VACUUM TRUCK WERE ED TO DISPOSAL. AREA WILL BE CLEANED AND FRESH f my knowledge and understand that pursuant to NMOCD rules and ns and perform corrective actions for releases which may endanger D marked as "Final Report" does not relieve the operator of liability				
ination that pose a threat to ground water, surface water, human health elieve the operator of responsibility for compliance with any other				
OIL CONSERVATION DIVISION				
by District Superviso ENVIRONMENTAL ENGINEER				
Date: 9.17.07 Expiration Date: 11,16.07				
ns of Approval:				
ABMIT FINAL READER ANALLE ATTE BOUCHTE CHLORIDE CONTENT ON ALL ATTE SPILLS				

1023 N. French Dr., Hobbs, NW 88240	of New Mexico Form Ils and Natural Resources Revised October				
District III Oil Cons 1000 Rio Brazos Road, Aztec, NM 87410 1220 Sou District IV 1220 Sou	ervation Division hth St. Francis Dr. Fe, NM 87505	Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form			
	on and Corrective Action				
Release notification					
Name of Company Legacy Reserves Operating LP	OPERATOR Contact Danny M. Broc	Initial Report 🗌 Final Report			
Address P.O. Box 10848, Midland, TX 79702	Telephone No 432-689-5219.				
Facility Name J. M. Denton Battery	Facility Type Production				
Surface Owner Darr Angel Mineral Owner	various	Lease No. 16898			
LOCATIO	ON OF RELEASE				
Unit LetterSectionTownshipRangeFeet from theNorJ1115S37E1980		West Line County East Lea			
(52 ¹) Latitude33.02996	Longitude103.17116				
	E OF RELEASE				
Type of Release Oil Source of Release Oil tanks	Volume of Release 70. Date and Hour of Occurrence	Volume Recovered 65 Date and Hour of Discovery			
	11-13-07 9:00 AM	11-13-07 10:00 AM			
Was Immediate Notice Given?	d If YES, To Whom? d Mark Whitaker w/ OCD				
By Whom? Danny M. Brock		1:30 AM			
Was a Watercourse Reached?	If YES, Volume Impacting the Wa	tercourse. 1314157677			
🗋 Yes 🖾 No	NA	1:30 AM tercourse.			
If a Watercourse was Impacted, Describe Fully. NA*		NOV 2007 Second 222 Hobbs			
Describe Cause of Problem and Remedial Action Taken. * The dump failed on FWKO sending all produced fluids to the oil tank to recover discharge.	s causing tanks to overflow. Dumps on	FWKO were repaired and trucks used 5			
I hereby certify that the information given above is true and complete to regulations all operators are required to report and/or file certain release	eth? <i>kemove</i> considerant. Call the best of my knowledge and understanotifications and perform corrective ac	tamineted soil antil and that pursuant to NMOCD rules and tions for releases which may endanger			
public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedi or the environment. In addition, NMOCD acceptance of a C-141 report federal, state, or local laws and/or regulations.	ate contamination that pose a threat to g	round water, surface water, human health			
Signature: Dann M. Brock	OIL CONSERV	ATION DIVISION			
Printed Name Danny M. Brock	Approved by District Supervisor:	This Williams			
Title: Production Superintendent	Approval Date: 1/16/08	Expiration Date: 4/16/08			
E-mail Address: dbrock@legacylp.com	Conditions of Approval:	Attached 🔲			
Date: 11/14/07 Phone: 432-689-5219		· · · · · · · · · · · · · · · · · · ·			
* Attach Additional Sheets If Necessary	9	RP#1711			

٢


<u>,</u>,

04/04/2	2016 1	10:26				C		<u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u><u></u></u>	Salara ang ang ang ang ang ang ang ang ang an	P.004/00/
							RECEIVE	תי		
bistrict I 625 N. French	Dr., Hobbs	NM 88240		St	ate of N				nm An	r 05, 2016
listrict II 11 S. First St.,				Energy Mi	inerals ar	nd Nati	by Jneyes	sal I.JZ	рш, др	103, 2010
istrict III 000 Rio Brazos	-			Oil C	Conserva	ation Div	rision	Submit I Co	py to appropri	iate District Office
istrict IV	-		•			St. Franc		i.	accordance w	III 19.15.29 NiMA
220 S. SL PIRA	cis ur., sem	a Fe, NM 8750:				<u>NM 875</u>				
			Rele	ease Notific	cation	and Co	orrective A	ction		
					(OPERAT	TOR	In:	itial Report	🔲 Final Rep
		egacy Reserv	/es			ontact Jess				
Address P (Facility Nar						elephone M acility Typ	No. 432-853-353	5		
						acinty Typ				
Surface Ow	ner			Mineral C	Owner	****		API 1	No. 3002505	275
						OF REJ				
Unit Letter	Section	Township 15S	Range 37E	Feet from the 1980	North/S South	outh Line	Feet from the 1980	East/West Lin West	e County Lea	
	• •							11601		
		La	itude	33.029945		Longitu	de -103.17262	23		
				endela estimativativa)F REL		44004569889889889889888988988989899998989898		
Type of Rele	ase Produ	ced Water	. 1949 - 19 00 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900 - 1900	IAI			Release 100	Volum	e Recovered 8	30
Source of Re	lease Batte	ty					lour of Occurrenc			scovery 2:30PM
Was Immedi	ate Notice	Given?				2:30PM 4		4/3/16		
		E	Yes [] No 🔲 Not R	lequired	Left a voi				
By Whom?						and the second	lour 9:00 AM 4/	and the second		
Was a Water	course Rea	ched?	Yes 🖬	1-10	Í	If YES, Volume Impacting the Watercourse.				
Y.C		pacted, Desci		-			677.119/1611.pm/mm/mm/mm/mil/100/1777-777-777			***
II a Wateroot	1100 1100 111	ipacion, 19630		K 47 2 2						
		lem and Reme							************	
Transfer lin	e got a lea	k ,picked up e	xcess were	5T						
Describe Are	a Affected	and Cicanup	Action Ta	сеп.*						
		, and replace v								
				t is true and comp nd/or file certain t						
public health	or the env	ironment. The	e accoptan	co of a C-141 rep	ort by the	NMOCD m	arked as "Final R	cport" does not	relieve the op	erator of liability
thould their (operations l	have failed to	adequately	investigate and i	remediate	contaminat	ion that pose a the	cat to ground w	ater, surface v	vater, human healti
ecteral, state,	, or local is	ws and/or reg	ulations.	ptance of a C-141	i report dos	Co HOL FEHEV	ve the observed of	responsibility it	n compliance	with any other
			<u></u>	~~~~~~			OIL CON	SERVATIC	N DIVISI	ON
Signature:		f-						Λ	. 1911	
an - Malagaray	. C.			5	A	pproved by	Environmental S	pecialist:	m & lhye	
Printed Nam	e: Jesse Ga	rcia		*****		4		-		
Title: Forem	<u>en</u>			1941	A	pproval Da	ie: 04/05/2016	Expirati	on Date: 06/0)5/2016
E-mail Addr	ess: ioarnia	@legacylp.co	m		C	onditions	f Approval:			620234
M.11601 17001	was likena	weive aug 1p.00	(c)	1949 / 1994 (19 54 - 1957 - 195			amples only. De	lineate and	Attache	xd [] P 4231
Date: 4/3/	and the second sec			one:432-853-353:	5 rei	nediate per	· NMOCD guide	lines. Geotagge	ed (R)	. TLUI
Attach Addi	itional She	ets If Neces	sary		ph	otos of ren	ediation recom	nended.	nŤ	XK1609648622

nJXK1609648622 pJXK1609648696

D.004/004

Appendix B EPI Preliminary Delineation Data





EP	P.O. Bo 2100 Ave Eunice, N	onmental Plus, Inc. P.O. Box 1558 2100 Avenue O unice, NM 88231 (575) 394-3481 COMPANY: Legacy PROJECT NAME: JM Denton CTB															
	(575) 39 (575) 394-2		COMPAN	Y: Legacy	PR	OJECT	NAME: JM D	Denton CTB									
PROJECT MANAGE	R: Brandon E	Boone		FIELD TE	CHNICIAN: HE	RI GAY	TAN							8/23/16			
								CHLOR	DE ANALY	YSIS							
SAMPLE ID	SAMPLE DEPTH (FT)	COLLECT	ION TIME	PID ANALYSIS TIME PID REA		PID READING (PPM)			Titration Tube Reading		mg/Kg	-	SOIL DESCRIPTI	ON			
SSP1	Surface	9::	57				2 gms of soil	40 ml H2O	200	x 20 =	4000+						
SSP1A	6"	10:	05				2 gms of soil	40 ml H2O	80	x 20 =	1600						
SSP2	Surface	10:	15				2 gms of soil	40 ml H2O	28	x 20 =	560						
SSP2A	6"	10:	10				2 gms of soil	40 ml H2O	120	x 20 =	2400						
SSP3	Surface	10:	20				2 gms of soil	40 ml H2O	16	x 20 =	320						
SSP3A	6"	10:	30				2 gms of soil	40 ml H2O	36	x 20 =	720						
SSP4	Surface	10:	45				2 gms of soil	40 ml H2O	4	x 20 =	80						
SSP4A	6"	10:	55				2 gms of soil	40 ml H2O	20	x 20 =	400						
SSP5	Surface	11:	08				2 gms of soil	40 ml H2O	68	x 20 =	1360						
SSP5A	6"	11:	16				2 gms of soil	40 ml H2O	12	x 20 =	240						
SSP6	Surface	11:	24				2 gms of soil	40 ml H2O	100	x 20 =	2000						
SSP6A	6"	11:	38				2 gms of soil	40 ml H2O	28	x 20 =	560						
SSP7	Surface	1:1	15				2 gms of soil	40 ml H2O	200	x 20 =	4000+						
SSP7A	6"	1:2	24				2 gms of soil	40 ml H2O	100	x 20 =	2000						
SSP8	Surface	1::	31				2 gms of soil	40 ml H2O	4	x 20 =	80						
SSP8A	6"	1:4	46				2 gms of soil	40 ml H2O	20	x 20 =	400	I					
	 						2 gms of soil	40 ml H2O		x 20 =		 					
							2 gms of soil	40 ml H2O		x 20 =							
							2 gms of soil	40 ml H2O		x 20 =							
				PID CALIBI			8		}				WEATHER	1			
Time		Fresh	ı Air	Span Gas	Time		Fresh	ı Air	ļ	Span G	as	Time	Temp. Mis	c			
									ļ			 					
												I					
									ļ			I					
							<u> </u>		<u> </u>								



January 03, 2017

Daniel Dominguez Environmental Plus, Inc. P.O. Box 1558 Eunice, NM 88231

RE: JM DENTON TANK BATTERY

Enclosed are the results of analyses for samples received by the laboratory on 12/22/16 15:35.

Cardinal Laboratories is accredited through Texas NELAP under certificate number T104704398-16-8. Accreditation applies to drinking water, non-potable water and solid and chemical materials. All accredited analytes are denoted by an asterisk (*). For a complete list of accredited analytes and matrices visit the TCEQ website at www.tceq.texas.gov/field/ga/lab_accred_certif.html.

Cardinal Laboratories is accreditated through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2	Haloacetic Acids (HAA-5)
Method EPA 524.2	Total Trihalomethanes (TTHM)
Method EPA 524.4	Regulated VOCs (V1, V2, V3)

Accreditation applies to public drinking water matrices.

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Celey D. Keine

Celey D. Keene Lab Director/Quality Manager



Environmental Plus, Inc. Daniel Dominguez P.O. Box 1558 Eunice NM, 88231 Fax To: (505) 394-2601

Received:	12/22/2016	Sampling Date:	12/21/2016
Reported:	01/03/2017	Sampling Type:	Soil
Project Name:	JM DENTON TANK BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	UL-K SEC. 11, T15S, R37E		

Sample ID: SP 1 (40') (H602864-01)

BTEX 8021B	mg/	kg	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	12/29/2016	ND	2.06	103	2.00	1.01	
Toluene*	<0.050	0.050	12/29/2016	ND	2.16	108	2.00	0.806	
Ethylbenzene*	<0.050	0.050	12/29/2016	ND	2.12	106	2.00	0.955	
Total Xylenes*	<0.150	0.150	12/29/2016	ND	6.36	106	6.00	0.865	
Total BTEX	<0.300	0.300	12/29/2016	ND					
Surrogate: 4-Bromofluorobenzene (PID	131 %	6 73.6-14	0						
Chloride, SM4500Cl-B	mg/	kg	Analyze	d By: AC					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	144	16.0	12/28/2016	ND	416	104	400	0.00	
TPH 8015M	mg/	kg	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	12/27/2016	ND	186	93.0	200	6.66	
DRO >C10-C28	<10.0	10.0	12/27/2016	ND	189	94.4	200	6.77	
Surrogate: 1-Chlorooctane	94.7 \$	% 35-147	,						
Surrogate: 1-Chlorooctadecane	105 %	6 28-171							

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatscever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including whoto limitation, business interruptors, loss of growths incurred by client, its subsidiaries, affiliates or successor arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celeg D. Keine



Environmental Plus, Inc. Daniel Dominguez P.O. Box 1558 Eunice NM, 88231 Fax To: (505) 394-2601

Received:	12/22/2016	Sampling Date:	12/21/2016
Reported:	01/03/2017	Sampling Type:	Soil
Project Name:	JM DENTON TANK BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	UL-K SEC. 11, T15S, R37E		

Sample ID: SP 2 (70') (H602864-02)

BTEX 8021B	mg/	kg	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	12/29/2016	ND	2.06	103	2.00	1.01	
Toluene*	<0.050	0.050	12/29/2016	ND	2.16	108	2.00	0.806	
Ethylbenzene*	<0.050	0.050	12/29/2016	ND	2.12	106	2.00	0.955	
Total Xylenes*	<0.150	0.150	12/29/2016	ND	6.36	106	6.00	0.865	
Total BTEX	<0.300	0.300	12/29/2016	ND					
Surrogate: 4-Bromofluorobenzene (PID	129 9	73.6-14	0						
Chloride, SM4500Cl-B	mg/	kg	Analyze	d By: AC					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	176	16.0	12/28/2016	ND	416	104	400	0.00	
TPH 8015M	mg/	kg	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	12/27/2016	ND	186	93.0	200	6.66	
DRO >C10-C28	18.1	10.0	12/27/2016	ND	189	94.4	200	6.77	
Surrogate: 1-Chlorooctane	83.6	% 35-147							
Surrogate: 1-Chlorooctadecane	89.0	% 28-171							

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the sample identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celeg D. Keine



Environmental Plus, Inc. Daniel Dominguez P.O. Box 1558 Eunice NM, 88231 Fax To: (505) 394-2601

Received:	12/22/2016	Sampling Date:	12/21/2016
Reported:	01/03/2017	Sampling Type:	Soil
Project Name:	JM DENTON TANK BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	UL-K SEC. 11, T15S, R37E		

Sample ID: SP 3 (70') (H602864-03)

BTEX 8021B	mg/	kg	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	12/29/2016	ND	2.06	103	2.00	1.01	
Toluene*	<0.050	0.050	12/29/2016	ND	2.16	108	2.00	0.806	
Ethylbenzene*	<0.050	0.050	12/29/2016	ND	2.12	106	2.00	0.955	
Total Xylenes*	<0.150	0.150	12/29/2016	ND	6.36	106	6.00	0.865	
Total BTEX	<0.300	0.300	12/29/2016	ND					
Surrogate: 4-Bromofluorobenzene (PID	130 %	6 73.6-14	0						
Chloride, SM4500Cl-B	mg/	kg	Analyze	d By: AC					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	672	16.0	12/28/2016	ND	416	104	400	0.00	
TPH 8015M	mg/	kg	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	12/28/2016	ND	181	90.3	200	0.348	
DRO >C10-C28	<10.0	10.0	12/28/2016	ND	187	93.5	200	2.11	
Surrogate: 1-Chlorooctane	86.5 9	% 35-147							
Surrogate: 1-Chlorooctadecane	97.9 9	28-171							

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the sample identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celeg D. Keine



Environmental Plus, Inc. Daniel Dominguez P.O. Box 1558 Eunice NM, 88231 Fax To: (505) 394-2601

Received:	12/22/2016	Sampling Date:	12/21/2016
Reported:	01/03/2017	Sampling Type:	Soil
Project Name:	JM DENTON TANK BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	UL-K SEC. 11, T15S, R37E		

Sample ID: SP 4 (40') (H602864-04)

BTEX 8021B	mg/	kg	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	12/29/2016	ND	2.06	103	2.00	1.01	
Toluene*	<0.050	0.050	12/29/2016	ND	2.16	108	2.00	0.806	
Ethylbenzene*	<0.050	0.050	12/29/2016	ND	2.12	106	2.00	0.955	
Total Xylenes*	<0.150	0.150	12/29/2016	ND	6.36	106	6.00	0.865	
Total BTEX	<0.300	0.300	12/29/2016	ND					
Surrogate: 4-Bromofluorobenzene (PID	130 %	6 73.6-14	0						
Chloride, SM4500Cl-B	mg/	kg	Analyze	d By: AC					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	112	16.0	12/28/2016	ND	416	104	400	0.00	
TPH 8015M	mg/	kg	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	12/28/2016	ND	181	90.3	200	0.348	
DRO >C10-C28	<10.0	10.0	12/28/2016	ND	187	93.5	200	2.11	
Surrogate: 1-Chlorooctane	101 %	6 35-147							
Surrogate: 1-Chlorooctadecane	109 %	6 28-171							

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the sample identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celeg D. Keine



Environmental Plus, Inc. Daniel Dominguez P.O. Box 1558 Eunice NM, 88231 Fax To: (505) 394-2601

Received:	12/22/2016	Sampling Date:	12/21/2016
Reported:	01/03/2017	Sampling Type:	Soil
Project Name:	JM DENTON TANK BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	UL-K SEC. 11, T15S, R37E		

Sample ID: SP 5 (70') (H602864-05)

BTEX 8021B	mg/	kg	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	12/29/2016	ND	2.06	103	2.00	1.01	
Toluene*	<0.050	0.050	12/29/2016	ND	2.16	108	2.00	0.806	
Ethylbenzene*	<0.050	0.050	12/29/2016	ND	2.12	106	2.00	0.955	
Total Xylenes*	<0.150	0.150	12/29/2016	ND	6.36	106	6.00	0.865	
Total BTEX	<0.300	0.300	12/29/2016	ND					
Surrogate: 4-Bromofluorobenzene (PID	131 %	6 73.6-14	0						
Chloride, SM4500Cl-B	mg/	kg	Analyze	d By: AC					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	240	16.0	12/28/2016	ND	416	104	400	0.00	
TPH 8015M	mg/	kg	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	12/28/2016	ND	181	90.3	200	0.348	
DRO >C10-C28	<10.0	10.0	12/28/2016	ND	187	93.5	200	2.11	
Surrogate: 1-Chlorooctane	75.6 9	% 35-147							
Surrogate: 1-Chlorooctadecane	93.6 9	28-171							

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the sample identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celeg D. Keine



Notes and Definitions


S-06	The recovery of this surrogate is outside control limits due to sample dilution required from high analyte concentration and/or matrix interference's.
QM-07	The spike recovery was outside acceptance limits for the MS and/or MSD. The batch was accepted based on acceptable LCS recovery.
ND	Analyte NOT DETECTED at or above the reporting limit
RPD	Relative Percent Difference
**	Samples not received at proper temperature of 6°C or below.
***	Insufficient time to reach temperature.
-	Chloride by SM4500Cl-B does not require samples be received at or below 6°C
	Samples reported on an as received basis (wet) unless otherwise noted on report

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatscever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including whose shall be interruptors, loss of profits incurred by client, its subsidiaries, afflicate or successor arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celeg D. Keine



22

Page 8 of 8



January 03, 2017

Daniel Dominguez Environmental Plus, Inc. P.O. Box 1558 Eunice, NM 88231

RE: JM DENTON TANK BATTERY

Enclosed are the results of analyses for samples received by the laboratory on 12/22/16 15:35.

Cardinal Laboratories is accredited through Texas NELAP under certificate number T104704398-16-8. Accreditation applies to drinking water, non-potable water and solid and chemical materials. All accredited analytes are denoted by an asterisk (*). For a complete list of accredited analytes and matrices visit the TCEQ website at www.tceq.texas.gov/field/ga/lab_accred_certif.html.

Cardinal Laboratories is accreditated through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2	Haloacetic Acids (HAA-5)
Method EPA 524.2	Total Trihalomethanes (TTHM)
Method EPA 524.4	Regulated VOCs (V1, V2, V3)

Accreditation applies to public drinking water matrices.

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Celey D. Keine

Celey D. Keene Lab Director/Quality Manager



Environmental Plus, Inc. Daniel Dominguez P.O. Box 1558 Eunice NM, 88231 Fax To: (505) 394-2601

Received:	12/22/2016	Sampling Date:	12/21/2016
Reported:	01/03/2017	Sampling Type:	Water
Project Name:	JM DENTON TANK BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	UL-K SEC. 11, T15S, R37E		

Sample ID: SP 5 (70') (H602865-01)

BTEX 8021B	mg/	L	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifie
Benzene*	0.003	0.001	12/29/2016	ND	0.020	97.6	0.0200	0.138	
Toluene*	< 0.001	0.001	12/29/2016	ND	0.019	96.9	0.0200	0.00516	
Ethylbenzene*	< 0.001	0.001	12/29/2016	ND	0.020	100	0.0200	0.290	
Total Xylenes*	<0.003	0.003	12/29/2016	ND	0.059	98.2	0.0600	0.299	
Total BTEX	<0.006	0.006	12/29/2016	ND					
Surrogate: 4-Bromofluorobenzene (PID	100 %	6 73.7-14	6						
Chloride, SM4500Cl-B	mg/	L	Analyze	d By: AC					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifie
Chloride*	370	4.00	12/28/2016	ND	100	100	100	3.92	
TPH 8015M	mg/	L	Analyze	d By: MS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifie
GRO C6-C10	<1.00	1.00	12/31/2016	ND	45.1	90.2	50.0	2.12	
DRO >C10-C28	<1.00	1.00	12/31/2016	ND	46.8	93.6	50.0	1.65	
EXT DRO >C28-C35	<1.00	1.00	12/31/2016	ND	0.759		0.00		
Surrogate: 1-Chlorooctane	95.7 9	34.8-13	1						
Surrogate: 1-Chlorooctadecane	108 9	6 30.4-16	7						

Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the sample identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celez D. Keine



Notes and Definitions

QM-07	The spike recovery was outside acceptance limits for the MS and/or MSD. The batch was accepted based on acceptable LCS recovery.
ND	Analyte NOT DETECTED at or above the reporting limit
RPD	Relative Percent Difference
**	Samples not received at proper temperature of 6°C or below.
***	Insufficient time to reach temperature.
-	Chloride by SM4500Cl-B does not require samples be received at or below 6°C
	Samples reported on an as received basis (wet) unless otherwise noted on report


Cardinal Laboratories

*=Accredited Analyte

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatscever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including whose shall be interruptors, loss of profits incurred by client, its subsidiaries, afflicate or successor arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celeg D. Keine

Celey D. Keene, Lab Director/Quality Manager



Appendix C

Photographs



Site Location



Site Prior to Remediation Viewing North, September 14, 2017



Site Prior to Remediation Viewing East, September 14, 2017



Site Prior to Remediation Viewing North, September 14, 2017



Site Prior to Remediation Viewing Southeast, September 14, 2017



Site Prior to Remediation Viewing South, September 14, 2017



Site Prior to Remediation Viewing Southwest, September 14, 2017



Site Prior to Remediation Viewing West, September 14, 2017



Site Prior to Remediation Viewing Northeast, September 14, 2017