

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Matador Resources	Contact Catherine Green	
Address 500 N Main St Suite 1 Roswell NM 88201	Telephone No. 575-623-6601	
Facility Name Caudill # 002	Facility Type Oil Well	
Surface Owner	Mineral Owner	API No. 30-025-30406

### LOCATION OF RELEASE

Unit Letter L	Section 8	Township 16S	Range 37E	Feet from the 1980	North/South Line FSL	Feet from the 810	East/West Line FWL	County Lea
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	---------------

Latitude\_32.9348221\_\_\_ Longitude\_,-103.278389\_\_\_\_\_

### NATURE OF RELEASE

Type of Release overflow of produced water tank	Volume of Release ~56 barrels	Volume Recovered 35 barrels
Source of Release Recirculation pump	Date and Hour of Occurrence August 24, 2016	Date and Hour of Discovery August 24, 2016 9am
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Catherine Green	
By Whom? Rickie Anguiano	Date and Hour August 24, 2016 10am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*	<div><b>REVISED</b> 4:18 pm, Mar 23, 2018</div> <div>originally reviewed C-141 missing.</div>	

Describe Cause of Problem and Remedial Action Taken.\*Connection broke to water dump valve. Gas lost on treater, circulating pump pumped oil out of oil tank to treater putting excess fluid in water tank.

Describe Area Affected and Cleanup Action Taken.\*

Leak was contained in containment area. Excess fluid was vacuumed up and removed. Soil containing unsatisfactory levels of BTEX, DROs, and chlorides will be removed and replaced. See attached.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Catherine S Green	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Catherine Green	Approved by Environmental Specialist:	
Title: Regulatory Analyst	Approval Date: 8/26/2016	Expiration Date:
E-mail Address: cgreen@matadorresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: August 24, 2016, 2016 Phone: 575-623-6601		

\* Attach Additional Sheets If Necessary

1RP-4418

nKL1623928950

pKL1623929612