

Work Plan Fasken Oil and Ranch, Ltd. Denton SWD Release January 9, 2007 Unit D, Section 13, Township 15S, Range 37E Lea County, New Mexico

January 19, 2007



Prepared for:

Fasken Oil and Ranch, Ltd. 303 West Wall Suite 1800 Midland, Texas 79701-5116

By:

Safety & Environmental Solutions, Inc. 703 E. Clinton Suite 102 Hobbs, New Mexico 88240 (505) 397-0510

TABLE OF CONTENTS

I.	Company Contacts	. 1
II.	Purpose	.1
III.	Background	.1
	Groundwater	
	Action Plan	
٧.	Action Plan	. 1
VI.	Figures & Appendices	.1
	Figure 1 – Vicinity Map	2
	Figure 1 – Vicinity MapFigure 2 – Site Plan	3
	Appendix A – C-141	4
	Appendix A – C-141Appendix B – Site Photos	5

I. Company Contacts

Jimmy Davis	Fasken	432-818-0267	jimmyd@forl.com
Jimmy Carlile	Fasken	432-818-0210	jimmyc@forl.com
Lonnie Arnold	Fasken	432-687-1777	lonniea@forl.com
Bob Allen	SESI	505-397-0510	ballen@sesi-nm.com

II. Purpose

The purpose of this work plan is to propose a plan for the cleanup of the area identified affected by a produced water release at the Denton SWD Facility. The site is located in Unit D, Section 13, Township; 15S, Range 37E. The land is owned by Mr. Darr Angell.

III. Background

On January 9, 2007 the injection pump shut down and both high level alarms at the facility failed causing a release of produced fluids from the stock tank. Approximately 5800 barrels were released, of which 5275 were recovered. The release covered affected approximately 88,700 sq.ft. July 15, 2005 the Denton SWD facility release approximately 5,000 barrels of produced water due to an equipment malfunction.

According to Permian Production Chemical, an analysis of the produced water handled by this facility indicates a chloride concentration of 53,053 ppm.

IV. Groundwater

There are three existing monitor wells at the facility water level measurements were taken from these wells on September 1, 2006. The average depth of water in these wells was 56.85'.

V. Action Plan

Sufficient soil borings will be installed in the affected are to document the vertical extent of contamination. The affected area will then be excavated to the hard caliche layer. The excavated soil will be blended with clean soil adjacent to the affected area until representative samples indicate the chloride concentrations to be no greater than 1000 ppm. The blended soil will then be used to backfill the excavated. After backfill the area will be returned to natural grade and reseeded.

The above action plan does not include installation of a liner due to the fact that Fasken Oil & Ranch Ltd. is upgrading the containment system at the facility. An overflow pit measuring 180' X 90' will be installed at the facility and all berms will be raised to a height of 5'. These steps will insure any future releases will not breach the containment area.

VI. Figures & Appendices

Figure 1. - Vicinity Map Figure 2. - Site Plan Appendix A - C-141 Appendix B – Site Photos

Figure 1 Vicinity Map






Figure 2 Site Plan



Lat/Long WGS 1984





Denton SWD Release 1-9-(1/19/2007

1/19/2007 GPS Pathfinder®Office



Appendix A C-141

District 1
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brizzos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Sente Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Name of Company Fasken 0il and Ranch, Ltd. Contact Jimmy D. Carlile Address 303 W. Wall, Suite 1800 Midland, TX Telephone No. 432 687-1777 Facility Name Denton SWD Facility Type Salt Water Disposal Surface Owner Darr Angell Mineral Owner Face Lease No. LOCATION OF RELEASE Unit Letter Section Township Range D 13 158 37E Feet from the North/South Line Feet from the East/West Line County Lea Latitude Longitude NATURE OF RELEASE Type of Release Crude 0il/salt water Volume of Release 5800 Volume Recovered 5275 Source of Release Strock tank Date and Hour of Occurrence Date and Hour of Discovery If YES, To Whom? Z am 1/9/07 am 1/9/07 By Whom? Jimmy D. Carlile Date and Hour 1/9/07 9 am MST. Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a system is being designed and installed.	Final Repo		
Address 303 W. Wall, Suite 1800 Midland, TX Telephone No. 432 687-1777 Facility Name Denton SWD Facility Type Salt Water Disposal Surface Owner Darr Angell Mineral Owner Face Lease No. LOCATION OF RELEASE Unit Letter Section Township Range 13 158 37E Lease No. Latitude Longitude NATURE OF RELEASE Type of Release Crude oil/salt water Volume of Release 5800 Volume Recovered 5275 Source of Release Stock tank Date and Hour of Occurrence Date and Hour of Discovery If YES, To Whom? Jimmy D. Carlile Date and Hour 1/9/07 9 am MST. Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a	A		
Facility Name Denton SWD Facility Type Salt Water Disposal Surface Owner Darr Angel Mineral Owner Fee Lease No. LOCATION OF RELEASE Unit Letter Section Township Range 13 158 37E Feet from the North/South Line Feet from the Least/West Line County Lea Latitude Longitude NATURE OF RELEASE Type of Release Crude oil/salt water Volume of Release 5800 Volume Recovered 5275 Source of Release Stock tank Date and Hour of Occurrence Date and Hour of Discovery If YES, To Whom? 2 am 1/9/07 7 am 1/9/07 By Whom? Jimmy D. Carlile Date and Hour 1/9/07 9 am MST. Was a Watercourse Reached? Yes X No If a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
Surface Owner Darr Angel] Mineral Owner Fee Lease No. Location of Release Lease No.			
LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County Leas Latitude Longitude NATURE OF RELEASE Type of Release Crude oil/salt water Volume of Release 5800 Volume Recovered 5275 Source of Release Stock tank Date and Hour of Occurrence Date and Hour of Discovery If YES, To Whom? 2 am 1/9/07 7 am 1/9/07 By Whom? Jimmy D. Carlile Date and Hour 1/9/07 9 am MST Was a Watercourse Reached? Yes Yes No If YES, Volume Impacting the Watercourse. Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alarms reset. and new a	········		
Unit Letter Section Township Range 158 37E Feet from the North/South Line Feet from the Least Vest Line County Least Latitude Longitude Latitude Longitude			
Latitude Longitude NATURE OF RELEASE Type of Release Stock tank Volume of Release Stock tank Was Immediate Notice Given? Elycs No Not Required By Whom? Jimmy, D. Carlile Was a Watercourse Reached? Yes X No If a Watercourse was Impacted, Describe Fally.* NA Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
Latitude NATURE OF RELEASE Type of Release			
NATURE OF RELEASE Type of Release			
Type of Release Crude oil/salt water Volume of Release 5800 Volume Recovered 5275 Source of Release Stock tank Date and Hour of Occurrence Date and Hour of Discovery Was Immediate Notice Given? If YES, To Whom? Z am 1/9/07 / am 1/9/07 EYes No Not Required Larry Johnson By Whom? Jimmy D. Carlile Date and Hour 1/9/07 9 am MST Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
Source of Release Stock tank Date and Hour of Occurrence Darc and Hour of Discovery Was Immediate Notice Given? Was Immediate Notice Given? Was Immediate Notice Given? Was Immediate Notice Given? Was a Watercourse Reached? Was a Watercourse Reached? Was a Watercourse Reached? Was a Watercourse was Impacted, Describe Fally.* NA Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
Was Immediate Notice Given? Yes No Not Required If YES, To Whom? Z am 1/9/07 / am 1/9/07 Z am 1/9/07 / am 1/9/07 Larry Johnson	 5		
By Whom? Jimmy D. Carlile Date and Hour 1/9/07 9 am MST. Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
Was a Watercourse Reached? Yes M No If a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
Was a Watercourse Reached? Yes XX No If a Watercourse was Impacted, Describe Fally.* NA Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
If a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a	If YES, Volume Impacting the Watercourse.		
NA Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
Describe Cause of Problem and Remedial Action Taken.* Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
Both high level alarms failed as the injection pump went down. Alrams reset, and new a			
system is being designed and installed.	1 manuar		
	Tarm		
Describe Area Affected and Cleanup Action Taken.*			
• • • • • • • • • • • • • • • • • • • •			
600' by 70' estimated area outside of dike, meeting scheduled for 1/12/07 with environment company (on site) to determine plan of remdiation and cleanup.	mental		
company (on site) to determine plan of remdiation and cleanup.			
hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rule	5.4-7		
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for release which may and	s and		
public health of the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport" does not volume the acceptance of a C-141 report by the NMOCD marked as "Final Deport by the NMOCD marked as "Final De	inger		
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, huma or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any of	4 L II I L.		
federal, state, or local laws and/or regulations.	ability		
OIL CONSERVATION DIVISION	ability		
Signature Mully alle	ability		
	ability		
Printed Name: Jimmy D. Carlile Approved by District Supervisor:	ability		
Title: Regulatory Affairs Coor. Approval Date: Expiration Date:	ability		
E-mail Address: jimmyc@forl.com Conditions of Approval:	ability		
Attached L	ability		
ate: 1/11/07 Phone: 432 687-1777 tach Additional Sheets If Necessary	ability		

Appendix B Site Photos































