

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Marathon Oil Company	Contact Callie Karrigan
Address 5555 San Felipe St, Houston TX, 77056	Telephone No. 405-202-1028 (cell) 575-297-0956 (office)
Facility Name Pearsall 6 Federal #9	Facility Type Oil Well

Surface Owner BLM	Mineral Owner BLM	API No. 30-025-39135
-------------------	-------------------	----------------------

### LOCATION OF RELEASE

Unit Letter I	Section 6	Township 18S	Range 32E	Feet from the 1750	North/South Line South	Feet from the 1060	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude\_32.7741432\_\_\_\_\_ Longitude\_-103.8006287\_\_\_\_\_ NAD83

### NATURE OF RELEASE

Type of Release produced water	Volume of Release 28 bbls	Volume Recovered 25 bbls
Source of Release 3 to 2 inch reducer fitting at the base of the produced water tank	Date and Hour of Occurrence 6/28/2017	Date and Hour of Discovery 6/28/2017 4:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu/NMOCD, Shelly Tucker/BLM	
By Whom? Wendy Gram	Date and Hour 6/29/2017 10:40 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\* N/A


Describe Cause of Problem and Remedial Action Taken.\*

Approximately 28 bbls of produced fluids were released from a hole in the 3-inch to 2-inch fitting on the produced water tank because of internal corrosion. The release was contained in lined containment. Well was shut in and a crew was called to begin cleanup.

Describe Area Affected and Cleanup Action Taken.\*

Fluids were removed by vacuum truck and tanks and liner were pressure washed. Liner integrity inspection performed by third party and the liner was found to be impervious.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<b>OIL CONSERVATION DIVISION</b>	
Signature: <i>Callie Karrigan</i>		Approved by Environmental Specialist: 	
Printed Name: Callie Karrigan			
Title: HES Professional		Approval Date: <b>5/7/2018</b>	Expiration Date: <b>xx/xx/xxxx</b>
E-mail Address: cnkarrigan@marathonoil.com		Conditions of Approval:	
Date: 5/2/2018 Phone: 405-202-1028		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

1RP-4754







