

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company DCP Midstream LP	Contact Yvonne Blair
Address 5301 Sierra Vista, Carlsbad NM 88220	Telephone No. cell 575-361-2406
Facility Name BL-3	Facility Type Natural Gas Gathering Pipeline

Surface Owner: N <b>State</b> Annette McCloy	Mineral Owner: <b>State</b>	API No. N/A
--	-----------------------------	-------------

### LOCATION OF RELEASE

Unit Letter <b>F/G</b>	Section 10	Township 24S	Range 33E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------------	------------	--------------	-----------	---------------	------------------	---------------	----------------	------------

Latitude \_ 32.232300 \_ Longitude -103.560200

### NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release 455 MCF	Volume Recovered 0
Source of Release Pipeline	Date and Hour of Occurrence 04-23-18 3:00 PM	Date and Hour of Discovery 04-23-18 3:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**APPROVED**

**By Olivia Yu at 2:32 pm, May 10, 2018**

If a Watercourse was Impacted, Describe Fully.\* N / A

Describe Cause of Problem and Remedial Action Taken.\*

DCPM was notified of a possible line strike on 04/23/18 caused by a 3<sup>rd</sup> party company to the BL-3 DCP Midstream line. Natural Gas release into atmosphere. No liquids were present and lines were shut in by operators.

Describe Area Affected and Cleanup Action Taken.\*

DCPM construction crew repaired the BL-3 completed on 04/24/18 by replacing 1 joint of 40' steel pipe. The line was put back in service on 4/24/18. No field remediation was required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health, or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: *Yvonne Blair*

Printed Name: Yvonne Blair

Title: Compliance Coordinator

E-mail Address: [yblair@dcpmidstream.com](mailto:yblair@dcpmidstream.com)

Date: 05/09/18

Phone: 575-361-2406

Approved by Environmental Specialist: *oy*

Approval Date: **5/10/2018**

Expiration Date: **xx/xx/xxxx**

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary

**fOY1813052775**

**1RP-5054**

**nOY1813059775**

**pOY1813060067**

