

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

Initial only

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Monet Federal Com #003H Tank Battery	Facility Type: Tank Battery	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-42763

LOCATION OF RELEASE

Unit Letter C	Section 04	Township 25S	Range 33E	Feet from the 190	North/South Line North	Feet from the 1980	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude 32.16674599 Longitude -103.5793769

REVISED

1:12 pm, Jul 19, 2018

NATURE OF RELEASE

Type of Release: Oil (Fire)	Volume of Release: EST. 188 bbls Oil	Volume Recovered: 0 bbls
Source of Release: Flare	Date and Hour of Occurrence: December 6, 2017 8:00 am	Date and Hour of Discovery: December 6, 2017 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu NMOCD / Ms. Tucker BLM	
By Whom? Becky Haskell	Date and Hour: December 6, 2017 1:23 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 10:25 am, Dec 18, 2017



Describe Cause of Problem and Remedial Action Taken.*

The release/fire was caused by paraffin plugging the supply gas little joe regulator which caused the vessels to lose supply pressure to the dumps, sending fluid to the flare. The little joe regulator will be replaced and the lines cleared of paraffin.

Describe Area Affected and Cleanup Action Taken.*

The release/fire was contained in the firewall around the flare and all fluids burned. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel	Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 12/18/2017	Expiration Date:
E-mail Address: dneel2@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: December 14, 2017 Phone: 575-748-2010		

* Attach Additional Sheets If Necessary

nOY1735238080

1RP-5128

pOY1820048486