From: Yu, Olivia, EMNRD

To: Karrigan, Callie N. (MRO); Hernandez, Christina, EMNRD; rmann@slo.state.nm.us

Cc: <u>Heather Patterson</u>

Subject: RE: Marathon Oil Company - 1RP-4869 and 1RP-5003 Closure

Date: Wednesday, July 25, 2018 10:33:00 AM

Attachments: reviewed_1RP4869_1RP5003_Tonto 15 State #1 Closure Report.pdf

Good morning Ms. Karrigan:

Notes

- Please be advised that any deferral of a portion of the release area, even if the majority of the impacted area has been remediated, will not require a final C-141.
- Please note that under the new NMAC 19.15.29, to be in effect in August 2018, there will be no adjustment to the permissible levels left in place. For example, if <= 600 mg/kg chloride level is not obtained (+ 5% standard deviation or standard error not accepted), the excavated area must be laterally or vertically extended.
- In assessing depth to groundwater, please check USGS database.

NMOCD will agree that delineation has been completed for 1RP-4869 & 1RP-5003. However, several concerns regarding the remediation process:

- 1. Please demarcated clearly the areas represented by each of the delineation sample locations. Where are the borders among the differing depths of excavation? For example, the area represented by L1 is proposed for deferral, while the L2/L3 area has 1.75 ft removed. The transition edge/sidewall should confirmatory soil samples taken.
- 2. Was the elevated BTEX, TPH extended, and chlorides at 0.5 ft in the area represented by L1, at least surficially addressed through non-mechanical methods? Any areas to be deferred must be explicitly outlined on a scaled map for documentation.

NMSLO may have additional concerns.

Thanks, Olivia

From: Karrigan, Callie N. (MRO) < cnkarrigan@marathonoil.com>

Sent: Thursday, July 19, 2018 2:36 PM

To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; Hernandez, Christina, EMNRD

<Christina.Hernandez@state.nm.us>; rmann@slo.state.nm.us

Cc: Heather Patterson heather.patterson@soudermiller.com **Subject:** Marathon Oil Company - 1RP-4869 and 1RP-5003 Closure

Good afternoon,

Please see the attached closure documents for 1RP-4869 and 1RP-5003 prepared by SMA. Clean-up pictures are also attached.





