

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Michael Shoemaker
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-748-3371
Facility Name	Cockburn Fed 2	Facility Type	Oil
Surface Owner	Private	Mineral Owner	Federal
		API No	30-025-36282

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	10	18S	33E	660'	FSL	660'	FWL	Lea

Latitude: 32.7565918

Longitude: -103.6573715

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 140bbls	Volume Recovered 0bbls
Source of Release Produced Water Tank	Date and Hour of Occurrence May 31, 2017 @ 7:05 PM	Date and Hour of Discovery May 31, 2017 @ 7:05 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Olivia Yu, OCD	
By Whom? Ky Scott, Asst. Production Foreman	Date and Hour Shelly Tucker, BLM May 31, 2017 @ 9:07 PM Olivia Yu, OCD May 31, 2017 @ 9:05 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

APPROVED

By Olivia Yu at 10:33 am, Sep 05, 2018

Describe Cause of Problem and Remedial Action Taken.*

Lightning struck a 500bbl fiberglass produced water tank causing it to catch on fire and structurally compromising the tank. The wells were immediately shut in. Emergency services were contacted and the fire department was dispatched to the location and extinguished the fire. Approximately 140bbls produced water was in the tank when the lightning strike occurred. A vacuum truck recovered approximately 100bbls of produced water. All fluids stayed inside the earthen berm containment and on location.

Describe Area Affected and Cleanup Action Taken.*

The release was contained to the lined facility. The facility infrastructure was removed. Confirmation soil samples were taken. The impacted area was vertically/horizontally delineated and remediated by Talon/LPE per NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michael Shoemaker</i>	OIL CONSERVATION DIVISION	
Printed Name: Michael Shoemaker	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Professional	Approval Date: 9/5/2018	Expiration Date: xx/xx/xxxx
E-mail Address: mike.shoemaker@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/16/18 Phone: 575.748.3371	Like approval from BLM.	

* Attach Additional Sheets If Necessary

1RP-4725