From: Yu, Olivia, EMNRD

To: "zach.robbins@rxsoil.solutions"; rmann@slo.state.nm.us; stucker@blm.gov

Cc: "Jace Caraway"; "Kallus Jr,Ronnie J"; "Patrick Windham"; brokencirclecattle@gmail.com

Subject: RE: 1RP-4854, 1RP-4871 Proposed Work Plans Date: Tuesday, August 28, 2018 12:44:00 PM

Mr. Robbins:

Acknowledged. I did find the subsequent email with the inclusion of BLM. Thanks.

In regards to 1RP-4854, why was sample location S-15 established then, if not associated with the current release? If Swiftwater is not the Responsible Party, who holds the lease for this location or owns the flowlines adjacent to Pipeline Road? The impacted soil represented by S-15 still will require delineation and remediation activities.

Proposed remediation will not be addressed until additional delineation is completed for 1RP-4854.

1RP-4871 will be addressed in a separate email.

Thanks, Olivia

From: zach.robbins@rxsoil.solutions <zach.robbins@rxsoil.solutions>

Sent: Tuesday, August 28, 2018 11:21 AM

To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; rmann@slo.state.nm.us; stucker@blm.gov

Cc: 'Jace Caraway' < jace.caraway@rxsoil.solutions>; 'Kallus Jr,Ronnie J' < RKALLUS@travelers.com>;

'Patrick Windham' < PWindham@swiftwater.com>; brokencirclecattle@gmail.com

Subject: RE: 1RP-4854, 1RP-4871 Proposed Work Plans

Ms. Yu,

My apologies for not including the BLM on the initial email. I realized the omission and sent a separate email following the submittal to the NMOCD. I will be sure to include them on all communications and report submittals moving forward.

Delineation activities for 1RP-4854 include the initial delineation performed by Talon (posted on NMOCD website here) and the follow up delineation led by RXSoil described in the report, completed 6/6/18. This follow up was to address the stipulations given via email (here) for locations S-4 and S-5. Delineation was not continued on sample location S-15, as it was determined by Swiftwater that the area surrounding borehole location S-15 was not part of this release and therefore will not be addressed in this remediation plan.

Let me know if you require any further information.

Thank you, Zach

Zach Robbins I Technical and Engineering Analyst I RXSoil, Inc.

Cell: 210-400-7645 | zach.robbins@rxsoil.solutions

From: Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us>

Sent: Tuesday, August 28, 2018 10:33 AM

To: <u>zach.robbins@rxsoil.solutions</u>; <u>rmann@slo.state.nm.us</u>; <u>stucker@blm.gov</u>

Cc: 'Jace Caraway' < <u>jace.caraway@rxsoil.solutions</u>>; 'Kallus Jr,Ronnie J' < <u>RKALLUS@travelers.com</u>>;

'Patrick Windham' < PWindham@swiftwater.com; brokencirclecattle@gmail.com

Subject: RE: 1RP-4854, 1RP-4871 Proposed Work Plans

Good morning Mr. Robbins:

Please be advised that both these proposed workplans have release areas on Federal surface and Federal minerals. BLM must be included in all communications and report submittals.

Was additional delineation completed for 1RP-4854?

Thanks, Olivia

From: <u>zach.robbins@rxsoil.solutions</u> < <u>zach.robbins@rxsoil.solutions</u>>

Sent: Monday, August 6, 2018 2:13 PM

To: Yu, Olivia, EMNRD < <u>Olivia.Yu@state.nm.us</u>>; <u>mnaranjo@slo.state.nm.us</u>

Cc: 'Jace Caraway' < <u>iace.caraway@rxsoil.solutions</u>>; 'Kallus Jr,Ronnie J' < <u>RKALLUS@travelers.com</u>>;

'Patrick Windham' < PWindham@swiftwater.com; brokencirclecattle@gmail.com

Subject: 1RP-4854, 1RP-4871 Proposed Work Plans

Ms. Yu,

Attached are the proposed work plans for remediation projects 1RP-4854 and 1RP-4871. Please reach out with any questions. Thank you.

Best,

Zach

Zach Robbins I Technical and Engineering Analyst I RXSoil, Inc.

201 Main Street, Suite 1360, Fort Worth, Texas 76102

Cell: 210-400-7645

zach.robbins@rxsoil.solutions