

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443	
Facility Name: GC Federal #27	Facility Type: Battery	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 30-025-39264

LOCATION OF RELEASE

Unit Letter N	Section 20	Township 17S	Range 32E	Feet from the 990	North/South Line South	Feet from the 2200	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude: 32.8155708 Longitude: -103.7900696 NAD83

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 80 bbls PW; 0.25 bbls Oil	Volume Recovered: 78 bbls PW; 0 bbls Oil
Source of Release: Tank Overflow	Date and Hour of Occurrence: 1-20-2018	Date and Hour of Discovery: 1-20-2018 1:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu NMOCD & Shelly Tucker BLM	
By Whom? Dakota Neel	Date and Hour: 1-21-2018 10:17 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 1:34 pm, Jan 26, 2018

Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a transducer malfunctioned and caused the tank gauge to read the incorrect reading resulting in the tank overflow. The transducer has been replaced.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. A vacuum truck was dispatched to recover all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

[Signature]

Signature:

Printed Name: Dakota Neel

Title: HSE Coordinator

Approval Date:

1/26/2018

Expiration Date:

E-mail Address dneel2@concho.com

Conditions of Approval:

Attached ☐

Date: 1-24-2018

Phone: 575-746-2010

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

* Attach Additional Sheets If Necessary

1RP-5258

REVISED

3:42 pm, Nov 05, 2018

nOY1802648272

pOY1830956441