District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

1

Incident ID	NCH1836251271
District RP	1RP-5295
Facility ID	
Application ID	pCH1836251636

Release Notification

Responsible Party

Responsible Party	BTA Oil Producers	OGRID <u>260297</u>	
Contact Name Ben Grimes		Contact Telephone (432) 682-3753	
Contact email	bgrimes@btaoil.com	Incident # NCH1836251271 ROJO AE 7811 JV-P	
Contact mailing address 104 S. Pecos St., Midland, TX 79701 FED 001H @ 30-025-43476			

Location of Release Source

Latitude 32.107610

Longitude -103.56410 (NAD 83 in decimal degrees to 5 decimal places)

Site Name Rojo AE 7811 JV-P Fed 001H (closest well)	Site Type Tank Battery
Date Release Discovered 12/02/2018	API# (if applicable) 30-025-43476

Unit Letter	Section	Township	Range	County	
D	27	25S	33E	Lea	

Surface Owner: State Federal Tribal Private (Name: _

Nature and Volume of Release

Volume Released (bbls) 350	BBL Volume Recovered (bbls) 200 BBL
Volume Released (bbls) 3	BBLVolume Recovered (bbls)20 BBL
Is the concentration of dissolved chlor produced water >10,000 mg/l?	de in the Yes No
Volume Released (bbls)	Volume Recovered (bbls)
Volume Released (Mcf)	Volume Recovered (Mcf)
Volume/Weight Released (provide u	ts) Volume/Weight Recovered (provide units)
	Volume Released (bbls) 35 Is the concentration of dissolved chloriproduced water >10,000 mg/l? Volume Released (bbls)

Cause of Release

A dump valve froze into a closed position on the separator, causing the vessel to pressure up and the high pressure relief valve (pop-off) to open to prevent rupture of the vessel and the incoming lines.

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	


Was this a major release as defined by	If YES, for what reason(s) does the responsible	party consider this a major release?		
19.15.29.7(A) NMAC?				
Yes 🗌 No	The spill volume was greater than 25 BB	L, which the NMOCD Rules define as a major release.		
If YES, was immediate no	otice given to the OCD? By whom? To whom?	When and by what means (phone, email, etc)?		
	Email sent to Shelly Tucker, BLM, and Christina Hernandez, NMOCD, by Michael Alves, Cajun Energy, on 12/2/2018 at 9:02 PM.			
	Initial Resp	onse		
The responsible p	party must undertake the following actions immediately unle	ss they could create a safety hazard that would result in injury		
The source of the rele	ease has been stopped.			
The impacted area ha	as been secured to protect human health and the e	nvironment.		
V Released materials ha	ave been contained via the use of berms or dikes,	absorbent pads, or other containment devices.		
M All free liquids and re	ecoverable materials have been removed and ma	naged appropriately.		
If all the actions described	d above have <u>not</u> been undertaken, explain why:			
Per 19.15.29.8 B. (4) NM	IAC the responsible party may commence remec	iation immediately after discovery of a release. If remediation		
has begun, please attach	a narrative of actions to date. If remedial effor	ts have been successfully completed or if the release occurred attach all information needed for closure evaluation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Printed Name: Ben Gr	rimes T	itle: Production Manager		
Signature: Ben	T	ate: <u>12141 18</u>		
email:bgrime	es@btaoil.com Te	lephone: (432) 682-3753		
OCD Only				
Received by:	Da	te:		

If YES, for what reason(s) does the responsible party consider this a major release?

Release Notification for 12/2/2018 Incident

Calculations for Rojo AE 7811 JV-P Federal 001H (nearest well)

• The impacted area outside of the tank battery containment was calculated as follows:



- Plus: 220 BBL was contained and recovered from the tank battery secondary containment area.
- Plus: Estimated 25 BBL fluid remains inside secondary containment spread across the top of the tanks, vessels and piping.

Total volume reported: 385 BBL

At 10% Water Cut, Volumes in this Release Notification estimate are:

Crude Oil: 350 BBL

Produced Water: 35 BBL