

# State Of New Mexico

## Energy, Minerals and Natural Resources Department

**Michelle Lujan Grisham**

Governor

**Sarah Cottrell Propst**


Cabinet Secretary

**Todd E. Leahy, JD, PhD**

Deputy Cabinet Secretary

**Adrienne Sandoval**

Division Director



### **"Response Required - Deadline Enclosed"**

*Field Inspection Program  
"Preserving the Integrity of Our Environment"*

28-Dec-20

**ARMSTRONG ENERGY CORP**

P.O. Box 1973

Roswell, NM 88202

**LETTER OF VIOLATION - Field Inspection**

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### ***INSPECTION DETAIL SECTION***

[30-025-36408] BUDDY 9 #001

OGRID: 1092

K-09-16S-37E 2085 FSL 2055 FWL

|                        |                        |                     |                                 |                       |
|------------------------|------------------------|---------------------|---------------------------------|-----------------------|
| <b>Inspection Date</b> | <b>Type Inspection</b> | <b>Inspector</b>    | <b>Corrective Action Due By</b> | <b>Inspection No.</b> |
| 12/9/2020              | Routine Inspection     | [EZB] Eugene Bolton | 3/31/2021                       | iEZB2034445990        |

**Violations:**

**Rule**

19.15.29 Releases

**Violation**

Surface  
Leaks/Spills

**Comment:**

Potential breach at floor bottom interface with ground from 1 to 3 crude tanks, appears long-term release under underneath. Any release above 5 bbl threshold requires form C-141.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Eugene Bolton, Compliance Ofc.

Hobbs OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.