

Submit 1 Copy To Appropriate District Office

State of New Mexico  
Oil, Gas, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD

JUN 19 2012

CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

WELL API NO. 30-025-10768
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 546440
7. Lease Name or Unit Agreement Name New Mexico BZ State NCT 8
8. Well Number 10
9. OGRID Number 873
10. Pool name or Wildcat Langlie Mattix; Eunice North Blinbry-Tubb Drinkard Tros; Q,GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well  Gas Well  Other

2. Name of Operator  
Apache Corporation

3. Address of Operator  
303 Veterans Airpark Lane, Ste 3000, Midland TX 79705

4. Well Location  
Unit Letter P : 660 feet from the South line and 660 feet from the East line  
Section 16 Township 23-S Range 37-E NMPM Lea County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3304' DR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- DOWNHOLE COMMINGLE
- PLUG AND ABANDON
- CHANGE PLANS
- MULTIPLE COMPL

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING/CEMENT JOB
- ALTERING CASING
- P AND A

OTHER:

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 5/25/12 P&A Equipment to location. 5/29/12 Notify Mark (OCD) of P&A intent. RU RIH w/gauge ring tag @ 3360'. Notify Randy Hunter. CIBP was set @ 3360'. POH with gauge ring. RIH w/2-3/8 tbg tag CIBP @ 3360'
- 5/30/12 Load Well pressure test casing to 500 psi 10 min ok. Circulate well w/54bbls MLP @ 3360' Spot 25x class "c". PUH to 2867' Spot 35x class "c". Woc 4 hrs. Open well 0 psi RIH tag toc @ 2350'. PUH to 1200'. Spot 25x class "c" POH w/ 15 stands woc overnite.
- 5/31/12 Open well 0 psi. RIH tag toc @ 828' PUH to 300' spot 20x class "c" to surface. LD all W.S. ND BOP. Rig down pulling unit and all P&A equip. Cutoff wellhead, anchors and clean location. Install dryhole marker.

Spud Date:

[Empty box for Spud Date]

Rig Release Date:

[Empty box for Rig Release Date]

Approved for plugging of well bore only.  
Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Form: www.oemnr.state.nm.us/oed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Jimmy Bagley*

TITLE

Manager

DATE

4/23/12

Type or print name

Jimmy Bagley

E-mail address:

PHONE:

432-561-8600

For State Use Only

APPROVED BY:

*Maley Brown*

TITLE

Compliance Officer

DATE

6/19/2012

Conditions of Approval (if any):

JUN 20 2012