

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-25594
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: A.L. Christmas(NCT-C)
8. Well No. 11
9. Pool name or Wildcat Blinebry

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator
 Chevron USA, Inc.

3. Address of Operator
 15 Smith Rd. Midland, Tx 79705

4. Well Location
 Unit Letter H : 1780 feet from the North line and 810 feet from the East line
 Section 18 Township 22-S Range 37-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)


11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Notify OCD 24 hrs prior to MI &RU
2. Set 5 1/2 CIBP @ 5375, spot 25sx 5375-5175(Blinebry)WOC Tag.
3. Displace hole w/mlf, 9.5 # Brine w/25# Gel P/BBL.
4. Spot 40sx plug 3300-2900(Queen,DV-Tool)
5. Spot 35sx plug 2800-2500(Yates, B-salt)WOC Tag.
6. Spot 30sx plug 1200-950(8 5/8 shoe, T-salt)WOC Tag.
7. Perf 4 holes @ 300 circ 90sx plug 300-surf 5 1/2X 8 5/8 to insure cmt behind 5 1/2 was circ to surf.
If unable to pump into perfs, Fill 5 1/2 csg w/30sx plug 300-surf(WOC Tag).
8. Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE G.R. Bledsoe TITLE HES Specialist DATE 5/16/2003

Type or print name G.R. Bledsoe Telephone No. 915-687-7153

(This space for State use)
 APPROVED BY Gary W. Wink TITLE OCD FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAY 21 2003

Conditions of approval, if any.