

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

RECEIVED APR 03 2013 HOBBS OCE		WELL API NO. 30-025-40922
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>		6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name PADUCA BREAKS 32 26 32 STATE		8. Well Number 1H
9. OGRID Number 4323		10. Pool name or Wildcat JENNINGS; BONE SPRING, UPPER SHALE
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3101' GR		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input checked="" type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input checked="" type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please find work performed from 3/19/2013 through 4/01/2013.

3/19/2013:

HELD PJSM WORKING ON HEATER TREATER AND FWKO, RUN LINE FROM SEPERATOR TO FWKO, AND SET VOLUME POTS.

3/20/2013:

HELD PJSM, PULL OUT TANKS AND SET TO SIDE, WORK ON VESSELS AND BEGIN TO LAY LINES TO TANKS.

(CONT. PAGE 2)

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Bryan Arrant

TITLE Regulatory Specialist II

DATE 04/02/2013

Type or print name Bryan Arrant (Agent)

E-mail address: bryan.arrant@chk.com

PHONE: (405)935-3782

For State Use Only

APPROVED BY:

El B...

TITLE

Dist. Mgr

DATE

4-9-2013

Conditions of Approval (if any):

APR 09 2013

PADUCA BREAKS 32 26 32 STATE 1H
UNIT A, SEC. 32, T-26-S R-32-E
LEA CO., NM
30-025-40922

((WORK HISTORY))

3/21/2013:

HELD PJSM, SET HEADER AND RUN LINE TO SEPERATOR FROM HEADER, DELIVER COMBUSTOR TO LOCATION AND SET. DELIVER METER RUNS AND SET.

3/22/2013:

HELD PJSM SET COMBUSTOR AND BEGIN TO HOOK UP,WORK ON BURNER ON HEATER.

3/25/2013:

HELD PJSM SET NEW TANKS AND INSTALL LANDING AND LADDER, BEGIN TO INSTALL CONNECTIONS

3/26/2013:

HELD PJSM HOOK UP VENT LINES ON TANK AND FILL LINE FROM VRT, HOOK UP ALL GAS SUPPLY TO DUMPS AND RUN MAKE UP GAS LINE TO HEATER AND FWKO.

3/27/2013:

HELD PJSM, CONTINUE TO WORK ON PLUMBING UP TANKS. FINISH BURNER ON HEATER.

3/28/2013:

HELD PJSM,WORK ON GAS SUPPLY LINES TO FWKO AND HEATER. INSTALL LINE TO COMBUSTOR FROM TANKS.

4/01/2013:

HELD PJSM, BEGIN TO DIG HOLES FOR CORNER POST AND H BRACES. RUN STAINLESS STEEL LINES TO IGNITOR ON COMBUSTOR.