Submit I Copy To Appropriate District Office District 1 – (575) 393-6161 State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised August 1, 2011
1625 N. French Dr., Hobbs. NM 88240 A 2013	WELL API NO.
District 11 – (575) 748-1283 APR 3 0 2013 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-33753
District III ~ (505) 334-6178 1220 South St Francis Dr	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 RECEIVED District IV – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name LEA AQ STATE
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well D Other	8. Well Number
2. Name of Operator CIMAREX ENERGY CO. OF COLORADO	9. OGRID Number 162683
3. Address of Operator	10. Pool name or Wildcat
600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701	PEARL SAN ANDRES, WEST
4. Well Location Unit Letter C : 620 feet from the NORTH line and	1700 feet from the WEST line
Section 32 Township 19S Range 35E	
11. Elevation (Show whether DR, RKB, RT, GR, etc.	<i></i>
3728' - GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK D PLUG AND ABANDON X REMEDIAL WOR	·
— — — — — — — — — — — — — — — — — — — —	
PULL OR ALTER CASING	ТЈОВ
OTHER: OTHER:	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 	
 SET 5-1/2" CIBP @ 5,650'; PUMP 55 SXS. CMT. @ 5,650'-5,225' (T/S.A.); CIRC. WELL W/ PXA FLUID. PUMP 25 SXS. CMT. @ 3,350'-3,215' (T/YATES X B/SALT); WOC X TAG CMT. PLUG. 	
3) PUMP 25 SXS. CMT. @ 1,860'1,745' (T/SALT); WOC X TAG CMT. PLUG.	
 MIX X CIRC. TO SURF. 65 SXS. CMT. @ 500'-3' (8-5/8" CSG.SHOE). DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER. 	
5) DIG OUT X COT OTT WEELNERD 5 D.C.E., WEED ON STELETERTE TO CSGS. X INSTRUE DRT HOLE MARKER.	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge	e and belief.
\sim . O	
SIGNATURE DALEA TITLE: AGENT DATE: 04/23/13	
Type or print name: DAVID A. EYLER E-mail address: <u>deyler@milagro</u>	res.com PHONE: 432.687.3033
$\neg \land \land$	OW $E/-/$
APPROVED BY: / VIany A Mown TITLE COM Mance) (JACCED DATE] / 2/2013
Conditions of Approval (if any)	
24 hours prior to the beginning of Plugging Operations begin V	
MAY 0-2 2013	

-



