HYDROGEN SULFIDE (H2S) CONTINGENCY PLAN MOBBS OCN HAMON FED COM A #2H

Assumed 100 ppm ROE = 3000'

JAN 2 4 2014

100 ppm H2S concentration shall trigger activation of this plan.

RECEIVED

This is an open drilling site. H₂S monitoring equipment and emergency response equipment will be rigged up and in use when the company drills out from under surface casing. H₂S monitors, warning signs, wind indicators and flags will be in use.

- A. All personnel shall receive proper H2S training in accordance with Onshore Order 6 III.C.3.a
- B. Briefing Area: Two perpendicular areas will be designated by signs and readily accessible.
- C. Required Emergency Equipment:
 - Well control equipment •
 - a. Flare line 150' from wellhead to be ignited by flare gun.
 - b. Choke manifold with a remotely operated choke.
 - c. Mud/Gas Separator.
 - Protective Equipment for essential personnel. Breathing apparatus:
 - a. Rescue Packs (SCBA) 1 unit shall be placed at each briefing area. 2 units shall be stored in the safety trailer.
 - b. Work/Escape packs 4 packs shall be stored on the rig floor with sufficient air hose not to restrict work activity.
 - c. Emergency Escape Packs 4 packs shall be stored in the doghouse for emergency evacuation.

Auxiliary Rescue Equipment:

- a. Stretcher
- b. Two OSHA full body harness
- c. 100 ft. 5/8" OSHA approved rope
- d. One 20# class ABC fire extinguisher
- H2S detection and monitoring Equipment:

The stationary detector with three sensors will be placed in the upper doghouse, set to visually alarm @ 10 ppm and audible @ 14 ppm. Calibrate a minimum of every 30 days or as needed. The sensors will be placed in the following places: Rig floor, Bell nipple, end of flare line or where well bore fluid is being discharged (Gas sample tubes will be stored in the safety trailer).

- Visual warning systems.
 - a. One color code condition sign will be placed at the entrance to the site reflecting the possible conditions at the site.
 - b. A colored condition flag will be on display, reflecting the current condition, at the drilling site.
 - c. Two wind socks will be placed in strategic locations being visible from all angles.

• Mud Program:

The mud program has been designated to minimize the volume of H2S circulated to surface. The operator will have the necessary mud products to minimize hazards while drilling in H2S bearing zones.

- Metallurgy:
 - a. All drill strings, casings, tubing, wellhead, blowout preventer, drilling spool, kill lines, choke manifold and lines, shall be suitable for H2S service.
 - b. All elastomers used for packing and seals shall be H2S trim.
- Communication:

Communication will be via two way radio in emergency and company vehicles. Cell phones and land lines where available.

H₂S Operations

۲

Though no H_2S is anticipated during the drilling operation, this contingency plan will provide for methods to ensure the well is kept under control in the event an H_2S reading of 100 ppm or more are encountered. Once personnel are safe and the proper protective gear is in place and on personnel, the operator and rig crew essential personnel will ensure the well is under control, suspend drilling operations and shut-in the well (unless pressure build up or other operational situations dictate suspending operations will prevent well control), increase the mud weight and circulate all gas from the hole utilizing the mud/gas separator downstream of the choke, the choke manifold and the emergency flare system located 150' from the well. Bring the mud system into compliance and the H_2S level below 10 ppm, then notify all emergency officers that drilling ahead is practical and safe.

Proceed with drilling ahead only after all provisions of Onshore Order 6, Section III.C. have been satisfied.

Ignition of Gas source

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO₂). Intentional ignition must be coordinated with the NMOCD and local officials. Additionally the NM State Police may become involved. NM State Police shall be the Incident Command on scene of any major release. Take care to protect downwind whenever this is an ignition of the gas.

Common	Chemical	Specific	Threshold	Hazardous	Lethal
Name	Formula	Gravity	Limit	Limit	Concentration
Hydrogen Sulfide	H₂S	1.189 Air = l	10 ppm	100 ppm/hr	600 ppm
Sulfur Dioxide	SO ₂	2.21 Air = I	2 ppm	N/A	1000 ppm

Characteristics of H₂S and SO₂

Contacting Authorities

Legacy Reserves Operating's personnel must liaison with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such as type and volume of release, wind direction, location of release, etc. Be prepared with all information available including directions to site. The following call list of essential and potential responders has been prepared for use during a release. (Operator Name)'s response must be in coordination with the State of New Mexico's "Hazardous Materials Emergency Response Plan" (HMER).

Emergency Assistance Telephone List

L

PUBLIC SAFETY:			911 or	
Lea County Sheriff or Police			(575) 396-3611	
Fire Department			(575) 397-9308	
Hospital			(575) 492-5000	
Ambulance			911	
Department of Public Safety			(392) 392-5588	
Oil Conservation Division			(575) 748-1823	
New Mexico Energy, Minerals & Natural Resources Departme	ent		(575) 748-1283	
LEGACY RESERVES OPERATING LP				
Legacy Reserves Operating LP	Offic	Ce	(432) 689-5200	
Legacy Reserves Operating Li	Olin			
Drilling Manager:	Offic	~	(432) 689-5200	
Mike Parrish	Cell		(432) 664-2150	
Mike Partish	Cell		(432) 004-2150	
Senior Engineer	Offic	~~	(433) 690 5300	
Senior Engineer:			(432) 689-5200	
Blain Lewis	Cell		(432) 230-7450	
Operations Manager:	Office	(43	2) 689-5200	
Ernie Hanson	Cell (Cell (432) 230-9009		
Evenutive Vice President of Operations	Offic	~~	(422) 690 5200	
Executive Vice President of Operations Paul Horne	Onic	e	(432) 689-5200	
Safety Coordinator	Offic	ce	(432) 689-5200	
Randy Williams	Cell	1	(432) 260-5566	
Drilling Contractor – Patriot Drilling rig #5				
Tool Pusher:				
Donny Boatright	Cell		(575) 390-3721	
Relief Tool Pusher:				
Kenny Hayes	Cell		(575) 631-4554	
Drilling Manager:	Offic	~~	(432) 686-2780	
			(432) 889-8884	
Leroy Peterson	Cell		(432) 009-0004	
LEGACY SAFETY	Hobb	s	(575)	393-
7233				
Field Operations Manager:				
Buddy Boydston	Cell	(57	5) 631-0820	
	- 411	(01)	-,	
Operations Manager:				
Danny Owens	Cell	((575) 605-6715	
,				

Evacuee Description: Residents: THERE ARE NO RESIDENTS WITHIN 3000' ROE.



