

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-08508
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 27821
7. Lease Name or Unit Agreement Name: State B
8. Well Number 2
9. OGRID Number 162928
10. Pool name or Wildcat Townsend; Perno Upper Perm

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM 1088) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	FEB 14 2014
2. Name of Operator Energen Resources Corporation	
3. Address of Operator 3300 North A St., Bldg. 4, Ste. 100, Midland, TX 79705	RECEIVED
4. Well Location Unit Letter O : 3690 feet from the South line and 2200 feet from the East line Section 1 Township 16S Range 35E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3974'	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See attached P&A procedure.

THANK YOU!

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Brenda F Rathjen TITLE Regulatory Analyst DATE 02/13/2014
Type or print name Brenda F Rathjen E-mail address: brenda.rathjen@energen.com PHONE 432/688-3323

For State Use Only

APPROVED BY Mary S Brown TITLE Compliance Officer DATE 2/14/2014
Conditions of Approval (if any):

FEB 18 2014

State B #2
Fee Lease No. 27821
API 30-025-08508
Energen Resources Corporation - OGRID #162928

HOBBS OCD

FEB 14 2014

RECEIVED

P & A Procedure:

1/28/14 - MIRU Rig. Started RIH w/tubing.

1/29/14 - RIH w/tubing. Tag CIBP @ 10,501'. Circ 90 bbl MLF. Spot 35sx "H" on CIBP. Start POOH. SI. SDON.

1/30/14 - Opened well, no PSI. POOH w/tbg. RIHWL, perf @ 7425'. Start RIH w/tailpipe, packer & tbg. SI. SDON.

1/31/14 - Finish RIH. Loaded hole, set packer @ 7066', RU pump. Pump 35sx "C" & displaced. During displacement got a rock in valve of pump. Tore down, removed rock (40 min). Got back in pump, cement flash set. Tried working cement, tried to reverse cement, no luck. POOH w/tbg. SI. SDFWE.

2/03/14 - RIH w/tbg & packer, loaded hole & set pkr @ 7066'. Tried to pump in perfs to 1500#, no rate. Dropped down to 7495', spot 25sx "H", displaced cement. PUH. SI. SDON.

2/04/14 - Open well. RIH & tag cement @ 7179'. RIHWL & perf @ 4725'. POOH. RIH w/pkr to 4226'. RU pump & loaded hole. Set pkr, test perfs to 1500#, no leakoff. Release pkr. POOH. SI. SDON.

2/05/14 - Finish POOH w/tbg. ND BOP, pull out 8-5/8" pkr, NU BOP. RIH to 4820'. Loaded hole, spot 60sx "C" cement & displaced to 4750'. SI. SDON to WOC.

2/06/14 - RIH & tag cement @ 4351'. RIHWL & perf @ 2750'. RIH to 2509' w/pkr. Loaded hole, set pkr, PSI perfs to 1500#, no pressure loss. Unset pkr, dropped down to 2806' per Maxey Brown @ NMOCD, spot 50sx "C" & displaced to 2640'. LD tbg. SI. SDON to WOC.

P/A'd → 2/07/14 - Opened well, no PSI. Tag cement @ 2580'. PU & perf @ 1900'. RIH w/pkr & tbg to 1651'. Loaded hole, set pkr, tested perfs to 1500#, no leakoff. Dropped down to 1948', spot 50sx "C" w/3% CaCl & displaced. POOH. WOC 4 hrs. RIH & tag cement @ 1721'. PU & perf @ 400'. RIH w/pkr, loaded hole, set pkr & tested perfs to 1500#, no leakoff. POOH w/pkr. RIH to 462' and circ cement to surf w/140sx. ND BOP, topped off well, wash up BOP & tbg. RDMO.

02/10/14 - Dug out wellhead to 1' below surface head. Cut off 3 strings casing. Welded plate on casing & dry hole maker on plate. Filled in cellar, dug up anchors 2' down & cut off. Levelled & cleaned location. Well is P&A and ready for inspection.

RAH
02/13/2014