

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

HOBBS OGD

MAY 14 2014

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-03240
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Injection Well <input type="checkbox"/>		5. Indicate Type of Lease STATE XX FEE
2. Name of Operator State of New Mexico formerly Xeric Oil & Gas Corp		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240		7. Lease Name or Unit Agreement Name West Pearl Queen Unit
4. Well Location Unit Letter I : 1980 feet from the South line and 660 feet from the East line Section 29 Township 19S Range 35E NMPM Lea County		8. Well Number 119
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 25482
		10. Pool name or Wildcat Pearl Queen

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A XX
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/24/2014 MIRU and dig out cellar.
4/25/2014 Cut off wellhead cap and install BOP. Released packer and laid down IPC tubing. Started picking up workstring and SION.
4/26/2014 RIH to 4717 and spotted 25 sx class C cement. WOC and tagged at 4459'. Circulated MLF. Shut down for wind.
4/29/2014 Spotted 25 sx cement at 3315'. POOH and perforated at 1840'. Perfs would not take fluid. Spotted 50 sx cement across perfs from 1890'.
4/30/2014 RIH and tagged at 1402'. Perforated at 200' and tried to establish circulation down 5 1/2 casing to perfs and up annulus to surface. Pumped 40 bbls brine with no circulation. Pumped 30 sx cement down 5 1/2" casing. Cut off wellhead. One inched annulus to surface from 60' and filled up 5 1/2" casing. Installed marker and cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: Mary Brown TITLE Dist. Supervisor DATE 5/14/2014
Conditions of Approval (if any):