Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources	Form C-103 June 19, 2008	
1625 N. French Dr., Hobbs, NM 87240District IIDistrict III1301 W. Grand Ave., Artesia, NM 88210OIL CONSERVATION DIVISIONDistrict III1220 South St. Francis Dr.1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505District IV1220 S. St. Francis Dr., Santa Fe, NM8750587505	WELL API NO. <u>30-025-07364</u> 5. Indicate Type of Lease <u>STATE</u> FEE X 6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other WIW 2. Name of Operator	 7. Lease Name or Unit Agreement Name: North Hobbs G/SA Unit 8. Well Number 241 9. OGRID Number 	
Occidental Permian Ltd. 3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294	157984' 10. Pool name or Wildcat Hobbs: Grayburg-San Andres	
4. Well Location Unit Letter N : 330 feet from the South line and	2310 feet from the West line	
Section 19 Township 18-S Range 38-E 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM County Lea	
3661' DF 12. Check Appropriate Box to Indicate Nature of Notice, 1		
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL ULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT J OWNHOLE COMMINGLE VALUE VALUE	Well to Injection X	
See Attached		
Spud Date: 4/28/14 (RUPU) Rig Release Date: 5/20/14 (RDPU)		
hereby certify that the information above is true and complete to the best of my knowledge and belief.		
Mark_Stephens@oxy.com Mark_Stephens@oxy.com ype or print name Mark_Stephens@oxy.com E-mail address: PHONE (713) 366-5158		
<u>or State Use Only</u> PPROVED BY Bill Semanah	Manoger DATE 11/20/2019	
Conditions of Approval (if any): PMX - 267	t fm	

2014
S
2
NOV

North Hobbs G/SA Unit No. 241 API No. 30-025-07364 Lea Co., NM

4/28/14 - 5/20/14:

MI x RU pulling unit. ND cap flange x NU BOP. RIH w/6-1/8" bit x tag plug at 3887'. Drill cement from 3887' to 3906' (CIBP). Drill on 7" CIBP to 3940' x fell through. Circulate well clean. RIH x tag CIBP at 4031'. Change out to 5-1/2" equipment. Tag top of liner at 3940'. Pick up x run 92 jts. of 5-1/2", 15.5# tie-back liner to surface. RU Halliburton x pump 180 sx. 14.8# Cl. C behind liner. RIH w/4-3/4" bit x tag cement at 3893'. Drill out cement x fell through at 3967'. Circ. well clean x test casing to 500 psi. Drill on cement x CIBP from 4059' to 4156'. Circ. well w/100 bbls 10# BW. RIH x set 5-1/2" CICR at 4057'. RU Warrior x pump 33 bbls .2% Super CBL into perfs at 4128'-35'. RIH w/4-3/4" bit x drill out CICR x cement to 4105'. Test squeeze to 600 psi x held. RU Renegade WL x perf at 4053'-60' & 4068'-92' (4 JSPF, 132 holes). RIH w/5-1/2" treating packer x set at 3984'. Acidize new perfs with 500 gal. 15% acid x 500# rock salt block x 1000 gal. HCL. Let acid spend x release treating packer. RIH x tag PBTD at 4105'. RIH w/injection packer x set at 4000'. RIH w/122 jts. 2-7/8" duoline injection tubing x latch on to packer. ND BOP x NU WH x test tree to 3000 psi. Run MIT x chart for the NMOCD (Bill Sonnamaker witnessed). RD x MO x clean location.

7/25/14: Commence injection in accordance with PMX-267.

