		OCD Ho	bbs	•.	
			FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010		
SUNDRY	NOTICES AND REPOR	TS ON WELLS	OBBS OCD	<ol> <li>Lease Serial No. NMLC054668</li> </ol>	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name		
	PLICATE - Other instruct	ions on reverse side.	PK & CON	8920003820	eement, Name and/or No.
1. Type of Well Oil Well Gas Well Oti			RECEIVED	8. Well Name and Ne R.F.U. 4-4	0.
2. Name of Operator Contact: DAVID A EYLER CIMAREX ENERGY COMPANY OF CO-Mail: DEYLER@MILAGRO-RES.COM			9. API Well No. 30-025-11943		
3a. Address       3b. Phone No. (include area         600 NORTH MARIENFELD STREET, SUITE 600       Ph: 432-687-3033         MIDLAND, TX 79701       Ph: 432-687-3033			ode)	10. Field and Pool, c RHODES	• • •
4. Location of Well (Footage, Sec., 7	F., R., M., or Survey Description)			11. County or Parish	, and State
Sec 4 T26S R37E NWSE 231	OFSL 1980FEL			LEA COUNTY	, <b>NM</b>
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE C	OF NOTICE, R	EPORT, OR OTHI	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION E-PERMITTING <swd inject<="" td=""></swd>				
Notice of Intent		Deepen		ERSION	NDINJECTI RBDMS
□ Subsequent Report	Alter Casing	□ Fracture Treat	<b>RETU</b>	RN TO	TA
☐ Final Abandonment Notice	□ Casing Repair □ Change Plans	New Construction Plug and Abandon	CSNG		CHG LOC
	Convert to Injection	Plug Back	INT TO	PAPM, P&A	NRP&A R
If the proposal is to deepen directions Attach the Bond under which the woi following completion of the involved testing has been completed. Final At determined that the site is ready for fi 1) SET 7" CIBP @ 3,150'; PUI	rk will be performed or provide th l operations. If the operation resu- pandonment Notices shall be filed inal inspection.)	e Bond No. on file with BLM, Its in a multiple completion or only after all requirements, in	BIA. Required su recompletion in a cluding reclamatic	bsequent reports shall b new interval, a Form 31 n, have been completed	e filed within 30 days 60-4 shall be filed once , and the operator has
1) SET 7" CIBP @ 3,150"; PUI 2) PERF.X ATTEMPT TO SQ 3) PERF.X ATTEMPT TO SQ 4) PERF.X ATTEMPT TO SQ 5) PERF.X CIRC. TO SURF., 6) DIG OUT X CUT OFF WEL DURING THIS PROCEDURE THE REQUIRED DISPOSAL,	Z.125 SXS.CMT.@ 1,255'-' Z. 50 SXS.CMT.@ 339'-22' FILLING ALL ANNULI, 25 I.HEAD 3' B.G.L.; WELD C WE PLAN TO USE THE C	910'(T/SALT,T/ANHY.); \ 9'(9-5/8"CSG.SHOE); W SXS.CMT. @ 63'-3'. N STEEL PLATE TO CS LOSED-LOOP SYSTEM	NOC X TAG. OC X TAG. SGS. X INSTAL	CONDITION	NS OF APPROV
				RECL	AMMINAN PROCEDUR ANTACHEDROCEDU
14. I hereby certify that the foregoing is	Electronic Submission #29	1909 verified by the BLM	Well Information	n System	<u></u>
Name (Printed/Typed) DAVID A	For CIMAREX ENEI Committed to AFMSS for pro	RGY COMPANY OF CO, s	ent to the Hobb 04/06/2015 (15.	s	
Signature (Electronic S	Submission)	Date 02/1	7/2015		
	THIS SPACE FOR	R FEDERAL OR STAT	E OFFICE U	SE	
_Approved By	a. am	Title	SPET		14-12-15 Date
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to condu	itable title to those rights in the si	ibject lease	CF0		
	U.S.C. Section 1212, make it a cr	ime for any person knowingly any matter within its jurisdict	and willfully to m	ake to any department o	r agency of the United
Tifle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	automonity of representations us to				
states any false, fictitious or fraudulent s	SED ** BLM REVISED			D ** BLM REVISE	D **

GINNN 23		Cimarex Energy Co. of Colorado Rhodes Federal Unit # 4-4	
		2310' FSL & 1980' FEL	
Original Name: Farnsworth #4		Sec. 4, T-26-S, R-37E, Lea Co., NM	
Spudded 9/7/1959		J Piwetz 30-025-11943 10/10/2013	
Original Operator: Olsen Oils			
		•	
	95/	26# oca @ 280'	
		9 5/8", 36# csg @ 289' cmtd w/ 200 sx	
		eezed casing leak (1054' - 1114') w/ 300 sx	
	dr	iled out and would not hold pressure	
	Tubing		
		8" 4.7# 8rd J-55 Tbg	
	1 2-3/8" SM		
	1 jt OE MA		
	Rods		
TOC - N/R	22 7/8" + 1 Pump - 2"		
	Pump - 2".	K 1-1/2" X 12'	
	· · · · · · · · · · · · · · · · · · ·		
		· · · · · · · · · · · · · · · · · · ·	
	Queen per	fs (3178' - 3223')	
	PBTD @ 3	222' Hard Fill to 3206' (4/2000)	
		# J-55 @ 3237' cmtd w/ 550 sx	
	TD @ 3248'		

Cimarex Energy Co. of Colorado Rhodes Federal Unit # 4-4 2310' FSL & 1980' FEL Original Name: Farnsworth #4 Sec. 4, T-26-S, R-37E, Lea Co., NM 10/10/2013 Spudded 9/7/1959 J Piwetz 30-025-11943 Original Operator: Olsen Oils PERF. X CIRC. 25 5×5. @ 63'-3! Pxt LUND 9 5/8", 36# csg @ 289' cmtd w/ 200 sx Circ. T-ANLY 960 T-Salt 1205 B. Salt 2460 PERF. X SQZ. 50 5×5. C 339-229 - THE PXA FLUID Squeezed casing leak (1054' - 1114') w/ 300 sx drilled out and would not hold pressure z585 Yatos PERF. X 507. 125 5×5. 1255-910- TAG PXA 2840 1R 3212 Qu 233075 9-17-59 PERF. X 507. 100 5×5. @ 2635-2410-776 TOC - N/R Ful FLUND Pump 25 5x5. @ 3150'-3050' SET 7" OTBP@ 3150'. Queen perfs (3178' - 3223') PBTD @ 3222' Hard Fill to 3206' (4/2000) 7", 23 & 26# J-55 @ 3237' cmtd w/ 550 sx า ี่ 10 @ 3248 DAS 02/10/15

**Cimarex Energy Co. of Colorado** Rhodes Federal Unit # 4-4 2310' FSL & 1980' FEL Original Name: Farnsworth #4 Sec. 4, T-26-S, R-37E, Lea Co., NM Spudded 9/7/1959 J Piwetz 30-025-11943 10/10/2013 Original Operator: Olsen Oils PERF.X CIRC. 25 5×5. @ 63'-3' Pxt FLUD 9 5/8", 36# csg @ 289' cmtd w/ 200 sx PERF. X 50 2. 50 5×5. @ 339-229 - THG PKA FLUID Squeezed casing leak (1054' - 1114') w/ 300 sx drilled out and would not hold pressure PERF. X 502. 125 5×5. 1255-910-7AG 2×A FLUD DERF. X SQZ. 100 5x5, @ 2635-2410-7745 TOC -- N/R ParA FLUID Pump 25 5x5. @ 3150-3050' SET 7" OTBPE 3150'. Queen perfs (3178' - 3223') PBTD @ 3222' Hard Fill to 3206' (4/2000) 7", 23 & 26# J-55 @ 3237' cmtd w/ 550 sx TD @ 3248 DAS 02/10/15

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged</u>.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

J. Amos 3/6/11



## United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

## **Reclamation Objectives and Procedures**

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Duncan Whitlock Environmental Protection Specialist 575-234-5926

Linda Denniston Environmental Protection Specialist 575-234-5974 Cody Layton Supervisory Multi Resources 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Jeffery Robertson Natural Resource Specialist 575-234-2230

Solomon Hughes Natural Resource Specialist 575-234-5951