Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0135

	E	xpires:	July	31,	20
ease	Serial	No.			
	0000	474D			

SUNDRY N	OTICES AND	REPORTS ON	WELLS
Do not use this	form for propos	sals to drill or to	re-enter an
abandoned well.	Use form 3160	-3 (APD) for suc	ch proposals.

D	11.1			
abandoned v	this form for proposals to o vell. Use form 3160-3 (APD)	frill or to re-enter an) for such proposals.	6. In	Indian, Allottee or Tribe Name
SUBMIT IN T	RIPLICATE - Other instruct	ions on reverse side.	7. I	FUnit or CA/Agreement, Name and/or No.
Type of Well ☐ Oil Well ☐ Gas W	8. W	Vell Name and No. VH RHODES B FEDERAL NCT-1 15		
2. Name of Operator PPC OPERATING COMPA	/ Contact: F	BOB COX		PI Well No. 0-025-21953-00-S1
3a. Address 4700 W SAM HOUSTON P HOUSTON, TX 77041	KWY N STE 140	3b. Phone No. (include area c Ph: 325.668.9230	F	Field and Pool, or Exploratory RHODES
4. Location of Well (Footage, Sec.	, T., R., M., or Survey Description)			County or Parish, and State
Sec 27 T26S R37E NENE 6	660FNL 660FEL	APR 27	2016 L	EA COUNTY, NM
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE NATURE	FNOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE	E OF ACTION	Da
Notice of Intent	☐ Acidize	Deepen	☐ Production (S	INT TO PA_MX ff
_	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	P&A NR
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	P&A R
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	☐ Temporarily	A ¹
	☐ Convert to Injection	☐ Plug Back	☐ Water Dispos	sal
If the proposal is to deepen directi Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for	onally or recomplete horizontally, g work will be performed or provide the red operations. If the operation resu Abandonment Notices shall be filed r final inspection.)	tive subsurface locations and m he Bond No. on file with BLM. alts in a multiple completion or d only after all requirements, in	easured and true vertical BIA. Required subseque recompletion in a new in cluding reclamation, have	d work and approximate duration thereof. depths of all pertinent markers and zones. ent reports shall be filed within 30 days terval, a Form 3160-4 shall be filed once e been completed, and the operator has
If the proposal is to deepen directi Attach the Bond under which the following completion of the invol- testing has been completed. Final determined that the site is ready for 1) MIRU. NDWH, NUBOP. 2) Set CIBP @ 2958'. Circ h	onally or recomplete horizontally, gwork will be performed or provide the pred operations. If the operation results abandonment Notices shall be filed in final inspection.) POOH w/ Prod. Tbg nole w/ MLF. Cap BP w/ 25sx 2596' Tag 1358' Seff Saz Cmt 1113' Tag 103 mt to surface fy cmt @ surface, RDMO.	tive subsurface locations and me Bond No. on file with BLM. alts in a multiple completion or donly after all requirements, in community and the subsection of the subsection o	easured and true vertical 'BIA. Required subseque recompletion in a new in cluding reclamation, have	depths of all pertinent markers and zones. Int reports shall be filed within 30 days terval, a Form 3160-4 shall be filed once been completed, and the operator has
If the proposal is to deepen directi Attach the Bond under which the following completion of the involvesting has been completed. Final determined that the site is ready for the following complete is ready for the following complete in the following complete is ready for the following complete in the following complete is possible for the following complete in the following complete is the following complete in the following compl	onally or recomplete horizontally, gwork will be performed or provide the ved operations. If the operation results have been considered on the operation of the	tive subsurface locations and me Bond No. on file with BLM. alts in a multiple completion or donly after all requirements, in comt 745 at 264 cm 1508-1398. Tag	easured and true vertical 'BIA. Required subseque recompletion in a new in cluding reclamation, have IC' or higher	depths of all pertinent markers and zones. Int reports shall be filed within 30 days terval, a Form 3160-4 shall be filed once been completed, and the operator has
If the proposal is to deepen directi Attach the Bond under which the following completion of the involvesting has been completed. Final determined that the site is ready for the following completed. Final determined that the site is ready for the following that the following the following the following that the following the following that the following the followi	onally or recomplete horizontally, gwork will be performed or provide the pred operations. If the operation results abandonment Notices shall be filed in final inspection.) POOH w/ Prod. Tbg nole w/ MLF. Cap BP w/ 25sx 2596' Tag 1358' Seff Saz Cmt 1113' Tag 103 mt to surface fy cmt @ surface, RDMO.	tive subsurface locations and me Bond No. on file with BLM. alts in a multiple completion or donly after all requirements, in comt 745 at 264 cm 1508-1398. Tag	easured and true vertical 'BIA. Required subseque recompletion in a new in cluding reclamation, have IC' or higher	depths of all pertinent markers and zones. Int reports shall be filed within 30 days terval, a Form 3160-4 shall be filed once been completed, and the operator has
Attach the Bond under which the rollowing completion of the involvesting has been completed. Final determined that the site is ready for the strain of the site is ready for the site is r	onally or recomplete horizontally, gwork will be performed or provide the development of the operations. If the operation recomplete of the operation is a shall be filed a final inspection.) POOH w/ Prod. Tbg tole w/ MLF. Cap BP w/ 25sx 2596'—Tag 1358'—Tag 103 mt to surface fy cmt @ surface. RDMO. stall dry hole marker TION PROCEDURE TTACHED g is true and correct. Electronic Submission #3: For PPC OPERA ommitted to AFMSS for process.	ive subsurface locations and me Bond No. on file with BLM. alts in a multiple completion or donly after all requirements, in comt 795 at 264 complete and some statements of the second statement of the second statem	easured and true vertical 'BIA. Required subseque recompletion in a new in cluding reclamation, have C' or higher EE ATTACHED NDITIONS O Well Information System to the Hobbs Z on 03/03/2016 (16P)	depths of all pertinent markers and zones. Int reports shall be filed within 30 days terval, a Form 3160-4 shall be filed once been completed, and the operator has FOR FAPPROVAL
If the proposal is to deepen directi Attach the Bond under which the following completion of the involvesting has been completed. Final determined that the site is ready for 1) MIRU. NDWH, NUBOP. 2) Set CIBP @ 2958'. Circ h 3) Spot 25sx cmt @ 2696' - 4) Spot 25sx cmt @ 1458' - 5) Spot 25sx cmt @ 1213' - 6) Perf @ 200' - Circ 50sx c 7) POOH. Fill wellbore. Veri 8) Cut off WH & anchors. In RECLAMA A	onally or recomplete horizontally, gwork will be performed or provide the very department. If the operation recomplete horizontally, gwork will be performed or provide the very department. If the operation recomplete horizons. If the operation recomplete horizons. If the operation recomplete horizons had been department of the operation. POOH w/ Prod. Tbg hole w/ MLF. Cap BP w/ 25sx 2596'—Tag 1258—Tag 12	ive subsurface locations and me Bond No. on file with BLM. Its in a multiple completion or donly after all requirements, in comt 745 at 264 cmt 745 at 264 cmt 7508-7596. Tag	easured and true vertical 'BIA. Required subseque recompletion in a new in cluding reclamation, have C' or higher EE ATTACHED NDITIONS O Well Information System to the Hobbs Z on 03/03/2016 (16P)	depths of all pertinent markers and zones. Int reports shall be filed within 30 days terval, a Form 3160-4 shall be filed once been completed, and the operator has FOR FAPPROVAL
If the proposal is to deepen directi Attach the Bond under which the following completion of the involvesting has been completed. Final determined that the site is ready for 1) MIRU. NDWH, NUBOP. 2) Set CIBP @ 2958'. Circ h 3) Spot 25sx cmt @ 2696' - 4) Spot 25sx cmt @ 1458' - 5) Spot 25sx cmt @ 1213' - 6) Perf @ 200' - Circ 50sx c 7) POOH. Fill wellbore. Veri 8) Cut off WH & anchors. In RECLAMA A 4. I hereby certify that the foregoing C Name (Printed/Typed) GREG I	onally or recomplete horizontally, gwork will be performed or provide the development of the operations. If the operation recomplete of the operation is a shall be filed a final inspection.) POOH w/ Prod. Tbg tole w/ MLF. Cap BP w/ 25sx 2596'—Tag 1358'—Tag 103 mt to surface fy cmt @ surface. RDMO. stall dry hole marker TION PROCEDURE TTACHED g is true and correct. Electronic Submission #3: For PPC OPERA ommitted to AFMSS for process.	ive subsurface locations and me Bond No. on file with BLM. alts in a multiple completion or donly after all requirements, in comt 745 at 264 cmt 745 at 264 cmt 7508-7596. Tag 31828 verified by the BLM. TING COMPANY LLC, sets ssing by PRISCILLA PERETitle AGE	easured and true vertical 'BIA. Required subseque recompletion in a new in cluding reclamation, have C' or higher EE ATTACHED NDITIONS O Well Information System to the Hobbs Z on 03/03/2016 (16P)	depths of all pertinent markers and zones. Int reports shall be filed within 30 days terval, a Form 3160-4 shall be filed once been completed, and the operator has FOR FAPPROVAL
If the proposal is to deepen directi Attach the Bond under which the following completion of the involvesting has been completed. Final determined that the site is ready for 1) MIRU. NDWH, NUBOP. 2) Set CIBP @ 2958'. Circ h 3) Spot 25sx cmt @ 2696' - 4) Spot 25sx cmt @ 1458' - 5) Spot 25sx cmt @ 1213' - 6) Perf @ 200' - Circ 50sx c 7) POOH. Fill wellbore. Veri 8) Cut off WH & anchors. In RECLAMA A A 14. I hereby certify that the foregoing C Name (Printed/Typed) GREG I	onally or recomplete horizontally, gwork will be performed or provide it ded operations. If the operation rest Abandonment Notices shall be filed a final inspection.) POOH w/ Prod. Tbg hole w/ MLF. Cap BP w/ 25sx 2596'—Tag hole w/ 25sx 2596'—	ive subsurface locations and me Bond No. on file with BLM. alts in a multiple completion or donly after all requirements, in comt 745 at 264 cmt 745 at 264 cmt 7508-7596. Tag 31828 verified by the BLM. TING COMPANY LLC, sets ssing by PRISCILLA PERETitle AGE	easured and true vertical BIA. Required subseque recompletion in a new including reclamation, have the completion of the completion of the complete of the com	depths of all pertinent markers and zones. Int reports shall be filed within 30 days terval, a Form 3160-4 shall be filed once been completed, and the operator has FOR FAPPROVAL
If the proposal is to deepen directi Attach the Bond under which the following completion of the involvesting has been completed. Final determined that the site is ready for 1) MIRU. NDWH, NUBOP. 2) Set CIBP @ 2958'. Circ h 3) Spot 25sx cmt @ 2696'- 4) Spot 25sx cmt @ 1458'- 5) Spot 25sx cmt @ 1213'- 6) Perf @ 200' - Circ 50sx c 7) POOH. Fill wellbore. Veri 8) Cut off WH & anchors. In RECLAMA A 14. I hereby certify that the foregoing C Name (Printed/Typed) GREG I	onally or recomplete horizontally, gwork will be performed or provide it ded operations. If the operation rest Abandonment Notices shall be filed a final inspection.) POOH w/ Prod. Tbg hole w/ MLF. Cap BP w/ 25sx 2596'—Tag hole w/ 25sx 2596'—	ive subsurface locations and me Bond No. on file with BLM lits in a multiple completion or d only after all requirements, in comt 795 at 264 cm 1508-1396. Tag SI COMPANY LLC, sersing by PRISCILLA PERE Title AGE	easured and true vertical BIA. Required subseque recompletion in a new including reclamation, have the completion of the completion of the complete of the com	depths of all pertinent markers and zones. Int reports shall be filed within 30 days terval, a Form 3160-4 shall be filed once been completed, and the operator has FOR FAPPROVAL

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

FOR RECORD ONLY MW/OCD 4-28-2016

W H Rhodes B Federal #15 Wellbore Diagram_(rev_TR_2 8 16)

Rhodes, W.H.-B- Fed NCT-1 #15 LEASE & WELL NO. FORMER NAME n/a **Rhodes Yates** FIELD NAME **COUNTY & STATE** Lea County, NM 660' FNL & 660' FEL Sec. 27, T-26S, R-37E, Unit A LOCATION API NO. 30-025-21953 2994' (DF) K.B. ELEV. **CURRENT COMPLETION GROUND LEVEL** 9-7/8" Hole Size **Formation Tops MD** Top Anhy 1095 Top of Salt 1458 Btm of Salt 2696 Top of Yates 2992 SURFACE CASING SIZE 15&24# 7-5/8" WEIGHT **DEPTH** 1163' GRADE SX. CMT. 575 sx TOC@ Surf. **WELL HISTORY** 6-5/8" Hole Size SPUD DATE: 1/9/1967 RR DATE: 3/1/1967 **COMPLETION DATE:** Perf'd 3008' - 3195' w/ 2 spf (gross) 03/67 Depth Degrees Acidized w/ 2,500 gals 15% NEA in 5 stages w/ 6 BS b/t stages 300 0.25 Frac'd w/ 30,000 gals XLG & 30,000# Sand 496 0.5 700 0.75 IP 3 BOPD x 61.9 MCFD x 0 BWPD flowing 23/64" choke 1170 0.75 FTP = 180#, 35.4 deg API oil gravity 1464 1.25 1912' 1.5 05/67 TA'd well to be held for secondary recovery. 2368 1.75 2645 2 09/93 NOI to pull equip, clean out and convert to injection. 2748' 3.25 2905' 2.75 *Cleaned out to PBTD @ 3260'. Re-perf'd Yates 3132'-3164'. 05/10 3000 3.25 RIH w/ pkr to 3081', acidized w/ 3,000 gals 15% HCI 80/20 acid 3300' 3.25 Returned to injection 5/22/10. PKR @ +/-3080' Perforations: 3008, 3040, 3055, 3060, 3134, 3139, 3144, 3 PRODUCTION CASING 3177', 3184', 3190', 3195' 4-1/2" 9.5# SIZE WEIGHT DEPTH 3300 (sqz'd w/ 300xs)? GRADE J-55 SX. CMT. 450 sx TOC@ 250 *Re-perf'd: 3150'-3164', 3132'-3146' (4 spf,

PBTD@

TD@

3260

3300

W H Rhodes B Federal #15 Wellbore Diagram_(rev_TR_2 8 16)

LEASE & W	ELL NO.	Rhodes, W.HB- Fed I	NCT-1 #15	FORMER NAME n/a	
FIELD NAM		Rhodes Yates		COUNTY & STATE Lea County, NM	
LOCATION		660' FNL & 660' FEL Sec. 2	7, T-26S, R-37E, Unit A	API NO. 30-025-21953	
V 0 5151/		20041 (DE)		CHOCKET MADIETICAL	
K.B. ELEV. GROUND LE	EVE!	2994' (DF)	9-7/8" Hole Size	ZE Formation Tops MD	
GROOND EL	.VLL		5-7/6 TIONE 5126		
				Pla 200 to soit 50 sks cont	-
			7.		
		SURFACE CASING	Toc 250		
SIZE		WEIGHT 15&24#	DEPTH1163'		
GRADE		SX. CMT. <u>575 sx</u>	TOC @ Surf.	pert+592 1103	
					.4.
				400 Tag	Z.
				Woc Tag	
WELL HISTO	DRY		6-5/8" Hole Size	ze	
		. 10 10 00			
SPUD DATE	:	1/9/1967		Perf+592	
RR DATE:	N DATE:	3/1/1967		Too	
COMPLETIC	M DATE.	3/1/190/		Perf+ Sqz Snot 25 5kcm+ Tag	
03/67		195' w/ 2 spf (gross)		1458 1358 Depth Degrees	
		00 gals 15% NEA in 5 stages	w/ 6 BS b/t stages	300 0.25	
	Frac d W/ 30,00	0 gals XLG & 30,000# Sand		1508 - 1398 496' 0.5 700' 0.75	
	IP 3 BOPD x 61.	.9 MCFD x 0 BWPD flowing 2	3/64" choke	1170' 0.75	
		4 deg API oil gravity		1464' 1.25	
				1912' 1.5	
05/67	TA'd well to be	held for secondary recovery	/·	2368' 1.75	
			1-141	2645' 2	
09/93	NOI to pull equ	ip, clean out and convert to	injection.	2748' 3.25 2905' 2.75	
05/10	*Cleaned out to	o PBTD @ 3260'. Re-perf'd Y	ates 3132'-3164'.	Supt 25 SKC Not needed	1
03/10		081', acidized w/ 3,000 gals		1 22001 1 27 7	
		ection 5/22/10.	•	2691-2596 33.25 (ov	
					prev.
				Plu	5.
				LOV 11/2	
				Tag al 20 40	
				Set CIBP 2958 w 25560	T
				Perforations:	10
				3008, 3040, 3055, 3060, 3134, 3139, 314	4,:
		PRODUCTION CASING		3177', 3184', 3190', 3195'	
SIZE	4-1/2"	WEIGHT 9.5#	DEPTH 3300'	(sqz'd w/ 300xs)?	
GRADE	J-55	SX. CMT. 450 sx	TOC @ 250'	*Re-perf'd: 3150'-3164', 3132'-3146' (4 s	pf,
			PBTD@ 3260'		
			TD@ 3300'		

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.

- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Linda Denniston Environmental Protection Specialist 575-234-5974

Henryetta Price Environmental Protection Specialist 575-234-5951

Dara Glass Environmental Protection Specialist 575-234-5924

Shelly Tucker Environmental Protection Specialist 575-234-5979