Office I CORDO (D	State of New Me			Form C-103
<u>bistrict I</u> – (575) 393-6161 HOBBS @ 625 N. French Dr., Hobbs, NM 88240	nergy, Minerals and Natur	ral Resources	WELL API NO.	d July 18, 2013
$\frac{\text{District II}}{11 \text{ S. First St., Artesia, NM 8821} \text{ EP } 1520$	DIL CONSERVATION	DIVISION	30-025-34643	
nsurct m = (303) 334-0178	1220 South St. Fran	cis Dr.	5. Indicate Type of Lease STATE STATE FEE	
000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87	505	6. State Oil & Gas Lease No.	
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 87505			19552	
	ND REPORTS ON WELLS	12-1-1-	7. Lease Name or Unit Agree	ment Name
O NOT USE THIS FORM FOR PROPOSALS TO FFERENT RESERVOIR. USE "APPLICATION (OPOSALS.)			North Hobbs Unit (G/SA)	1
. Type of Well: Oil Well X Gas W	ell 🗌 Other		8. Well Number 521	1
Name of Operator Occidental Permian Ltd		-	9. OGRID Number 157984	
. Address of Operator			10. Pool name or Wildcat	
P.O. Box 4294, Houston, TX 7721	10		Hobbs (G/SA)	d'anna ann
Well Location	feet from the North		1500 feet from the W	lost 1:
Unit Letter C : 990 Section 33		line and nge 38E		line
	Township 18S Rate levation (Show whether DR,	·	NMPM County	Lea
	46' GL	nue, ni, on, etc	·/	
	~			
12. Check Approp	riate Box to Indicate Na	ature of Notice,	, Report or Other Data	
NOTICE OF INTENT		CLIE		
		CASING/CEMEN		
OSED-LOOP SYSTEM				
HER:		OTUED		
		OTHER:		
13. Describe proposed or completed op		ertinent details, an		
13. Describe proposed or completed op of starting any proposed work). SE	E RULE 19.15.7.14 NMAC	ertinent details, an		
13. Describe proposed or completed op	E RULE 19.15.7.14 NMAC	ertinent details, an		
13. Describe proposed or completed op of starting any proposed work). SE	E RULE 19.15.7.14 NMAC	ertinent details, an		
 Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion 	EE RULE 19.15.7.14 NMAC on.	ertinent details, an . For Multiple Co	ompletions: Attach wellbore diag	
 Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg x 	EE RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII	ompletions: Attach wellbore diag H treating pkr @ 4010.	gram of
 Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg x Chemical treatment w/ 50 gals PAO7 	EE RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' –	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w 	E RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' –	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w 	E RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' –	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w 	E RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' –	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w 	E RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' –	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w 	E RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' –	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w 	E RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' –	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w. PBTD @ 4265. RD x NDBOP x NUWH 	E RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F ush w/ 50 bbls F	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' –	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w. PBTD @ 4265. RD x NDBOP x NUWH 	E RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F ush w/ 50 bbls F	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' –	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w. PBTD @ 4265. RD x NDBOP x NUWH 	E RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F ush w/ 50 bbls F	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' –	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RH 5 ½" pkr @ 3959. Run acid job w/PBTD @ 4265. RD x NDBOP x NUWH I Date: 07/01/16 	EE RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu Rig Release Dat	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls Fu ush w/ 50 bbls Fu e: 07/11/16	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' – W. POOH pkr x RIH 122 jts x E	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w. PBTD @ 4265. RD x NDBOP x NUWH d Date: 07/01/16 	EE RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu Rig Release Dat	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls Fu ush w/ 50 bbls Fu e: 07/11/16	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' – W. POOH pkr x RIH 122 jts x E	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w, PBTD @ 4265. RD x NDBOP x NUWH d Date: 07/01/16 	EE RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu Rig Release Dat	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F ush w/ 50 bbls F e: 07/11/16	ompletions: Attach wellbore diag H treating pkr @ 4010. W. POOH pkr x perf'd 4044' – W. POOH pkr x RIH 122 jts x E	gram of - 4227'.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w PBTD @ 4265. RD x NDBOP x NUWH d Date: 07/01/16 	EE RULE 19.15.7.14 NMAC on. EESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu Rig Release Dat	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F ush w/ 50 bbls F e: 07/11/16 st of my knowledg	M treating pkr @ 4010. W. POOH pkr x perf'd 4044' – W. POOH pkr x RIH 122 jts x E ge and belief.	gram of - 4227'. SP.
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w PBTD @ 4265. RD x NDBOP x NUWH d Date: 07/01/16 	EE RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu Rig Release Dat	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F ush w/ 50 bbls F e: 07/11/16 st of my knowledg	M treating pkr @ 4010. W. POOH pkr x perf'd 4044' – W. POOH pkr x RIH 122 jts x E ge and belief. DATE 09/12	gram of - 4227'. SP. 2/2016
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w. PBTD @ 4265. RD x NDBOP x NUWH d Date: 07/01/16 reby certify that the information above is NATURE April Hood 	EE RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu Rig Release Dat	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F ush w/ 50 bbls F e: 07/11/16 st of my knowledg	M treating pkr @ 4010. W. POOH pkr x perf'd 4044' – W. POOH pkr x RIH 122 jts x E ge and belief. DATE 09/12	gram of - 4227'. SP. 2/2016
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 RIH 5 ½" pkr @ 3959. Run acid job w/PBTD @ 4265. RD x NDBOP x NUWH I Date: 07/01/16 eby certify that the information above is NATURE A Completion of the information above is NATURE A Complete the information above is NATURE A Complete	EE RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu Rig Release Dat	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F ush w/ 50 bbls F e: 07/11/16 st of my knowledg	M treating pkr @ 4010. W. POOH pkr x perf'd 4044' – W. POOH pkr x RIH 122 jts x E ge and belief. DATE 09/12 ty.com PHONE: 713	2/2016 -366-5771
 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion MIRU x NDWH x NUBOP. POOH tbg > Chemical treatment w/ 50 gals PAO7 Chemical treatment w/ 50 gals PAO7 CH 5 ½" pkr @ 3959. Run acid job w BTD @ 4265. RD x NDBOP x NUWH Date: 07/01/16 eby certify that the information above is NATURE April Hood 	EE RULE 19.15.7.14 NMAC on. CESP. RIH 5 ½" CIBP @ 42 2 x 14 glas WLC603 x flus / 2600 glas 15% NEFE x flu Rig Release Dat	ertinent details, an For Multiple Co 75 w/ 9' cmt. RII hed w/ 30 bbls F ush w/ 50 bbls F e: 07/11/16 st of my knowledg	M treating pkr @ 4010. W. POOH pkr x perf'd 4044' – W. POOH pkr x RIH 122 jts x E ge and belief. DATE 09/12	2/2016 -366-5771