

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOCD

Hobbs

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMNM0558018

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
UNION SI FEDERAL 69. API Well No.
30-005-20869-00-S110. Field and Pool or Exploratory Area
TOMAHAWK-SAN ANDRES11. County or Parish, State
CHAVES COUNTY, NM**SUBMIT IN TRIPLICATE - Other instructions on page 2**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CROSS BORDER RESOURCES, INC-E-Mail: ROSS@REDMOUNTAINRESOURCES.COM

Contact: ROSS PEARSON

3a. Address

14282 GILLIS ROAD
FARMERS BRANCH, TX 75244

3b. Phone No. (include area code)

Ph: 214-871-0400 Ext: 1019
Fx: 214-871-0406

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 1 T8S R31E SWNE 1650FNL 1650FEL
33.651582 N Lat, 103.723895 W Lon

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Hydraulic Fracturing☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other
Production Start-up

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

MIRU pulling unit.

POOH with rods and pump. POOH with production tubing.

Check fluid level. Acidize well if it is carrying a fluid level (800 to 1000' above the perms).

Hydrotest tubing back into the hole.

Run pump and rods.

Return well to production.

ACCEPTED FOR **3** MONTH PERIOD
ENDING **MAY 15 2017****Accepted For Record Only! Approval Subject
To Putting Well On Continuous Production
And Keeping Well On Continuous Production
Or Plugging Well With An Approved Plugging
Program!**

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #367162 verified by the BLM Well Information System
For CROSS BORDER RESOURCES, INC., sent to the Roswell
Committed to AFMSS for processing by DAVID GLASS on 02/15/2017 (17DRG0103SE)**

Name (Printed/Typed) ROSS PEARSON

Title VP OPERATION

Signature (Electronic Submission)

Date 02/15/2017

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

(ORIG. SGD) DAVID R. GLASS

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Kc