Submit 1 Copy To Appropriate District State of New Mex	E C 102
Office District I – (575) 393-6161 Energy, Minerals and Natura	al Resources Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	WELL API NO. 30-025-31926
District III – (575) 748-1283 OIL CONSERVATION I 811 S. First St., Artesia, NM 88210 0IL CONSERVATION I District III – (505) 334-6178 1220 South St. France	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 875	SIAIE FEE
1220 S. St. Francis Dr., Santa Fc, NM 87505	NM-86148
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOF	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other SWD	2
2. Name of Operator EOG Y Resources	9. OGRID Number 025575
3. Address of Operator	10. Pool name or Wildcat
104 S. Fourth Street Artesia, NM 88210	SWD; Bell Canyon
4. Well Location Unit Letter <u>D</u> : <u>330</u> feet from the <u>N</u> line and	<u>330</u> feet from the W line
Section 17 Township 22S Range	32E, NMPM County Lea
11. Elevation (Show whether DR, 1	RKB, RT, GR, etc.)
3726' GR	
12. Check Appropriate Box to Indicate Na	ture of Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK
	COMMENCE DRILLING OPNS. P AND A CASING/CEMENT JOB
DOWNHOLE COMMINGLE	
OTHER:	OTHER: MIT
	VINER. MIII
15. Deserve proposed of completed operations. (Clearly state all pe	ertinent details, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed.	For Multiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes.	For Multiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD.	For Multiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD.	For Multiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD.	For Multiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD.	For Multiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD.	For Multiple Completions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD. Copy of chart attach.	For Multiple Completions: Attach wellbore diagram of HOBBS OCD MAR 2 3 2017 RECE.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD.	For Multiple Completions: Attach wellbore diagram of HOBBS OCD MAR 2 3 2017 RECE.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD. Copy of chart attach.	For Multiple Completions: Attach wellbore diagram of HOBBS OCD MAR 2 3 2017 RECE
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD. Copy of chart attach.	For Multiple Completions: Attach wellbore diagram of HOBBS OCD MAR 2 3 2017 RECE
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD. Copy of chart attach. I hereby certify that the information above is true and complete to the bes SIGNATURE for the formation above is true and complete to the bes SIGNATURE for the formation above is true and complete to the bes SIGNATURE for the formation above is true and complete to the bes SIGNATURE for the formation above is true and complete to the bes Type or print name Miriam Morales E-mail address: Mitted the formation above is true and complete to the bes	For Multiple Completions: Attach wellbore diagram of HOBBS OCD MAR 2 3 2017 RECE
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD. Copy of chart attach.	For Multiple Completions: Attach wellbore diagram of HOBBS OCD MAR 2 3 2017 RECE t of my knowledge and belief. roduction Acct DATE 3/16/17 iriam_morales@eogresources.com PHONE: 575-748-4200
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD. Copy of chart attach. I hereby certify that the information above is true and complete to the bes SIGNATURE Comments of the strue and complete to the bes SIGNATURE Comments of the strue and complete to the bes Mither the information above is true and complete to the bes SIGNATURE Comments of the strue and complete to the bes Mither the information above is true and complete to the bes Mither the information above is true and complete to the bes SIGNATURE Comments of the strue and complete to the bes Mither the information above is true and c	For Multiple Completions: Attach wellbore diagram of HOBBS OCD MAR 2 3 2017 RECE t of my knowledge and belief. roduction AcctDATE3/46/17
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD. Copy of chart attach. I hereby certify that the information above is true and complete to the bes SIGNATURE Comments of the strue and complete to the bes SIGNATURE Comments of the strue and complete to the bes Mitter of the strue and complete to the bes SIGNATURE Comments of the strue and complete to the bes Mitter of the strue and complete to the bes SIGNATURE Comments of the strue and complete to the bes Mitter of the strue and complete to the bes Mitter of the strue and complete to the bes	For Multiple Completions: Attach wellbore diagram of HOBBS OCD MAR 2 3 2017 RECE t of my knowledge and belief. roduction Acct DATE 3/16/17 iriam_morales@eogresources.com PHONE: 575-748-4200
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. proposed completion or recompletion. MIT performed on 3/15/17, passed. Started at 560 psi and ended at 525 for 32 minutes. Witnessed by Gary Robinson from OCD. Copy of chart attach. I hereby certify that the information above is true and complete to the bes SIGNATURE Comments of the strue and complete to the bes SIGNATURE Comments of the strue and complete to the bes Mither the information above is true and complete to the bes SIGNATURE Comments of the strue and complete to the bes Mither the information above is true and complete to the bes Mither the information above is true and complete to the bes SIGNATURE Comments of the strue and complete to the bes Mither the information above is true and c	For Multiple Completions: Attach wellbore diagram of HOBBS OCD MAR 2 3 2017 RECE t of my knowledge and belief. roduction Acct DATE 3/16/17 iriam_morales@eogresources.com PHONE: 575-748-4200

