Form 3160-5 (June 2015)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Hobbs

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018


Lease Serial No. NMNM02965A


SUNDRY NOTICES AND REPORTS ON WELLS


Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals RRS OCD⁶. If Indian, Allottee or Tribe Name


	,		- HODD	3 001			
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.						
Type of Well	EIVED	8. Well Name and No. EL MAR 21 WODM FED COM 2H					
Name of Operator MEWBOURNE OIL COMPAN	9. API Well No. 30-025-42935	/					
3a. Address PO BOX 5270 HOBBS, NM 88241	3b. Phone No. (include area code) Ph: 575-393-5905			10. Field and Pool or I 98097	Exploratory Area		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	1)			11. County or Parish,	State	
Sec 21 T26S R33E Mer NMP		LEA COUNTY, NM					
	,						
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	ON TYPE OF ACTION						
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off	
☐ Notice of Intent	☐ Alter Casing	☐ Hyd	draulic Fracturing Reclama		ation	☐ Well Integrity	
Subsequent Report	☐ Casing Repair	□ Nev	ew Construction Recom		olete	Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug	g and Abandon	☐ Tempor	arily Abandon	Well Spud	
*	☐ Convert to Injection	Plug	Back	□ Water I	Disposal		
testing has been completed. Final Al determined that the site is ready for f 10/13/17Spud 17 1/2" hole. with 600 sks Class C w/addit Mixed @ 14.8#/g w/ 1.34 yd. I BOPE to 10000# & Annular to P.M. 10/16/17, tested csg to 1 test to EMW of 10.5 PPG. Chart & Schematic attached. Bond on file: NM1693 nationw	Tinal inspection. TD'd hole @ 944'. Rankives. Mixed @ 13.5 #/g wives. Mixed @ 10:30 P.M. o 5000#. Tested standpipersonal for 30 minutes, held wide & NMB000919	934' of 13 3/8 / 1.35 yd. Tail 10/14/17. Cir e & mud lines	" 54.5# J55 ST& w/200 sks Class c 225 sks cemen to the pumps to	C csg. Cems C w/2% Cast to pit Test	nented aCl2.		
14. I hereby certify that the foregoing is true and correct. Electronic Submission #392828 verified by the BLM Well information System For MEWBOURNE OIL COMPANY, sent to the Hobbs Committed to AFMSS for processing by JENNIFER SANCHEZ on 10/24/2017 () Name (Printed/Typed) JACKIE LATHAN Title AUTHORIZED REPRESENTATIVE							
Name (1 raneal types) BAONIE E	ATTAN		The Adillo	800			
Signature (Electronic S	Submission)		Date 10/24/2	ACUEP 1	TED FOR REC	ORD	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to conduct the second of the secon	uitable title to those rights in th uct operations thereon.	e subject lease	Title Office		SBAD FIELD OFFICE	Date Agency of the United	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **









MAN WELDING SERVICES, INC.

Company Membourne Date 0-15-17
Lease [L Mar 2 WODM Fed Cass #2 County CO NM
Drilling Contractor Potterson 231 Plug & Drill Pipe Size CET 39/4/3
Accumulator Pressure: 3000 Manifold Pressure: 1500 Annular Pressure: 1000
Accumulator Function Test - OO&GO#2
To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)
 Make sure all rams and annular are open and if applicable HCR is closed. Ensure accumulator is pumped up to working pressure! (Shut off all pumps) 1. Open HCR Valve. (If applicable) 2. Close annular. 3. Close all pipe rams. 4. Open one set of the pipe rams to simulate closing the blind ram. 5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems). 6. Record remaining pressure 10/15 psi. Test Fails if pressure is lower than required. a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system} 7. If annular is closed, open it at this time and close HCR.
To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)
 Start with manifold pressure at, or above, maximum acceptable pre-charge pressure: a. {800 psi for a 1500 psi system} b. {1100 psi for 2000 and 3000 psi system}
 Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure) Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to. Record pressure drop psi. Test fails if pressure drops below minimum. Minimum: a. (700 psi for a 1500 psi system)

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
 - 1. Open the HCR valve, {if applicable}
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time \[\lambda_0 \rangle \]. Test fails if it takes over 2 minutes.
- a. {950 psi for a 1500 psi system}
 b. {1200 psi for a 2000 & 3000 psi system}



WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

ANTI O PERSONS	Lovington, NM • 575-396-4540	Pg of
company: Meintourile	Date: 10-15-17	Invoice #B805412
Lease: EL Mar 20 WOVM ted Co	m 21 Drilling Contractor: Potter	Rig#231
Plug Size &Type:	Drill Pipe Size (IT-39/49IF	restor 211on Roughalds
Required BOP:	Installed BOP:	
*Appropriate Casing Valve Must Be Open During BOP Test *	• CH	nack Valve Must Be Open/Disabled To Test Kill Line Valves
Pipe Rams #12 Blind Rams #13 #11 #10 #9 Pipe Rams #14	#26 #2 #4 #5 #6 #6 Kelly/ Top Drive #3 #17 #88 Manual IBOP #17 #25 Super Choke	Pump Valve #20 #21
		and the second
Casing		

TEST #	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	REMARKS
1	13,9,1,2,50,6	10-10	250	10,000	Pass
2	25, 26, 5, 9, 13	to Bump		10,000	Pass
3	1-	10.10	250	10,000	
4	10,10,3,4,5,8B	10.10	250	10000	Pass
5	12,10,8	10.19	250	10000	Pa 55
6	12.11,7	10-10	250	10000	Pass
7	15,11,7	19-10	250	5,000	Pass
8	20,21,22,23	10-10	250	5000	P855
9	1 17	10-10	250	5000	Pass.
10	16	10.10	250	500	P835
11	18 43 IF	10-10	250	5000	Poss
12	19 45IF	10.10	250)	500	Pass
13	19 ([7.39	10-10	250	5ans	Pass
IL	18 (ET-39	10.10	250	5000	Pass
1			1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		
-				Con and	
- 12	The state of the s	The state of the state of the state of			. The state of the