

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-44372
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Ojo Chiso SWD
8. Well Number 2
9. OGRID Number 370997
10. Pool name or Wildcat DEVONIAN
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD

2. Name of Operator
Grama Ridge Disposal, LLC

3. Address of Operator
Box 1105 Eunice, NM 88231

4. Well Location

Unit Letter O : 412 feet from the S line and 1844 feet from the E line
Section 24 Township 22 Range 34 NMPM County Lea

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: Drill SWD ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Grama Ridge Disposal, LLC plans to drill and complete as a SWD per Order SWD-1713. (See attached)

HOBBS OCD

MAR 02 2018

RECEIVED

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Eddie W. Seay TITLE Agent DATE 3-1-18

Type or print name Eddie W. Seay E-mail address: seay04@leaco.net PHONE: 575-392-2236

For State Use Only

APPROVED BY: Mary Brown TITLE AO/II DATE 3/5/2018

Conditions of Approval (if any):

WORKPLAN
Drill and Convert to SWD
Ojo Chiso SWD #2
API 30-025-44372
SWD 1713

- 1) Build location, install anchors.
- 2) Notify OCD.
- 3) Move in rig.
- 4) Install 20", 13 3/8", 9 5/8", and 7" liner as permit approved.
- 5) Complete in open hole section from 14480' to 16030'.
- 6) Install 4 1/2" coated tubing and packer within 100 ft. of top open hole section.
- 7) Load backside with packer fluid.
- 8) Notify OCD; run MIT.
- 9) File all sundry notices on pipe installments.
- 10) Put on injection.

HOBBS OCD
MAR 02 2018
RECEIVED