

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OGD**  
**CONSERVATION DIVISION**  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
**JUL 02 2018**

**RECEIVED**

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-43100
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Active Injector <input checked="" type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Occidental Permian Ltd.		6. State Oil & Gas Lease No. N/A
3. Address of Operator P.O. Box 4294, Houston, Tx 77210		7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit
4. Well Location (Surface) Unit Letter <u>N</u> : <u>179</u> feet from the <u>North</u> line and <u>1840</u> feet from the <u>West</u> line Section <u>9</u> Township <u>19S</u> Range <u>38E</u> NMPM Lea County		8. Well Number 268
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3616.3' (KB)		9. OGRID Number: 157984
		10. Pool name or Wildcat: Hobbs (G/SA)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☒ PB bottom of well

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MIRU PU. ND Wellhead. NU BOP.
- 2) POOH with injection equipment
- 3) Cleanout well to current TD
- 4) PB bottom perforations with cement/CIBP to improve injection conformance
- 5) RIH with injection equipment
- 6) ND BOP. NU Wellhead. RDMO PU. Return well to injection

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

**Condition of Approval: notify**

**OCD Hobbs office 24 hours**

**prior of running MIT Test & Chart**

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jacob A Cox TITLE Production Engineer DATE 07/02/2018

Type or print name Jacob S. Cox E-mail address: Jacob\_Cox@oxy.com PHONE: 713-497-2053

For State Use Only

APPROVED BY: Malay S Brown TITLE AO/I DATE 7/2/2018

Conditions of Approval (if any):

MB