Office			f New Mexic	-		_	Form C-10	
District 1 - (575) 3		Energy, Minerals	s and Natural	Resources			ised July 18, 201	
1625 N. French Dr District II - (575)	., Hobbs, NM 88240 748-1283				WELL API N 30-02	NO. 25-29999		
811 S. First St., Ar		OIL CONSER			5. Indicate T			
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			th St. Francis			STATE FEE X		
District IV – (505) 1220 S. St. Francis 87505	476-3460	Santa F	Fe, NM 8750	5	6. State Oil	& Gas Lease N	10.	
	SUNDRY NOT	FICES AND REPORTS C	ON WELLS		7. Lease Nai	ne or Unit Ag	reement Name	
(DO NOT USE TH DIFFERENT RES	IIS FORM FOR PROP ERVOIR. USE "APPL	OSALS TO DRILL OR TO DE LICATION FOR PERMIT" (FO	EPEN OR PLUG I RM C-101) FOR S	BACKERO A	Wrig	ht		
PROPOSALS.) 1. Type of We	ll: Oil Well X	OSALS TO DRILL OR TO DEI ICATION FOR PERMIT" (FOI Gas Well Other		LV WIG			<u> </u>	
2. Name of Op	orator		<u>O</u> r	DO SEE	9. OGRID N	lumber 1092	2	
3. Address of		Energy Corporation		6	10. Pool nar	ne or Wildcat	····	
		73, Roswell, NM 88202-	-1973	~0 ^{5°}	Hu	mble City; Wo	olfcamp	
4. Well Locati			0	9				
		0 feet from the North			the <u>East</u> line		a .	
Sectio	n 12	Township 11. Elevation (Show w		ange 37E		PM Lea	County	
			vhether DR, RI 123 GR		eic.j			
	10 01 1				·			
		Appropriate Box to I	indicate Nati		· •			
		NTENTION TO:			UBSEQUENT			
			= 1	EMEDIAL V			NG CASING	
TEMPORARIL					DRILLING OPNS.	=	A [
PULL OR ALTE				ASING/CE	VENT JOB			
DOWNHOLE C								
CLOSED-LOO	P SYSTEM]		THER: F	Recompletion		х	
				INEN. I			~	
13. Describ	e proposed or com	pleted operations. (Clear	rly state all per			t dates, includ	ling estimated of	
of start		npleted operations. (Clear work). SEE RULE 19.15. ecompletion.		inent detail	s, and give pertinen			
of start	ing any proposed we ad completion or re	work). SEE RULE 19.15. ecompletion.	7.14 NMAČ.	inent detail For Multiple	s, and give pertinen e Completions: Att			
of start propose 1/14/19	ing any proposed v ed completion or re RU PU (Lucky).	vork). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10	7.14 NMAČ. 9,265'). NUBO	inent detail For Multiple P, TOH w/1	s, and give pertinen e Completions: Att 50 stands. SD.	ach wellbore	diagram of	
of start	ing any proposed we ed completion or re RU PU (Lucky). Finish TOH w/10	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub	7.14 NMAČ. 265'). NUBO ing tally (320jt	inent detail For Multiple P, TOH w/1 s). RU JSI	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga	ach wellbore a	diagram of nk basket, wen	
of start propose 1/14/19	ing any proposed we ed completion or re RU PU (Lucky). Finish TOH w/10	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH	7.14 NMAČ. 265'). NUBO ing tally (320jt	inent detail For Multiple P, TOH w/1 s). RU JSI	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga	ach wellbore a	diagram of nk basket, wen	
of start propose 1/14/19	RU PU (Lucky). Finish TOH w/16 down to 11,116' tubing testers, te	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH	7.14 NMAČ. 9,265'). NUBO ning tally (320jt I w/gun, shot p	inent detail For Multiple P, TOH w/1 s). RU JSI erfs @ 1085	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga 50'-10870', 2 spf, 9	ach wellbore auge ring & ju 0-degree phas	diagram of nk basket, wen ing. SD JSI. F	
of start propose 3/14/19 3/15/19 ≸	RU PU (Lucky). Finish TOH w/16 down to 11,116' tubing testers, te TIH w/188jts tbg	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD.	7.14 NMAČ. 265'). NUBO ing tally (320jt I w/gun, shot p t pump into it,	inent detail For Multiple P, TOH w/1 s). RU JSI erfs @ 1085 plugged off	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga 50'-10870', 2 spf, 9 C. Rig up to knife tu	ach wellbore auge ring & ju 0-degree phas bing. Pumpe	diagram of nk basket, wen ing. SD JSI. F d 1 drum of	
of start propose 3/14/19 3/15/19 ≸	RU PU (Lucky). Finish TOH w/16 down to 11,116' tubing testers, te TIH w/188jts tbg	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn'	7.14 NMAČ. 265'). NUBO ing tally (320jt I w/gun, shot p t pump into it,	inent detail For Multiple P, TOH w/1 s). RU JSI erfs @ 1085 plugged off	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga 50'-10870', 2 spf, 9 C. Rig up to knife tu	ach wellbore auge ring & ju 0-degree phas bing. Pumpe	diagram of nk basket, wen ing. SD JSI. F d 1 drum of	
of starti propose 9/14/19 9/15/19	RU PU (Lucky). Finish TOH w/16 down to 11,116' tubing testers, te TIH w/188jts tbg toluene, got thro (2,375'). SD.	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn'	7.14 NMAČ. 265'). NUBO ing tally (320jt I w/gun, shot p t pump into it,	inent detail For Multiple P, TOH w/1 s). RU JSI erfs @ 1085 plugged off	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga 50'-10870', 2 spf, 9 C. Rig up to knife tu	ach wellbore auge ring & ju 0-degree phas bing. Pumpe	diagram of nk basket, wen ing. SD JSI. F d 1 drum of	
of start propose 3/14/19 3/15/19 ≸	RU PU (Lucky). Finish TOH w/16 down to 11,116' tubing testers, te TIH w/188jts tbg toluene, got thro (2,375'). SD.	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn'	7.14 NMAČ. 265'). NUBO ing tally (320jt I w/gun, shot p t pump into it,	inent detail For Multiple P, TOH w/1 s). RU JSI erfs @ 1085 plugged off	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga 50'-10870', 2 spf, 9 C. Rig up to knife tu	ach wellbore auge ring & ju 0-degree phas bing. Pumpe	diagram of nk basket, wen ing. SD JSI. F d 1 drum of	
of starti propose 9/14/19 9/15/19 9/18/19	RU PU (Lucky). Finish TOH w/16 down to 11,116' tubing testers, te TIH w/188jts tbg toluene, got thro (2,375'). SD.	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn's ugh tight spot (825'-950')	7.14 NMAČ. 9,265'). NUBO 9 ing tally (320jt 1 w/gun, shot p 1 pump into it,) w/2 3/8" knift	inent detail For Multiple P, TOH w/1 s). RU JSI erfs @ 1085 plugged off e. TOH, pu	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga 50'-10870', 2 spf, 9 C. Rig up to knife tu	ach wellbore auge ring & ju 0-degree phas bing. Pumpe	diagram of nk basket, wen ing. SD JSI. R d 1 drum of	
of starti propose 9/14/19 9/15/19	RU PU (Lucky). Finish TOH w/16 down to 11,116' tubing testers, te TIH w/188jts tbg toluene, got thro (2,375'). SD.	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn's ugh tight spot (825'-950')	7.14 NMAČ. 265'). NUBO ing tally (320jt I w/gun, shot p t pump into it,	inent detail For Multiple P, TOH w/1 s). RU JSI erfs @ 1085 plugged off e. TOH, pu	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga 50'-10870', 2 spf, 9 C. Rig up to knife tu	ach wellbore auge ring & ju 0-degree phas bing. Pumpe	diagram of nk basket, went ing. SD JSI. R d 1 drum of	
of start propose 3/14/19 3/15/19 3/18/19 5/18/19 5pud Date:	RU PU (Lucky). Finish TOH w/10 down to 11,116' tubing testers, te TIH w/188jts tbg toluene, got thro (2,375'). SD. TWO***	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn' ugh tight spot (825'-950') Rig	7.14 NMAČ. 9,265'). NUBO ing tally (320jt I w/gun, shot p t pump into it,) w/2 3/8" knift g Release Date:	inent detail For Multiple P, TOH w/1 s). RU JSI erfs @ 1085 plugged off e. TOH, pu	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" gi 50'-10870', 2 spf, 9 7. Rig up to knife tu t on 2 7/8" knife. M	ach wellbore auge ring & ju 0-degree phas bing. Pumpe	diagram of nk basket, wen ing. SD JSI. F d 1 drum of	
of start propose 3/14/19 3/15/19 3/18/19 5/18/19 5pud Date:	RU PU (Lucky). Finish TOH w/10 down to 11,116' tubing testers, te TIH w/188jts tbg toluene, got thro (2,375'). SD. TWO***	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn's ugh tight spot (825'-950')	7.14 NMAČ. 9,265'). NUBO ing tally (320jt I w/gun, shot p t pump into it,) w/2 3/8" knift g Release Date:	inent detail For Multiple P, TOH w/1 s). RU JSI erfs @ 1085 plugged off e. TOH, pu	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" gi 50'-10870', 2 spf, 9 7. Rig up to knife tu t on 2 7/8" knife. M	ach wellbore auge ring & ju 0-degree phas bing. Pumpe	diagram of nk basket, wen ing. SD JSI. R d 1 drum of	
of starti propose 9/14/19 9/15/19 ***SEE PAGE 7 Spud Date: hereby certify t	RU PU (Lucky). Finish TOH w/10 down to 11,116' tubing testers, te TIH w/188jts tbg toluene, got thro (2,375'). SD. TWO***	work). SEE RULE 19.15. ecompletion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn's ugh tight spot (825'-950') Rig n above is true and compl	7.14 NMAČ. 2,265'). NUBO ing tally (320jt I w/gun, shot p t pump into it,) w/2 3/8" knift g Release Date: lete to the best	inent detail For Multiple P, TOH w/1 s). RU JSI erfs @ 1085 plugged off e. TOH, pu	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" gi 50'-10870', 2 spf, 9 7. Rig up to knife tu t on 2 7/8" knife. M	auge ring & ju 0-degree phas bing. Pumpe Worked 95 sin	diagram of ink basket, went ing. SD JSI. R d 1 drum of gles in hole	
of start propose 3/14/19 3/15/19 3/18/19 5/18/19 5pud Date:	RU PU (Lucky). Finish TOH w/10 down to 11,116' tubing testers, te TIH w/188jts tbg toluene, got thro (2,375'). SD. TWO*** 8/17/1987	work). SEE RULE 19.15. completion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn' ugh tight spot (825'-950') Rig n above is true and completion TI	7.14 NMAČ. 9,265'). NUBO 9,105'). NUBO 9,105' 1 w/gun, shot p 1 w/gun	of my know	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga 50'-10870', 2 spf, 9 C. Rig up to knife tu t on 2 7/8" knife. M vledge and belief.	auge ring & ju 0-degree phas bing. Pumpe Worked 95 sin	diagram of ink basket, wen ing. SD JSI. R d 1 drum of gles in hole	
of starti propose 9/14/19 9/15/19 9/18/19 9/18/19 1/18/19	RU PU (Lucky). Finish TOH w/10 down to 11,116' tubing testers, te TIH w/188jts tbg toluene, got thro (2,375'). SD. TWO*** 8/17/1987	work). SEE RULE 19.15. completion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn' ugh tight spot (825'-950') Rig n above is true and completion TI	7.14 NMAČ. 9,265'). NUBO 9,105'). NUBO 9,105' 1 w/gun, shot p 1 w/gun	of my know	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga 50'-10870', 2 spf, 9 C. Rig up to knife tu t on 2 7/8" knife. M vledge and belief.	auge ring & ju 0-degree phas bing. Pumpe Worked 95 sin	diagram of ink basket, wen ing. SD JSI. R d 1 drum of gles in hole	
of starti propose 9/14/19 9/15/19 9/18/19 9/19	RU PU (Lucky). Finish TOH w/10 down to 11,116' tubing testers, te: TIH w/188jts tbg toluene, got thro (2,375'). SD. TWO*** 8/17/1987 that the informatio me Kye A Dnly	work). SEE RULE 19.15. completion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn' ugh tight spot (825'-950') Rig n above is true and completion TI	7.14 NMAČ. 9,265'). NUBO 9,105'). NUBO 9,105' 1 w/gun, shot p 1 w/gun	of my know	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" ga 50'-10870', 2 spf, 9 C. Rig up to knife tu t on 2 7/8" knife. M vledge and belief.	auge ring & ju 0-degree phas bing. Pumpe Worked 95 sin	diagram of ink basket, wen ing. SD JSI. R d 1 drum of gles in hole	
of starti propose 9/14/19 9/15/19 9/18/19 9/19	RU PU (Lucky). Finish TOH w/10 down to 11,116' tubing testers, te: TIH w/188jts tbg toluene, got thro (2,375'). SD. TWO*** 8/17/1987 that the informatio me Kye A Dnly	work). SEE RULE 19.15. completion. TOH w/rods. Pump (10 60 stands. TAC, total tub . TOH, had no drag. TIH st 132 jts in. SD. g, RU HO truck. Couldn' ugh tight spot (825'-950') Rig n above is true and completion TI	7.14 NMAČ. 9,265'). NUBO 9,105'). NUBO 9,105' 1 w/gun, shot p 1 w/gun	of my know	s, and give pertinen e Completions: Att 50 stands. SD. WL, TIH w/4.5" gi 50'-10870', 2 spf, 9 7. Rig up to knife tu t on 2 7/8" knife. M	auge ring & ju 0-degree phas bing. Pumpe Worked 95 sin	diagram of ink basket, wen ing. SD JSI. F d 1 drum of gles in hole	

Perceloum Bagineer

.

N.

, same .

.

.

C-103 -Sub Report-Recompletion Wright 2 #1 API # 30-025-2999 Page

3/19/19 TIH w/49 more triples to get to 6100' w/2 7/8" knife. TOH, RU swab. Put 3/4 cup on, swab tubing dry. Broke sand line. Set up to repair tomorrow. Pumped 2 bbl toluene down tubing to soften paraffin. SD. Repair sand line. TIH w/rods & 2 7/8" knife to 10,241'. TOH working spots with drag. Prep to 3/20/19 swab clean. 3/21/19 TIH with 2 7/8" cups to 6195', Pull out & ran 2 3/8" cup, went to SN. Ran back with 2 7/8" cups & tagged @ 8400'. Couldn't work past. Decided to TOH w/tbg 115 stands, located plugged its, LD and replace them. SD. 3/22/19 With 114 stands out, ran 2 7/8" cups to SN no problem. TIH w/20 more stands, ran cups to SN no restrictions. RU tubing testers @ 94 stands out to 8,000psi w/GT tubing testers. Test in hole to 10,678.5'. 331 total its. Set packer, RU Crain acid, start on xylene 250gal pumped @ 2.5bpm rate. Total acid pumped - 2,000gal 15% NEFE with 80 ball sealers, flush with 64bbl 2%KCL water. ISIP - vac. SD, RU to swab, went in on 1st run and tagged fluid @ 5000'. Sand line broke first swab run. Unseat packer and left tubing swinging. SD. 3/23/19 Pulled tubing to get to sand line, pulled out of hole and replace with new. TIH w/tubing, set packer @ 10,768.5'. SDFW. 3/25/19 TP 150psi, 122 bbl to recover. Made 14 swab runs. Recovered 85.5bbl, 36.5 bbl to remaining to recover load. Fluid level held between 5616' and 7660' throughout runs. 3/26/19 Continue swabbing. Recovered 37bbl over load. Made 16 runs, on 8th run 100% oil cut, held until 14th run, dropped to 50% oil cut. H2S monitors indicated sour gas. SD to test and found gas at 30,000ppm H2S. SISD for evaluation. 3/27/19 Ran gas analysis (attached to report), indicating very high H2S concentrations, around 3%. Backside (existing, still-open perforations) @ 2,000ppm. Pumped 75bbl 2% KCL down tubing to kill well. Unset packer, removed BOP, flanged up, TIH w/rods. Left swinging, RDPU. Office spoke with OCD, no other record of H2S concentrations this high in immediate area. Plan to squeeze these perforations next week in interest of safety and liability elimination. This well is near the town of Lovington and in the vicinity of inhabited structures and livestock. RDPU 4/1/19 RUPU. TOH w/rods and tubing. Pumped 70bbl 2% down tubing. Pumped 100bbl additional while tripping out. SD RU pump truck, pump 30bbl 2% KCL to kill well. TIH w/330its 2 7/8" tubing. Set packer @ 4/2/19 10,741.85'. RU to swab. First run FL was @ 3618'. 275bbl LLTR. Made 13 runs recovered 105bbl. No OC after 4th run, slight gas show. Fluid level maintained @ 2928' to 6100' throughout runs. SD. Swabbing. First 2 runs 100% oil cut, remaining were all water until 9th run, started getting slight 4/3/19 oil & gas show, 10% oil cut. On run 12, started getting emulsion and swab would not go through. Recovered 72bbl total fluid, 98bbl LLTR. SD. 4/4/19 Swabbing. Runs 1 & 2 - 80-90% oil cut, runs 3-8 slight oil & gas show, runs 9-12- 40-50% oil cut. Last run of day had significant increase in gas, with sign of H2S. 61.5bbl load recovered today. 36.5bbl LLTR. SD. 4/5/19 SITP 90psi. Made 5 swab runs, recovered 38.5bbl – 2 bbl over load. Run gas analysis, results = 2% H2S. Prep to abandon zone, squeeze next week. SDFW.

、

. .

·

·

.

C-103 -Sub Report-Recompletion Wright 2 #1 API # 30-025-2999 Page

- 4/8/19 SITP 320psi. Kill well w/50bbl 2% KCL. TOH w/packer, TIH w/retainer. Set cement retainer @ 10648.82', 327 jts. Set tool to pressure up & test tubing. Loaded in 31 bbl. Got 500psi on tbg & lost 10 points, BS started blowing. LD 177 its. SD. 4/9/19 Kill w/20bbl. Finish TOH w/270 jts, found split collar down hole. TIH w/259 jts 6 doubles in derrick with 4 11/16" collar overshot. Grabbed ahold of fish, stung out of retainer & TOH w/39 stands. SD. 4/10/19 Kill well w/20bbl 2%. Finish TOH w/fish, LD 57 jts. Replaced stinger, TIH w/200 jts. Shut down due to wind. Par 5 scheduled for 9am tomorrow to squeeze sour interval. 4/11/19 Finish TIH & found retainer 327 its in. Put 6' sub on, stung into retainer, 15 points. Put valve on tubing, shut BOP, waited on Par 5. RU Par 5 cement, test lines to 4000psi, pump 14 bbl FW to load @ 2bpm rate, 2600psi. Pumped 24 bbl FW, started mixing cement lead, Pump 150sx class "H". SD. Pulled out of retainer. 1/2 bbl of cement left on top of retainer. TOH w/310 jts total. Standing in derrick + KB + packer (10108.73'). TIH w/pkr, left pkr swinging @ 9289.16'. SD. 4/12/19 Started in with remaining 12 stands, tagged cement stringers @ 9737.06', couldn't push through. TOH w/packer, MU scraper, bit sub, and 4.75" roller cone bit. TIH to 9737', worked through stringers for about 150'. Fell through, ran bit to 10,300' with no issues. TOH. SDFW. 4/15/19 TIH w/310jts 2 7/8" w/packer & SN, set pkr @ 10,108.73'. RU to swab test original zone. Made 12 runs. SDFD. 50bbl total fluid recovery. 4/16/19 RU to swab. RU Crain acid. Test lines to 5000psi, pump 8 bbl water lead @ 3.25bpm, started on acid. 2000gal 15% acid, 75 ball sealers & 60bbl 2% KCL water flush, total pumped. ISIP 1815psi, 5 min 813psi, 10 min 272psi, 15 min vac. 107bbl LLTR. Made 10 more swab runs, started getting sour gas show last two runs. Recovered 71.5 total bbl. 35.5 bbl LLTR from acid job. SD. H2S monitors going off on overload. 4/17/19 SITP 200psi. Pulled H2S tube, showed 5,000ppm. Swabbing. Made 13 runs, recovered 71+bbl, varying oil cut. Pulled tube and maxed out 2% H2S tube. Prep to TOOH and set CIBP over these perforations. SISD. 4/18/19 SITP 200psi. Got off on/off tool, let equalize, unseat packer and killed well with 30bbl 2% KCL. TOH w/tubing. Pumped 20bbl down casing while TOH, released kill truck, RU WL. Pack off, TIH w/CCL & CIBP. Set @ 10,151.5'. Got hung up, decided to set there, 50.5' above top perforation. TOH, trip back in w/l bailer of cement & dump on CIBP. TIH two more times
- 4/19/19 TIH w/l bailer of cement, shot off blasting cap, dumped cement on top of CIBP. SDFW.

trying to get second bailer glass to break, no luck. SDFD.

- 4/22/19 RU WL, TIH, tie-in and perforate <u>9872'-9886'</u>, 2 spf, 90-degree phasing. TIH w/2 7/8" x 5 1/2" Arrowset packer, on/off tool w/2.313x profile nipple, SN, 300 jts 2 7/8" tubing. 11 stands in, well started kicking, shut BOP and stab TIW valve. Pumped 16bbl 2% down tubing, 3000psi, SD, opened BS to frac tank, pumped 25bbl circulating to tank. TIH to 5400', well started kicking again. Pumped 35bbl down tubing, BS open to tank. Finish TIH, circulate 150bbl 2%, set packer @ 9792', pressure up BS to 5090psi, held OK. RD kill truck & water truck, RU to swab. Made 4 swab runs. 43bbl total recovered. SDFD.
- 4/23/19 SITP vacuum. RU to swab. RU acid truck and load tubing w/46bbl 2% KCL. Spot acid @ 9886'. 12 bbl 15% acid, 54bbl 2% behind for balanced spot. Pumped 20bbl down tubing to put acid away. Average rate 1.4bpm, average treating pressure 4018psi. ISIP 2950psi, 5 min 2603psi, 10min 2547psi, 15min 2500psi. 75bbl LLTR. Made 3 runs, recovered 25 bbl. FL on last run was 3318'. SDFD.

4/29/19 Swab. Recover 40 bbl fluid. High H2S. Prep to Plug. SD

4808 North Michigan Ave. Roswell, NM. 88202-8323 (575) 626-9874 Precision Gas Measurement, Inc. Natural Gas Analysis Report

بالمعالية والمناطقة والمحالية والمحالية والمحالية والمحالية والمحالية والمحالية والمحالية والمحالية والمحالية

Sample Information

	Sample Information	 	
Company Name	ARMSTRONG ENERGY	 	 - •
Lease Name	WRIGHT # 2		
Location ID			
Sample Date	3/27/2019		
Method Name	BTUH2S.met		
Injection Date	2019-03-27 13:35:42		
NGA Phys. Property Data Source	GPA Standard 2145-16 (FPS)	 	

Component Results

Component Name	Norm%	Gross HV (Dry) (BTU / Ideal cu.ft.)	Gross HV (Sat.) (BTU / Ideal cu.ft.)	Relative Gas Density (Dry)	GPM (Dry) (Gal. / 1000 cu.ft.)	
H2S C	2.8957	18.4	18.1	0.03407	0.000	
Nitrogen	0.4322	0.0	0.0	0.00418	0.000	
Carbon Dioxide	16.4640	0.0	0.0	0.25017	0.000	
Methane	34.8578	351.0	344.8	0.19308	0.000	
Ethane	21.5873	380.8	. 374.2	0.22412	5.787	
Propane	10.3201	258.9	254.3	0.15712	2.850	
N-Butane	7.7491	252.0	247.6	0.15551	2.449	
I-Butane	2.2275	72.2	70.9	0.04470	0.731	
N-Pentane	1.3343	53.3	52.4	0.03324	0.485	
I-Pentane	1.8402	73.4	72.1	0.04584	0.675	
C6+	0.2918	14.9	14.7	0.00939	0.127	
Water	0.0000	0.0	0.0	0.00000	0.000	
Total:	100.0000	1474.9	1449.1	1.15142	13.103	

Results Summary

Result	Dry	Sat. (Base)	As Delivered(Flowing)	
Total Normalzed Mole%	100.0000	100.0000	100.0000	
Pressure Base (psia)	14.650			
Flowing Temperature (Deg. F)	60.0			
Flowing Pressure (psia)	50.0			
Water Mole%	-	1.7502	0.5316	
Gross Heating Value (BTU / Ideal cu.ft.)	1474.9	1449.1	1467.0	
Gross Heating Value (BTU / Real cu.ft.)	1486.8	1461.6	1479.2	
Relative Density (G), Real	1.1603	1.1515	1.1576	
Compressibility (Z) Factor	0.9920	0.9914	0.9918	
Total GPM	13.103	12.980	13.065	
Gross Wobbe Index, Real	1380.343	1362.024	1374.793	

Let Your Interest In Measurement Be Our Concern

.

·

.

÷...